STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PROPOSED HIGHWAY PLANS DISTRICT NINE

FAP ROUTE 845 (IL 154)
SECTION D9 HOAN DETAIL REPAIR FY 09-1
C-99-047-08
FRANKLIN COUNTY

O28-0051
IL 154
REND LAKE
INVENTORY RATING HS 20.0
OPERATING RATING HS 27.7
ADT: 3500
12% TRUCKS

DUQUOIN

SESSER

WEST CITY
BENTON

CHRISTOPHER

34


THOMPSONVILLE

ROYALTON

WEST FRANKFORT

MAP NOT TO SCALE

*D9 HOAN DETAIL REPAIR FY09-1



STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

SURMITTED

PUTY DIRECTOR OF HIGHWAYS, REGION ENGINEE

October 3 20 08 Eriz E. Harm

toper 3 20 08

ristne M. Kled E. DIRECTOR OF HIGHWAYS, CHIEF ENGINEER

PRINTED BY THE AUTHORITY OF THE STATE OF ILLINOIS

PLAN DRAWINGS ARE NOT TO SCALE.

J.U.L.I.E.

JOINT UTILITY LOCATION INFORMATION FOR EXCAVATION 1-800-892-0123

CONTRACT NO. 78062

JECT ENGINEER: CASEY N. TECKENBROCK PH

ROUTE NO.	BRUTION		MTY	TOTAL BHESTS	SP-MCMET NG.		
FAP 845		FRAN	IKLIN	5.	2		
PED. ROAD DIST.	NO. 7	ILLINOIS	PEO. ALD PRO	Lightery-	·		

*D9 HOAN DETAIL REPAIR FY09-CONTRACT 78062

INDEX OF SHEETS

SHEET

DESCRIPTION

- 1 COVER SHEET
- INDEX OF SHEETS, STANDARDS, SIGNATURES
- 3 SUMMARY OF QUANTITIES
- 4 GIRDER PLAN AND ELEVATION
- 5 STIFFENER MODIFICATION DETAILS

STANDARDS

701201-02 LANE CLOSURE, 2L, 2W, DAY ONLY, FOR SPEEDS >= 45 MPH

701901 TRAFFIC CONTROL DEVICES

GENERAL NOTES

THE CONTRACTOR SHALL CONTAIN AND DISPOSE OF ALL DEBRIS. INCLUDING FRAGMENTS OF STEEL. NO WASTE OR DEBRIS SHALL BE ALLOWED TO ENTER THE LAKE WATER.


Prepared By: King Grammy
Examined By:
Examined By: Cani Nulsur
Examined By: DISTRICT PROGRAM DEVELOPMENT ENGINEER Examined By:
DISTRICT STUDIES & PLANS ENGINEER Examined By:
DISTRICT) CONSTRUCTION ENGINEER Examined By:
Examined By: Justinus
Examined By:
Approved By: //// / ////////////////////////////
DEPUTY DIRECTOR OF HIGHWAYS, REGION 5 ENGINEER 2005 DATE
DATE

ROUTE NO.	SECTION	COUNTY	TOTAL SHEETS	BHEET NO.
FAP 845	•	FRANKLIN	5	3


*D9 HOAN DETAIL REPAIR FY09-1 CONTRACT 78062


SUMMARY OF QUANTITIES

		100%	STATE			
	CONSTRUCTION TYPE CODE: SFTY - 2A	RURAL				
CODE NO.	ITEM DESCRIPTION	UNIT	QUANTITY			
67000400	ENGINEER'S FIELD OFFICE, TYPE A	CAL MO	3			
67100100	MOBILIZATION	L SUM	1			
70100450	TRAFFIC CONTROL AND PROTECTION, STANDARD 701201	L SUM	1			
X0322556	STIFFENER INTERSECTION MODIFICATION	EACH	132			



Contract Number: ----





GIRDER ELEVATION SHOWING TYPICAL LOCATIONS OF FRACTURE CONTROL MODIFICATION

(Looking North)
(Girder 1 shown, Girder 2 similar by 180° rotation)
Work to be performed on outside face of each girder.
See sheet 2 of 2 for girder orientation



<u>LEGEND</u>

· • · 2 Locations

⊙·· 1 Location

BILL OF MATERIAL

 İtem
 Unit
 Total

 Stiffener Intersection Modification
 Each
 132

PLAN & ELEVATION FAP 845 (IL 154) FRANKLIN COUNTY SN 028-0051

Expires: November 30, 2010

ROUTE NO.	BECTION	co	UNTY	TOTAL SHEETS	SHEET NO.	SH
FAP 845		FRAN	IKL IN	5	5	2
FED. ROAD DIST	ND. 7	ILLINDIS				


SHEET NO. 2

2 SHEETS

Contract Number: ----


	SPLICE A SPLICE B SPLICE C		SPLICE D			SPLICE E				SPLICE F														
	T	OP .	BOT	TOM	7	OP .	B07	ТОМ	T	OP .	<i>B01</i>	ТОМ	T	OP .	BOT	TOM	T	0P	BOT	ТОМ	T	OP	B07	ТОМ
GIRDER #	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT	LEFT	RIGHT
* 1	6	0	1	4	1	4	6	0	4	1	0	6	1	4	6	0	4	1	0	6	1	4	6	0
* 2	4	1	0	6	1	4	6	0	4	1	0	6	1	4	6	0	4	1	0	6	0	6	4	1

^{*} Looking North



REPAIR DETAIL

Hatched area indicates section removal. (Showing 2 locations)



Procedure for Repair Detail:

- 1. Cut existing longitudinal stiffener ±4" from face of vertical stiffener and along web as shown, with a 1" R (Min) at Web. The minimum distance from cut to face of web shall be the larger of \(^1_4\)" or web to plate weld size, with removal of remaining material by grinding as described below. The cut shall be made parallel to the web without angling the cut towards the web. Equipment and method of cutting shall be approved by the Engineer. Any method of removal to be used shall ensure that no damage is done to the existing web, vertical stiffener or welds connecting these elements. Cutting shall be done in a manner such that the paint on the opposite face of the web is not damaged. If damage occurs, the damaged area shall be repainted at the contractor's expense and procedures shall be modified to prevent damage at subsequent removal locations.
- 2. Remove material between cut and web by grinding and grind smooth at web surface and cut end of stiffener. Web ₧ surfaces and cut end of stiffener shall have a roughness average (Ra) of 250 µ in. or less. Grinding equipment shall be approved by the Engineer. The grinding operation should not gouge the girder web ₧.
- 3. The web surface at the modification shall be inspected using dye penetrant or magnetic particle (MT) methods. Any cracks found shall be identified and reported to the Bureau of Bridges and Structures for further disposition.
- 4. The exposed steel surfaces shall be cleaned and painted using an aluminum epoxy mastic primer according to Article 506.05 of the Standard Specifications.

Each 4" stiffener removal area is to be considered as one retrofit. Accepted above referenced work will be paid for at the contract unit price each for Stiffener Intersection Modification, which price shall include all materials, equipment, labor, cleaning, testing and painting.

STIFFENER MODIFICATION DETAILS

FAP 845 (IL 154)

FRANKLIN COUNTY

SN 028-0051

DESIGNED		ATH
CHECKED		AJB
DRAWN		Steffen
CHECKED	ATH	AJB

SIMD/REPS 03-02-2006

OCTOBER 2, 2008

EXAMINED A Carl Juny
PASSED RENDINEER OF STRUCTURAL SERVICES

PASSED RENDINEER OF BRIDGES AND STRUCTURES

c:\projects\kms\0280051.don 10/2/2008 3: 35: 35 PM