

SN 099-0008

I-55 (South Bound) over Des Plaines River Smith Bridge



2021 Bridge Inspection Report

Bridge Inspection By: The Illinois Department of Transportation

Bridge Inspection Report By: The Illinois Department of Transportation

TABLE OF CONTENTS

• Table of Contents	Page 2
• Executive Summary	Page 3
• Routine Inspection Report	Page 4
• Fracture Critical Inspection Report	Page 6
• Preliminary Pin and Link Inspection Journal	Page 8
• Element Level Inspection Report	Page 10
• Underwater Inspection Report	Page 12
• Framing Plan	Page 17
• Items Removed from Table of Deficiencies	Page 18
• Table of Deficiencies	Page 19
• Deficiency Details	Page 33
• Photographs	Page 84
• Table of Joint Openings	Page 168

Bridge Executive Summary

Bridge Description

The structure is 1,406' back to back of abutments and consists of three (3) steel truss main spans (Spans 4, 5, and 6) and four (4) steel multi-beam approach spans (Spans 1, 2, 3, and 7). Both abutments are reinforced concrete spill thru abutments on spread footing. Piers are concrete on spread footings.

Construction History

Date	Contract No.	Description
2013	60R2	Deck overlay and joints, painting
2011	60J24	Fiber Optic conduit Installation
2010	60K04	Deck overlay repairs and treatment
2005	62861	Joint and misc. repair
2002	82409	Superstructure repairs, painting, and new Bituminous Overlay
1999	60706	Milling new bituminous surface
1997	82962	Deck overlay and Joint repair
1993	82045	Bridge Repairs
1990	80710	Remove Debris
1978	33113	Reconstruction
1958		Maintenance and repair
1957		Original Plans

The 2021 Bridge Inspection was performed by Illinois Department of Transportation. The inspection was started on August 9, 2021 and concluded on August 12, 2021.

SN 099-0008 is generally in fair condition, with isolated locations of poor condition. Most of the bridge deck, superstructure, paint system, and substructure are in fair condition. The deck overlay is in fair condition. The HMA overlay was last replaced in 2013. The deck has cracking 2' to 8' apart, and stay in place forms beneath grid deck has rust throughout spans. Superstructure is in fair condition with up to 26% section loss in stringer, floorbeam and truss member. All pins in good condition with slight grooving around pin. Bearings are in fair condition throughout the structure with up to 30% section loss in bolster and 50% section loss in retainer. Substructure; the top of footing is exposed at pier 5.



SN: 099-0008	District: 1	Spans: 3	Appr. Spans: 4	Skew: 0	ADT: 24200	Truck Pct: 7
ADT Un: 0	Maint. Co: 99 - Will	Twsp: 01 - Channahon		Status: 1-Open, no restrictions		
Facility Carried: I- 55 SB			Feature Crossed: DES PLAINES RIVER			
Location: 2.3 M S OF US 6		Municipality: 0000	Team/Sub Section: 137/555		Insp/Rte: 037	
Bridge Name: SMITH BRIDGE			Material & Type: Steel Continuous / Cantilever (Suspended)			
Insp. Intervals Routine: 24		Fracture Critical: 24	Underwater: 60	Special: 0	Element Level: 24	
90 - Inspection Date: 08/09/2021		90C - Temp (°F): 80		90B1 - In Depth: <input checked="" type="checkbox"/>		
Is Delinquent: <input type="checkbox"/>		Reason:				
90A - Agency Program Manager: William A. Beisner						
90A1 - Team Leader: Joe Deckard			90A2 - Inspector: Keith Cason-Gossett			

90B - Previous Inspection Remarks

DECK - 24% SPALL/DELAM./MAP CRK., 5% SPALL/ DELAM.
 OVERLAY REPLACED IN 2013 WITH HMA IN TRUSS SPANS AND LATEX IN APPR. SPANS.
 DECK HAS CRKS. 2' - 8' APART, SIP FORMS BENEATH GRID DECK HAS RUST THROUGHOUT SPANS.
 SUPER - UP TO 26% S.L. IN STR., UP TO 26% S.L. IN FB., AND UP TO 26% S.L. IN TRUSS MBRS.
 (WORST CASE S.L. WITHOUT IRF > 1.0) CRK. T.W. THROUGHOUT.
 CRKS. IN C.F. CONN. @ APPR. SPANS. UP TO 30% S.L. (IRF > 1.0) TO BRG. BOLSTERS.
 SUB - ABUTS. & PIERS WERE REPAIRED IN 2013.
 TOP OF FOOTINGS EXPOSED.

Resources

Time to Inspect (H:M): 40:00	Traffic Control: 3	Boat: _	Waders: _	Snooper: S
Ladder: _	Manlift: M	Bucket Truck: _	Other: _	

Inspector's Appraisals

	Prev	New	Comments
58 - Deck Condition:	<u>5</u>	5	SEE 90B
59 - Superstructure Condition:	<u>5</u>	5	SEE 90B
60 - Substructure Condition:	<u>5</u>	5	SEE 90B
62 - Culvert Condition:	<u>N</u>	N	
61 - Channel Condition:	<u>7</u>	7	
71 - Waterway Adequacy:	<u>8</u>	8	
72 - Approach Rdwy Align:	<u>8</u>	8	
111 - Pier Navig Protection:	<u>5</u>	5	
36A - Bridge Railing Adequacy:	<u>3</u>	3	
Approach Guardrail Adequacy: 36B - Transitions:	<u>3</u>	3	36C - Guardrail: <u>3</u> 3 36D - Ends: <u>3</u> 3

Additional Inventory Data - To Be Verified During Routine Inspection

108A - Wearing Surface Type: <u>G</u>	108B - Type of Membrane: <u>A</u>	108C - Deck Protection: <u>J</u>
108D - Total Deck Thickness (In.): <u>7.5</u>		
59A - Paint Date (Mo/Yr): <u>10/2013</u>	59B - Paint Type: <u>S</u> <u>I</u> <u>U</u> :	
59C - Utilities Attached: <u>9</u> <u>N</u> <u>N</u>		
113A - Scour Critical Analysis Date: <u>02/01/1993</u>	113 - Scour Critical Rating: <u>8</u>	113B - Evaluation Method: <u>B</u>



SN: 099-0008	District: 1	Spans: 3	Appr. Spans: 4	Skew: 0	ADT: 24200	Truck Pct: 7
ADT Un:	Maint. Co: Will	Twsp: Channahon	Status: Open- No restriction			
Facility Carried: I - 55 South bound	Feature Crossed: Des Plaines River					
Location: 2.3 Miles South of US 6	Municipality:	Team/Sub Section: 137/555	Insp/Rte: 037			
Bridge Name: Smith Bridge	Material & Type: Steel Continuous/ Cantilever through Truss					
Insp. Intervals Routine: 24	Fracture Critical: 24	Underwater: 60	Special: 0	Element Level: 24		
93A- Inspection Date: 08 /09/2021	93A4- Temp. (°F): 80					
Is Delinquent: <input type="checkbox"/>	Reason:					
90A - Agency Program Manager: William A. Beisner	90A3 - Consultant Program Manager:					
93A3 - Team Leader: Joe Deckard	93A5 - Inspector: Keith Cason-Gossett					

Resources

Time to Inspect (H:M): 40:00	40:00	Traffic Control: <u>Y</u>	Y	Boat: <u>1</u>	1	Waders: <u> </u>	Snooper: <u>2</u>	2
Ladder: <u> </u>	Manlift: <u>1</u>	1	Bucket Truck: <u> </u>	Other: <u> </u>				

Inspector's Appraisals

92A1-Type: B3	If "X4-Other" Description: Span 5
93A1-Rating: Prev. <u>5</u> New <u>5</u>	FC Method: Prev. <u>V UT</u> New: MP <input type="checkbox"/> DP <input type="checkbox"/> UT <input checked="" type="checkbox"/> V <input checked="" type="checkbox"/>
93A2-Remarks: Members: U13-L13, U13'-L13'	
Up to 4% section loss in members.	

92A1-Type: B5	If "X4-Other" Description: Spans 4,5 & 6
93A1-Rating: Prev. <u>5</u> New <u>5</u>	FC Method: Prev. <u>V</u> New: MP <input type="checkbox"/> DP <input type="checkbox"/> UT <input checked="" type="checkbox"/> V <input checked="" type="checkbox"/>
93A2-Remarks: Members: L13-L17, U14-L14, U14-L15, U16-L16, U16-L17, L17-U16', U16'-L16', L15'-U14', U14'-L14' L17'-L13'	
Up to 9% section loss (IRF > 1.0) in members.	

92A1-Type: B6	If "X4-Other" Description: Spans 4,5 & 6
93A1-Rating: Prev. <u>5</u> New <u>5</u>	FC Method: Prev. <u>V</u> New: MP <input type="checkbox"/> DP <input type="checkbox"/> UT <input checked="" type="checkbox"/> V <input checked="" type="checkbox"/>
93A2-Remarks: Members: L0-L2, U1-U13, U1-L1, L2-U3, U3-L3, L4-U5, U5-L5, L6-U7, U7-L7, U9-L9, U9-L10, U11-L11, U11-L12, L0'-L2', U1'-U13', U1'-L1', L2'-U3', U3'-L3', L4'-U5', U5'-L5', L6'-U7', U7'-L7', U9'-L9', U9'-L10', U11'-L11', U11'-L12',	
Up to 26% section loss in members.	

92A1-Type: X2	If "X4-Other" Description: Spans 4,5 & 6
93A1-Rating: Prev. <u>5</u> New <u>5</u>	FC Method: Prev. <u>V</u> New: MP <input type="checkbox"/> DP <input type="checkbox"/> UT <input checked="" type="checkbox"/> V <input checked="" type="checkbox"/>
93A2-Remarks: Up to 25% SL in Bottom Flange, and 26% SL in Webs at ends of Floorbeams.	

92A1-Type: _____ If "X4-Other" Description: _____
 93A1-Rating: Prev. New FC Method: Prev. _____ New: MP DP UT V
 93A2-Remarks: _____

92A1-Type: _____ If "X4-Other" Description: _____
 93A1-Rating: Prev. New FC Method: Prev. _____ New: MP DP UT V
 93A2-Remarks: _____

92A1-Type: _____ If "X4-Other" Description: _____
 93A1-Rating: Prev. New FC Method: Prev. _____ New: MP DP UT V
 93A2-Remarks: _____

92A1-Type: _____ If "X4-Other" Description: _____
 93A1-Rating: Prev. New FC Method: Prev. _____ New: MP DP UT V
 93A2-Remarks: _____

92A1-Type: _____ If "X4-Other" Description: _____
 93A1-Rating: Prev. New FC Method: Prev. _____ New: MP DP UT V
 93A2-Remarks: _____

	Signature	Date
Inspection Team Leader:	<i>Joe Deckard</i>	01/05/2022
Consultant Program Manager:		
Agency Program Manager:	<i>William A. Beisner</i>	<i>1/4/2022</i>

Two Girder

- A1- Suspension Link & Pin
- A2- Suspension Single Pin
- A3- Tension Flanges Riveted/
Bolted Plate Girders
- A4- Bearing Seat of Suspended
Spans
- A5- Tension Flange of Rolled
Beam
- A6- Tension Flange of Welded
Plate Girders
- A7- Tension Flanges of Lattice
Truss Web Girders

Truss System

- B1- Eyebar & Pin Tension Members
- B2- Simple Span Welded Truss
Tension Members
- B3- Hanger Link & Pin of Suspended
Trusses
- B4- Single Element Tension Members
- B5- Simple Span Riveted/Bolted
Tension Members
- B6- Continuous Truss System- Welded,
Riveted or Bolted Tension Members

Cable Stayed & Suspension

- C1- Suspension Bridge- Cables
- C2- Cable Stayed- Cables
- Tied Arches**
- D1- Welded Box Ties
- D2- Riveted/Bolted Box Ties
- D3- Stiffened Girders
- Framed Steel Substructure**
- E1- Welded or Rolled Pier Cap
- E2- Riveted or Bolted Pier Cap
- E3- Welded or Rolled Pier Column
- E4- Riveted or Bolted Pier Column

Box Beams

- F1- Single Welded Box
- F2- Single Riveted/Bolted Box
- F3- Double Box Beam- Welded,
Riveted or Bolted
- Other Types**
- X1- Bascule
- X2- Floorbeams supporting other
steel members or spacing > 15 ft.
- X3- Cross Frames or Transfer
Beams
- X4- Other



Bridge Inspection Report

Structure Number: 099-0008 Date: 8/9/2021
 Inspector 1: Joe Deckard Qualification: IDOT I Employer: IDOT
 (IDOT, ASNT Level, etc.)
 Inspector 2: Various Qualification: IDOT I Employer: IDOT
 Prev. Insp. Date: 08/05/2019 Girder #1 on East side Upstation to South # joints =

Pin Data*:

Diam: 6.5" Length: 27.8" Material: A276 # nuts/end: 2

*If pin geometry varies between joints, use separate sheets.



For pins with special features (cotter pins, integral head, stepped shoulder) attach sketch of pin to report; Sketch

UT data:

Trans. diam: 1" Freq: 3.5 MHz Gain: 50% sc. ht. 60 dB Scan at 70 dB

Link data:

Width: 1.33" CL - CL Pins: 16.75" Thickness: 1.5" Material: Low Alloy (A242)



Span # 1

Span # 7

Nor Abut Pier # 1 Looking E

Pier # 6 S Abut

Check or "ok" indicates acceptable. For remarks, see below.

Member	Span	Dist to Pier #	Top/Single Pin	Bot Pin	Near Link	Far	Inspector #
L0E	4	at P3	OK	OK	OK	OK	1
L0W	4	at P3	OK	OK	OK	OK	1
L0'E	6	at P6	OK	OK	OK	OK	1
L0'W	6	at P6	OK	OK	OK	OK	1

Inspection Remarks:

Inspector	Signature	Date
Inspector 1:	<i>Joe Deckard</i>	01/04/2022
Inspector 2:		



SN: 099-0008	District: 1	Spans: 3	Appr. Spans: 4	Skew: 0	ADT: 24200	Truck Pct: 7
ADT Un:	Maint. Co: Will	Twsp: Channahon	Status: Open- No restriction.			
Facility Carried: I - 55 South bound			Feature Crossed: Des Plaines River			
Location: 2.3 Miles South of US 6		Municipality:	Team/Sub Section: 137/555	Insp/Rte: 24		
Bridge Name: Smith Bridge			Material & Type: Steel Continuous/ Cantilever through Truss			
Insp. Intervals Routine: 24		Fracture Critical: 24	Underwater: 60	Special: 0	Element Level: 24	
93C- Inspection Date: 08/09/2021		93C6- Temp. (°F): 80				
Is Delinquent: <input type="checkbox"/>	Reason:					
90E-Agency Program Manager: William A. Beisner		90E3-Consultant Program Manager:				
90E1- Team Leader: Joe Deckard		90E2- Inspector: Keith Cason-Gossett				

Resources

Time to Inspect (H:M):	<u>40</u> : <u>0</u>	40 : 0	Traffic Control: <u>Y</u>	Y	Boat: <u>1</u>	1	Waders: <u>_</u>	Snooper: <u>2</u>	2
Ladder: <u>_</u>	Manlift: <u>1</u>	1	Bucket Truck: <u>_</u>	Other: _____					

Inspector's Appraisals

Element	Element Description	Env	Quantity	Unit	CS1	CS2	CS3	CS4
12	Reinforced Concrete Deck	4	17036	SF	16593	273	60	110
	Remarks	<1% spall/ delamination with additional deficiencies						
29	Steel Deck with Concrete Filled Grid	4	32432	SF	6868	25263	301	0
	Remarks	10% Spalling. Steel forms have measurable corrosion, connections show cracks						
8102	Steel Beam/ Girder/ Stringer End	4	114	EA	36	70	8	0
	Remarks	8% with corrosion showing measurable section loss						
107	Steel Open Girder/ Beam	4	2886	LF	2790	16	40	40
	Remarks	2% with corrosion showing measurable section loss						
113	Steel Stringer	4	8262	LF	1694	5250	1318	0
	Remarks	15 % with corrosion showing measurable section loss < 1/16"						
120	Steel Truss	4	918	LF	843	75	0	0
	Remarks	8% Corrosion showing measurable section loss < 1/16"						
152	Steel Floor Beam	4	1332	LF	324	850	158	0
	Remarks	11 % with corrosion showing measurable section loss < 1/16"						
161	Steel Pin and Pin Hanger Assembly or both	4	64	EA	64	0	0	0
	Remarks							
162	Steel Gusset Plate	4	212	EA	100	92	20	0
	Remarks	10% with corrosion showing measurable section loss						
205	Reinforced Concrete Column	4	14	EA	10	4	0	0
	Remarks	Minor cracking						
210	Reinforced Concrete Pier Wall	4	252	LF	158	94	0	0
	Remarks	Minor cracking						
215	Reinforced Concrete Abutment	4	102	LF	102	0	0	0
	Remarks							
234	Reinforced Concrete Pier Cap	4	206	LF	139	67	0	0
	Remarks	Minor cracking						
300	Strip Seal Expansion Joint	4	180	LF	176	4	0	0
	Remarks	Cracks along seals						
301	Pourable Joint Seal	4	252	LF	252	0	0	0
	Remarks							
303	Assembly Joint with Seal (Modular)	4	36	LF	36	0	0	0
	Remarks							
310	Elastometric Bearing	4	108	EA	12	84	12	0
	Remarks	80% with little deterioration 10% with minor deterioration						


Element Level Inspection Report

Structure Number: 099-0008

Element	Element Description	Env	Quantity	Unit	CS1	CS2	CS3	CS4
311	Movable Bearing	4	10	EA	6	4	0	0
	Remarks	Surface rust						
313	Fixed Bearing	4	14	EA	6	8	0	0
	Remarks	Surface rust						
330	Metal Bridge Railing	4	1842	LF	1567	275	0	0
	Remarks	Surface rust, loose fasteners						
331	Reinforced Concrete Bridge Railing	4	964	LF	732	232	0	0
	Remarks	Cracks/delaminations						
8510	Flexible Wearing Surface	4	32432	SF	25470	6962	0	0
	Remarks	Minor cracking						
8511	Rigid Waring Surfaces	4	17036	SF	15334	1702	0	0
	Remarks	Minor cracking						
515	Steel Protective Coating	4	125442	SF	77067	40840	6940	595
	Remarks	Surface dulling, loss of pigment						
	Remarks							
	Remarks							
	Remarks							
	Remarks							
	Remarks							

	Signature	Date
Inspection Team Leader:	<i>Joe Deckard</i>	01/04/2022
Consultant Program Manager:		
Agency Program Manager:	<i>William A. Beisner</i>	<i>1/4/2022</i>

P 4



Detail A

Underwater Investigation

Sheet 1 of 3


Structure number: 099-0008

Water Elevation: 504.4'

Inspection date: 08/10/2021

Inspected by: A. Young, M. Rives, & J. Deckard

Detail/Dimension /Elevation: A / 3.6' / 508.02'



	50'	25'	Edge	Center Line	Edge	25'	50'
50'(+/-)	502	502	502	502	502	502	502
25'(+/-)	502	502	502	502	502	502	502
Edge	502	502	502	502	502	502	502
Centerline	502	502	502	<div style="border: 1px solid black; padding: 5px;"> <p align="center">PIER: 3</p> <p>Flow direction:</p> <p>Top Footing Elevation: 494.98'</p> <p>Bottom Footing Elevation: 490.48'</p> <p>Design Stream Bed Elevation: North /A</p> <p>Bottom Seal coat: 480.00'</p> </div>			
Edge	502	502	502	502	502	502	502
25'(+/-)	502	502	502	502	502	502	502
50'(+/-)	502	502	502	502	502	502	502

Underwater Investigation

Sheet 2 of 3


Structure number: 099-0008

Water Elevation: 504.4'

Inspection date: 08/10/2021

Inspected by: A. Young, M. Rives, & J. Deckard

Detail/Dimension /Elevation: A / 3.6' / 508.02'



	50'	25'	Edge	Center Line	Edge	25'	50'
50'(+/-)	502	494	493	493	493	491	492
25'(+/-)	502	497	495	495	495	493	492
Edge	502	502	497	498	498	494	493

PIER: 4

Flow direction:

**Top Footing
Elevation: 496.02'**

**Bottom Footing
Elevation: 490.02'**

**Design Stream Bed
Elevation: North /A**

Bottom Seal coat: 478.52'

Centerline	502	502	502	502	498	495	494
Edge	502	502	502	500	500	495	494
25'(+/-)	502	502	502	501	501	496	497
50'(+/-)	502	502	501	501	500	499	498

Underwater Investigation

Sheet 3 of 3


Structure number: 099-0008

Water Elevation: 504.4'

Inspection date: 08/10/2021

Inspected by: A. Young, M. Rives, & J. Deckard

Detail/Dimension /Elevation: A / 3.6' / 508.02'



	50'	25'	Edge	Center Line	Edge	25'	50'
50'(+/-)	503	503	501	500	503	503	503
25'(+/-)	503	503	501	501	503	503	502
Edge	503	503	501	501	503	503	503

PIER: 5

Flow direction:



Top Footing
Elevation: 500.02'

Bottom Footing
Elevation: 494.02'


Design Stream Bed
Elevation: North /A

Bottom Seal coat: 485.02'

Centerline	503	503	502		503	503	503
Edge	494	494	498	499	503	503	503
25'(+/-)	494	494	494	498	503	503	503
50'(+/-)	494	494	490	494	503	503	503



⊙ ITEM IN DEF. TABLE



DES PLAINES SMITH BRIDGE
099-0008
PAGE 1

Items Removed from Table of Deficiencies

These items have been removed from the Table of Deficiencies
9, 30, 77, 79, & 82

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
1	All	Paint	Throughout	1,2,3,4	See ELI Form	N/A Zone Paint at Joints & sides	2000	
2	1,2,3,7	Concrete Deck	Throughout	5, 6	See ELI Form	N/A	2000	
3	4,5,6	Filled Grid Deck	Throughout	7, 8	See ELI Form	N/A	2001	
4	All	Overlay	Throughout	9, 10	See ELI Form	N/A	2000	
5	1,2,3,7	Concrete Parapet	Throughout	11	See ELI Form	N/A	2005	
6	4,5,6	Aluminum Parapet	Throughout	12	A few losse bolts	N/A	2009	
127	4,5,6	Floorbeams at Relief Joints	at Stringer 3-Stringer 7	13	4% SL , 10- 13/16” Misdrilled Holes in Web of Floorbeam (1 in section)	N/A 4 % SL , IRF=1.50	2007	
7	2-7	Drain	Throughout	See Table 1	Missing Drain exterior & Drain covers (See Table 1)	Repair	2005	
8	4,6	Portal Frame	Lower Horizontal	14	Excessive Pigeon waste throughout	Clean	2015	
135	1	Cross Frame	3 RD Cross Frame from North Abutment at Girder 3, West side	15 LE	7 ½” crack in angle of Cross Frame	Repair	2017	
10	1	Cross Frame	3 RD Cross Frame from North Abutment at Girder 5, East face	16 LW	1 – 6” L crack at bottom of Stiffener & 2 Sheared Rivet heads	Repair	2011	
11	1	Girder 6	1 ST Stiffener South of 3 RD Cross Frame from Abutment East side	17 LW	Bent Stiffener 10" X 1" offset	N/A	1999	
12	1	Girder 2	2 ND Stiffener South of 4 TH Cross Frame from Abutment East side	18 LW	Bent Stiffener 15" X 1" offset	N/A	2001	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
13	2	Girder 3	2 ND Cross Frame from Pier 1	19 LE	Bottom Flange 24" X 3/8" offset	N/A	1999	
14	2	Girder 1	Midspan, between Cross Frame 4 & 5 from Pier 1, West face	20 LE	Bottom Flange 20" X 3" offset	N/A	1999	
136	2	Cross Frame	5th Cross Frame from Pier 1 at Girder 5	21 LS	1 loose Bolt	Repair	2017	
16	2	Girder 5	5th Cross Frame from Pier 1, West side	22 LE	16% SL , Web 12-13/16" Misdrilled Holes 11 filled with Caulk (See Detail 2)	N/A 16% SL , IRF=1.76	2011	
15	2	Girder 1	North of 6 TH Cross Frame from Pier 1, West side	23 LE	Top Flange 24" X 1 5/8" offset	N/A	1999	
17	2	Girder 6	2ND splice North of Pier 2	24 LE	12- rusted rivet heads with up to 75% SL	Repair	2013	
18	3	Girder 4	1 ST Stiffner North of C.F .3, from Pier 2, East face	25 LW	14 ¼" X ¾" offset in Stiffener	N/A	2015	
19	3	Cross Frame	4TH Cross Frame from Pier 2 at Girder 4 East & West sides	26 LW 27 LE	2" crack West & 3 ¼" crack East in angle of Cross Frame	Repair	2013	
20	3	Bearing	Girder 1 at Pier 3	28 LSE	30% SL in Bolster, 20% SL and 1" Hole in retainer, missing nut on West Anchor Bolt	N/A 30% SL in Bolster,, 20% SL to retainer IRF=34.80	2015	
21	3	Bearing	Girder 2, at Pier 3	29 LSW	20% SL in Bolster, 10% SL to retainers, missing nut on East Anchor Bolt	N/A 20% SL in Bolster, 10% SL to retainer IRF=24.23	2015	
22	3	Bearing	Girder 3, at Pier 3	30 LS	5% SL on Bolster, crack welds on North side, Bottom Flange to sole Plate, ½" on East end, 1" on West end	Repair	2015	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
23	3	Bearing	Girder 4, at Pier 3	31 LS	10% SL on Bolster, 40% SL on West retainer, loose Anchor Bolt, West side, crack weld on North side, between Bottom Flange & sole plate, 5" on East end	Repair	2015	
24	3	Bearing	Girder 5, at Pier 3	32 LSE	10% SL on Bolsters and retainers	Repair	2015	
25	3	Bearing	Girder 6, at Pier 3	33 LSW	13% SL on Bolster (See Detail 3), 50% SL with 1" Hole on retainer	N/A 13% SL on Bolster, 50% SL to retainer IRF=43.59	2015	
26	4	Gusset Plate	L0E (inside)	34 LNW	21% SL , inside Gusset Plates (See Detail 4)	N/A	2009	
27	4	Floorbeam 0	2' East of Midspan (Flange) throughout (Web)	35 LN	10% SL , Bottom Flange 4 – 5/8" Misdrilled Holes (2 in section) 7% SL , Web 4' X full length area of loss with .26" average remaining .72" nominal	N/A	2015	
28	4	L0E-L1E	at L0E, 2' North of L1E, & at L1E	36 LE	23% SL in Channels at L1E, 2 – 2" Holes in Channel Top Plate at 2' North (See Detail 5)	N/A 9% SL , IRF<4.6, 23% SL , IRF=4.64	2011/ 2013	
29	4	Stringer 2	Panel 1, full length	37 LS	29% SL Top Flange (See Detail 6)	N/A 29% SL , IRF=1.49	2011	
31	4	LOW-L1E	3' from LOW 3' from L1E	38 LSE	20% SL , 2" Hole in bottom of angle (LOW) 20% SL , 1" Hole in bottom of angle (L1E)	N/A	2015	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
32	4	Floorbeam 1	East end	39 LS 40 LN	21% SL Bottom Flange, 4% SL in Web (See Detail 7) 1" X 1/8" Diameter gouge in Web	N/A 21% SL , IRF=1.96	2011/ 2013	
33	4	Stringer 7	Panel 2, North end, East face	41 LNW	1 fully craked weld (connection Plate to Web), 2 part cracked welds (Form to connection Plate) (face of dead load counter weight)	N/A	2015	
34	4	L1W-L2W	at L1W	42 LW	5% SL , in Channels (See Detail 8)	N/A 5 % SL , IRF=4.63	2011/ 2013	
137	4	L1W-L2E	at L1W	43 LNW	15% SL , 2" area SL with 1" Hole	N/A	2017	
35	4	L1E-L2E	4' South of L1E, Top Plate	44 LW	0% SL , 1" Hole in Top Plate	N/A	2015	
36	4	U1E-L2E	3' from L2E	45 LW 46 LE	6% SL , 6" X 3' L area of loss with 3" hole and a 1" hole in Channel	N/A 6% SL , IRF=1.93	2009	
37	4	L1E-L2W	at L2W	47 LE	35% SL , 4" Hole horizontal leg	N/A	2011/ 2013	
38	4	Stringer 9	at Floorbeam 2 Panel 2	48 LS	27% SL Flange, 3% SL Web (See Detail 9)	N/A No Live Load 2013	2011/ 2013	
39	4	Floorbeam 2	Each end	49 LS 50 LS	11% SL , Web (See Detail 10)	N/A 10% SL , IRF=1.92	2013	
138	4	Gusset Plate	L2E (inside)	51 LS	26% SL , (See Detail 49)	Repair	2017	X
40	4	Gusset Plate	L2W (outside)	52 LN	7% SL , (See Detail 11)	N/A	2009	
41	4	L2E-L3E	at L2E	53 LE	5% SL , F.H. X 2" L area with .405 average remaining Webs, .45 nominal (2-C18 X 42.7)	N/A 5% SL , IRF=1.81	2011/ 2013	
157	4	Joint	Panel Point 3 East lane	54 LE	3' failed East side	Repair	2021	
42	4	Stringer 7	at Floorbeam 3, Panel 3	55 LS	2-missing Bolts in Stringer seat	Repair	2011	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
43	4	Floorbeam 3	Throughout	56 LS	7% SL Web, .67 average remaining, .725 nominal,	N/A 7% SL , IRF=2.03	2011/ 2013	
44	4	L3W-L4E	Last 8' from L3W	57 LNW	30% SL, 1" Hole in horizontal leg of angle	N/A	2015	
45	4	Stringer 3	Panel 4, at Midspan	58 LSW	16% SL, Bottom Flange, (See Detail 12)	N/A 16% SL, IRF=1.56	2015	
139	4	Diaphragm	Panel 4, at Stringer 6 Midspan	59 LSW	1 missing Bolt in Top connection angle	Repair	2017	
46	4	Gusset Plate	L6E (inside)	60 LS	16% SL, (See Detail 13)	N/A No Live Load 2013	1999	
47	4	Stringer 1	at Floorbeam 7 Panel 7	61 LS	5% SL Web, .37 average remaining for 12", .39 NOM	N/A	2011/ 2013	
48	4	Stringer 9	at Floorbeam 7 Panel 7	62 LE	17% SL Web, 8% SL Bottom Flange (See Detail 14)	N/A No Live Load 2013	2011/ 2013	
49	4	L6W-L7E	2' from L7E	63 LNW	10% SL, 1" X 4"L Hole in horizontal leg	N/A	2015	
50	4	Gusset Plate	at U7W (outside)	64 LE	1" Hole	N/A	2009	
51	4	Portal Frame	lowest horizontal between Panel Point 7 & Panel Point 8, East lane	65 LS	40" X 1" offset	N/A	2001	
52	4	L7E-L8W	Last 6' from L8W	66 LSW	30% SL, 2-1" Holes in horizontal leg	N/A	2013	
53	4	Stringer 1	at Floorbeam 8, Panel 8	67 LS	8% SL Bottom Flange 3% SL Web, (See Detail 48)	N/A No Live Load 2013	2011/ 2013	
54	5,4	Gusset Plate	See Table 15	?	16% SL, Gusset Plate thickness less than Plans (See Table 15)	Repair	2009	X
55	5	Portal Frame	Panel Point 8, lowest horizontal, middle of South bound lanes	68 LS	11" X ½" offset	N/A	2009	
56	5	Stringer 1	at Floorbeam 8 Panel 9	69 LNE	14% SL Web, (See Detail 16)	N/A No Live Load 2013	2011/ 2013	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
57	5	Stringer 7	at Floorbeam 8, Panel 9	70 LW	½” Notch at top of Cope	N/A (In repaired area)	2011	
58	5	Stringer 3	at Floorbeam 9, Panel 9, full length	71 LSW	11% SL Web, 9% SL, Bottom Flange (See Detail 17)	N/A 11% SL, IRF=2.25	2011/ 2013	
59	5	Stringer 8	at Floorbeam 9, Panel 10	72 LSW	11% SL Web, 17% SL Bottom Flange (See Detail 18)	N/A 11% SL Web, 17% SL Bottom Flange IRF=2.64	2011/ 2013	
140	5	Stringer 7	full length, Panel 10	73 LSW	26% SL, Bottom Flange, 16% SL, Top Flange 7% SL Web (See Detail 47)	N/A 27% SL, Bottom Flange, 17% SL, Top Flange 7% SL Web IRF=1.34	2017	
60	5	L9W-L10E	at L10E	74 LW	2” & 1” Holes in bottom connection Plate	N/A	2009	
61	5	Gusset Plate	L10W (outside)	75 LNW	13% SL, (See Detail 19)	Repair	2009	X
62	5	Stringer 1	at Floorbeam 10, Panel 11	76 LNW	5% SL Web, 19 % SL Flange (See Detail 20)	N/A No Live Load 2013	2011/ 2013	
63	5	U10E-U11E	at U11E	77 LSE	1” Crack in 3” Tack Weld (Tension Member)	N/A	2001	
64	5	Stringer 1	at Floorbeam 12, Panel 12	78 LS	25% SL Bottom Flange, 5% SLin Web at Cope (See Detail 21)	N/A No Live Load 2013	2011/ 2013	
65	5	Stringer 9	at Floorbeam 12, Panel 13	79 LNE	19% SL Bottom Flange (See Detail 22)	N/A No Live Load 2013	2011/ 2013	
151	5	Lateral Brace L12W to mid Floorbeam 13	5’ & 10’ from L12W	80 LSE	2-broken Rivets connection 2 Angles	N/A	2019	
66	5	Stringer 1-9	at Floorbeam 13, Panel 13	81 LSW	0% SL, 2” X 9”L abandoned Holes (reinforced)	N/A	2013	
67	5	Floorbeam 13	West end	82 LN	26 % SL, Web (See Detail 23)	Repair 22 % SL, IRF=1.73	2011/ 2013	X
141	5	Slide Pin	at U13E	83 LNE	3/16” Grooves	N/A	2017	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
68	5	Stringer 5	at Floorbeam 13, Panel 13	84 LW	0% SL, 1" X 3"L Hole top of Web, 1" Hole above repair angle	N/A	2005	
69	5	Lateral Brace	mid Floorbeam14 to L13E & mid Floorbeam14 to L13W at mid Floorbeam14	85 LN	12% SL, 8 – 13/16" Misdrilled Holes in Lateral Brace at connection Plate (2 in section)	N/A	2015	
70	5	Stringer 3	Panel 14, full length	86 LNW	9% SL BottomFlange 3% SL Web (See Detail 24)	N/A 9% SL, IRF=1.64	2011/ 2013	
71	5	Stringer 1	at Floorbeam 14 , Panel 14	87 LS	12 % SL Web (See Detail 25)	N/A No Live Load 2013	2011/ 2013	
72	5	L13E-L14E	at L14E	88 LSW	9% SL, (See Detail 45)	N/A 7% SL, IRF=4.56	2009	
73	5	L14W-U14W	at L14W, I.South Channel	89 LE	9% SL (See Detail 26)	N/A 9% SL, IRF=1.59	2011/ 2013	
74	5	L14W-L15W	at L14W & L15W	90 LE	10% SL (See Detail 26)	N/A 10 % SL, IRF=4.56	2011/ 2013	
75	5	Stringer 3	Panel 15, Full Length	91 LS	19% SL Bottom Flange, 9% SL Web, 16% SL Top Flange (See Detail 27)	Repair 15 % SL, IRF=1.57	2011/ 2013	
152	5	U14W-U15E	6' East of Centerline	92 LE	24" X 1" offset	N/A	2019	
76	5	L14E-L15W	at L15W	93 LW	10% SL, 1" X 2"L Hole in connection Plate	N/A	2015	
158	5	Joint	Panel Point 15 West lane	94 LN	3' Failed West side	Repair	2021	
78	5	L14E-L15E	at L15E	95 LW	6% SL, .41" average remaining in Top Web .40" average remaining exterior Web, 0.45" nominal	N/A 6 % SL, IRF=4.56	2013	
80	5	U15W-U16W	at U15W	96 LW	Partially cracked Tack Weld at I.South Gusset Plate	N/A	2011	
153	5	L15E-L16E	1' from L16E	97 LE	0% SL, 2" Hole in Top Plate (between access Holes)	N/A	2019	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
81	5	L15W-L16W	4' South of L15W	98 LE	0% SL, 2" Hole in Top Plate (between access Holes)	N/A 0% SL, IRF=2.83	2009	
83	5	L16E-L17E	at L16E & L17E, Top Plate	99 LS	5% SL, (See Detail 28) at L16E 0% SL, 4" X 15" L Hole in Top Plate, at L17E	N/A 5% SL, IRF=2.83	2013	
84	5	Gusset Plate	at L17W	100 LNE	11% SL(See Detail 29) (inside) 20% SL(See Detail 30) outside	Repair 7% SL, 12% SL IRF=3.58	2009	X
85	5	Floorbeam 17	West end	101 LNW	25% Bottom Flange, 14% SL Web (See Detail 46)	N/A 14% SL Web, 25% SL Flange, IRF=1.829	2011/ 2013	
154	5	L17E-L16'E	at L17E	102 LN	0% SL, 4" Hole in Top Plate (between access Holes)	N/A	2019	
142	5	L17W-L16'W	2' from L17W	103 LN	0% SL, 2" Hole in bottom Plate (between access Holes)	N/A	2017	
86	5	Stringer 9	at Floorbeam 16', Panel 17'	104 LSE	13% SL Web (See Detail 31)	N/A No Live Load 2013	2011/ 2013	
87	5	Gusset Plate	L16'E (outside)	105 LW	16" X 1/2" offset due to Pack Rust	N/A	2009	
88	5	L16'E-L15'E	at L16'E	106 LW	4% SL (See Detail 32)	N/A 4% SL, IRF=2.83	2011/ 2013	
89	5	U16'E-U16'W	at U16'E	107 LS	2- 1/4" Deep cuts into side Bottom Flange	N/A	2011	
143	5	L16'E-L15'E	2' from L15'E	108 LS	0% SL, 1" Holes in Top & bottom Plate (between access holes)	N/A	2017	
144	5	L16'E-L15'W	Last 4' from L15'W	109 LW	30% SL in angles, 2" Hole, 15% SL in bottom connection Plate, 1" Hole	N/A	2017	
90	5	Gusset Plate	L15'W (outside)	110 LN	9% SL, (See Detail 33)	N/A	2009	
91	5	Gusset Plate	L15'W (inside)	111 LN	10% SL, (See Detail 34)	N/A	2009	
92	5	Gusset Plate	L15'E (inside)	112 LE	10% SL, (See Detail 35)	N/A	2009	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
145	5	L15'W-U15'W	2' & 5' above Deck	113 LSW	5" X ½" offsets (each location)	N/A	2017	
146	5	Joint	Panel Point 15', West lane	114 LE	6' failed on West side 3' failed on East side	Repair	2017	
147	5	L15'E-L14'W	at L15'E	115 LW	10%SL, 1" Hole in bottom connection Plate	N/A	2017	
93	5	U15'W-U14'E	at U14'E	116 LS	3- ¼" Cuts into side Top Flange	N/A	2011	
94	5	L15'E-L14'E	at L14'E	117 LSW	6%SL (See Detail 36)	N/A 6 %SL, IRF=4.56	2011/ 2013	
95	5	L14'E-L13'E	at L14'E	118 LW	6%SL (See Detail 36)	N/A 6 %SL, IRF=4.56	2011/ 2013	
148	5	Lateral Brace	L14'E – mid Floorbeam13' at L14'E	119 LSW	30%SL 2" Hole in horizontal angle & 1 broken Rivet	N/A	2017	
96	5	Stringer 1	at Floorbeam13', Panel 14'	120 LE	36% SL Web, (See Detail 37)	N/A No Live Load 2013	2011/ 2013	
97	5	Slide Pin	at U13'E	121 LS	3/16" grooves	N/A	2015	
98	5	L13'E-U13'E	at L13'E	122 LW	4% SL, 10" X 1"L area of loss in Plate; 0.375" average remaining, 0.5" nominal	N/A 4 % SL, IRF=4.87	2009	
99	5	Floorbeam 13'	East end	123 LS	7% SL, Web .71" average remaining, .765" nominal	N/A 7 % SL, IRF=2.14	2013	
149	5	Joint	Panel Point 13', East & West lane	124 LN	6' failed on W side, 3' failed on E side	Repair	2017	
100	5	Stringer 1, 3-9	at Floorbeam13', Panel 13'	125 LW	0% SL, 2" X 4"L abandoned Holes (Reinforced)	N/A	2013	
101	5	Stringer 2	at Floorbeam13', Panel 13'	126 LE	0% SL, 2" X 4"L abandoned Hole (Reinforced), 2" X 4"L Hole	N/A	2013	
102	5	Gusset Plate	U13'W (outside)	127 LSW	2-plug weld on plate	N/A	2009	
103	5	Gusset Plate	U13'W (inside)	128 LSE	2-plug weld on plate	N/A	2009	
104	5	L13'W-U13'W	U13'W 18" below pin centerline	129 LW	0% SL, ½" X 2"L Torch cut, ¼" X 1"L Torch cuts on bottom fill Plate	N/A 0 % SL, IRF=5.07	2009	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
105	5	L13'W-U13'W	L13'W 18" above pin Centerline	130 LE	0% SL, ½" X 2"L & ½" X 3"L Torch cuts on top fill Plate	N/A 0 % SL, IRF=5.07	2009	
106	5	Lateral Brace	Midstrut to L12'E, 10' from L12'E	131 LS	5 Broken Rivets	Repair	2013	X
108	5	Gusset Plate	L12'W (inside)	132 LE	3% SL (See Detail 39)	N/A 3% SL, IRF=1.46	2009	
109	5	Floorbeam 12'	West end	133 LN	7% SL Web .675" average remaining Web .725" nominal	N/A 7 % SL, IRF=2.01	2011/ 2013	
107	5	Stringer 9	at Floorbeam 12', Panel 12'	134 LN	14% SL Web (See Detail 38)	N/A No Live Load 2013	2011/ 2013	
110	5	L12'W-L11'W	at L12'W	135 LN	5% SL .64" average remaining in Webs, 0.700" nominal	N/A 5 % SL, IRF=2.63	2011/ 2013	
111	5	Stringer 2	at Floorbeam 11' Panel 12'	136 LS	6% SL, Web 14" Cope .37 average remaining, .39" nominal	N/A 6% SL, IRF=2.80	2013	
112	5	Stringer 7	at Floorbeam 11' Panel 12'	137 LN	1/8" Notch in Top Cope	N/A	1999	
113	5	Floorbeam 11'	at Stringer 3	138 LS	5% SL, 15" X 24"L area of loss in Web; 0.65" average remaining, 0.725" nominal	N/A 5% SL, IRF=1.21	2009	
114	5	Sway Brace	Centerline at Panel Point 11'	139 LNE	6% SL, 1" Misdrilled Hole	N/A	2013	
115	5	Gusset Plate	L10'E (inside)	140 LN	13% SL (See Detail 40)	N/A 13% SL, IRF=2.40	2009	
116	5	Stringer 5	3' South of Floorbeam 10'	141 LE	8% SL Web, 2" X 3/8" Torch cut	N/A 8% SL, IRF=2.30	2009	
117	5	L9'E-L8'W	at L9'E	142 LE	10% SL, 1" X 2" Hole in bottom connection Plate	N/A	2015	X
118	5,6	Floorbeam 8'	East & West end	143 LS	6% SL Web .68" remaining .725" NOM, 5/8" average at end 2' of Bottom Flange	N/A 6 % SL, IRF=2.03	2011/ 2013	
119	6	Portal Frame	Between Panel Point 7' & Panel Point 8' over driving lane	144 LSE	6" X 1/8" offset	N/A	2000	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
120	6	Stringer 1	Midspan, Panel 8'	145 LSW	16% SL Bottom Flange (See Detail 41)	N/A No Live Load 2013	2011/ 2013	
121	6	L7'W-U7'W	mid height	146 LW	8" X 5/8" offset & 6" X 3/8" offset	N/A	2009	
122	6	Stringer 2 – 9	at Floorbeam 6'	147 LW	0% SL, 2 - 7/8" misdrilled Holes in Stringer Web repair Plate	N/A	2015	
150	6	Joint	Panel Point 6', West lane	148 LE	15' failed on West side	Repair	2017	X
123	6	U5'E-U4'E	U5'E	149 LNE	Fully crack tack weld between inside gusset plate and upper chord	N/A Crack relieved	2009	
124	6	Gusset Plate	L4'W (inside)	150 LNE	4% SL, (See Detail 42)	N/A	2009	
125	6	Floorbeam 4'	each end	151 LS	3% SL, Web .702 average remaining, .725 nominal (East) 5% SL Web .691" average remaining, .725 nominal (West)	N/A 5 % SL, IRF=2.06	2013	
126	6	Stringer 7	Panel 4' full length	152 LSW	8% SL Top Flange, 6% SL Web, 19% Bottom Flange (See Detail 43)	N/A 8% SL Top Flange, 6% SL Web, 19% Bottom Flange, IRF=1.47	2011/ 2013	
128	6	L3'E-L2'East	at L3'E & L2'E	153 LW	5% SL .403 average remaining Webs (.45 nominal)	N/A 5 % SL, IRF=1.80	2011/ 2013	
129	6	L2'E-L1'W	at L2'E	154 LE	2" Hole in bottom connection plate	N/A	2015	
130	6	Gusset Plate	L2'W (outside)	155 LNE	6% SL, (See Detail 44)	N/A	2009	
155	6	Stringer 7	Panel 2' full length	156 LW ?	10% SL Bottom Flange, .618 average remaining .682 nominal	N/A	2019	X
131	6	L2'W-L1'W	at L1'W	157 LS	7% SL, 11" X 3"L area of loss in Channels; 0.345" average remaining, 0.45" nominal	N/A 7 % SL, IRF=1.93	2009	

TABLE OF DEFICIENCIES (TOD)

Photo Direction denoted as LN = Looking North

SN: 099-0008

IRF=Inventory Rating Factor

In reference to stiffener, diaphragm, and crossframe:

Date: August 9, 2021

% SL shown is estimated

The first shall be on the Pier or Abut.

“?” Indicates new photo needed

Item #	Span(s)	Member(s)	Location(s)	Photo(s)	Deficiency(ies)	Corrective Action	Year	Load Cap. Re-Eval.
159	6	L1'E-L2'E	at L1' E	158 LSW 159 LSW	12% SL Lower Chord East side channel web with 1" and 2" holes. 2-4" holes in top of bottom chord, holes in line with access holes (See Detail 1)	Repair	2021	X
156	6	L1'E-L0'E	at L0'E	160 LS	22% SL in East Channel web, .399" average remaining in both Webs, .45" nominal (Detail 51)	N/A	2019	X
132	6	Floorbeam 0'	South side of Floorbeam	161 LE	14 Bracket welded to Bottom Flange	N/A	1999	
133	7	Cross Frame	at Pier 6, between Girder 5 & Girder 6	162 LS	26% SL, 3" & 1" X 2"L Hole in lower horizontal angle	N/A	2015	
134	7	Girder 1 & Girder 6	10' from Pier 6	163 LN 164 LW	Broken Bolts on temporary support 1 at G1 Flange connection 4 at G6 Flange connection, 4 Misdrilled Holes in vertical connection at G1 & G6		1999	X
151	7	Girder 3	at South Abutment	165 LSE	2" & 1½" Crack in Bottom Flange (See Detail 50)	N/A	2017	

Table 1			
Span	Location	Deficiency	Photo
2	Midspan, West side	missing drain cover	166 LS
5	2' South of Floorbeam 16' East side	1" hole in drain extention	*2017 ?
7	1 ST dain South of P6, West side	missing drain cover	167 LW

SPAN 6 @ L1'E

L1'E-U1'E

099-0008
ITEM 159
DETAIL 1

C18 x 42.7#

$d = 18.0$


$b_f = 3.95$

$t_w = 0.45$

15" x $\frac{3}{8}$ "


PLATES TOP & BOT.

w/6" x 12" L HOLES




ELEVATION

(Looking West)



SEC. A-A

(Looking South)



SEC. B-B

(Looking South)



- HOLE

- SECTION LOSS








- FULL SECTION

READINGS EQ. SP.

SPAN 2 @ G5

099-0008
ITEM 16
DETAIL 2



-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.

SPAN 4 @ LOE

099-0008
ITEM 26
DETAIL 4

C18 x 42.7#

$d = 18.0$



$b_f = 3.95$




$t_w = 0.45$

15" x 3/8"

PLATES TOP & BOT.


w/6" x 12"L HOLES



-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.




SPAN 4 2L1E & LOE


099-0008
ITEM 28
DETAIL 5



C18 x 42.7#
d = 18.0
bf = 3.95
tw = 0.45
tf = 0.625
15" x 3/8"
PLATES TOP & BOT.
w/6" x 12" L HOLES

ELEVATION
(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION




SEC. A-A


READINGS EQ. SP.

SPAN 4 S2 @ PANEL 1



099-0008
ITEM 29
DETAIL 6



ELEVATION
(LOOKING EAST)




SEC. A-A

-  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.


SPAN 4 FB 1

099-0008
ITEM 32
DETAIL 7




⊕ E. TRUSS



ELEVATION
(Looking South)



SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.

SPAN 4 @ L1W

099-0008
ITEM 34
DETAIL 8

C18 x 42.7#

$d = 18.0$



$b_f = 3.95$

$t_w = 0.45$

15" x $\frac{3}{8}$ "

PLATES TOP & BOT.

w/6" x 12" L HOLES



SEC. A-A


 - SECTION LOSS

 - FULL SECTION


READINGS EQ. SP.

SP. 4
 S9 @ FB. 2 PAN. 2




099-0008
 ITEM 38
 DETAIL 9
 @ FB. 8



ELEVATION
 (Looking East)



SEC. A - A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.

SP. 4 FB. 2



099-0008

ITEM 39


DETAIL 10

⊕ E. TRUSS

⊕ W. TRUSS



SEC. A-A




SEC. B-B

- SECTION LOSS
- FULL SECTION

READINGS EQ. SP.




SPAN 4 @ L2W

099-0008
ITEM 40
DETAIL 11




ELEVATION

(Looking West)


-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.

SP. 4
S3, MIDSPAN, PAN. 4

099-0008
ITEM 45
DETAIL 12



ELEVATION
(Looking East)




 - SECTION LOSS




 - FULL SECTION

READINGS EQ. SP.

SPAN 4 @ L6E



099-0008
ITEM 46
DETAIL 13




-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.

SP. 4
S9 PAN. 7

099-0008
ITEM 48
DETAIL 14



SEC. A-A




READINGS EQ. SP.

SPAN	Gusset Plate LOCATION	NOMINAL THICKNESS	MEASURED THICKNESS
5	L9'E (outside)	0.625"	0.523"
5	L9'E (inside)	0.625"	0.523"
6	L5'E (outside)	0.625"	0.544"
6	L5'E (inside)	0.625"	0.544"
6	L4'E (outside)	0.625"	0.542"


Table 15

SP. 5
S1 @ FB. 8 PAN. 9




099-0008
ITEM 56
@ FB. 8 DETAIL 16




ELEVATION
(Looking West)




SEC. A-A


-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION



ELEVATION
(Looking East)



SEC. A-A



SEC. B-B


 - SECTION LOSS

 - FULL SECTION


READINGS EQ. SP.

SP. 5
S8 PAN. 10

099-0008
ITEM 59
DETAIL 18



\rightarrow A ELEVATION
(Looking West)




- SECTION LOSS
- FULL SECTION




READINGS EQ. SP.

SPAN 5 @ L10W

099-0008
ITEM 61
DETAIL 19



ELEVATION
(Looking West)




-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.

SP. 5
S1 PAN. 11

099-0008
ITEM 62
DETAIL 20

☉ FB. 11


☉ FB. 10




- SECTION LOSS
 - FULL SECTION
 READINGS EQ. SP.

SP. 5
 S1 @ FB. 12
 PAN 12




099-0008
 ITEM 64
 DETAIL 21



ELEVATION
 (Looking West)




SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION


READINGS EQ. SP.

SP. 5
 S9 @ FB. 12 PAN. 13




099-0008
 ITEM 65
 DETAIL 22



ELEVATION
 (Looking East)



SEC. A-A


-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.


SP. 5
FB. 13, W. END

099-0008
ITEM 67
DETAIL 23

⊕ W. TRUSS



ELEVATION
(Looking North)



SEC. A-A



- HOLE



- SECTION LOSS




- FULL SECTION


READINGS EQ. SP.

SP. 5
S3 PAN. 14

099-0008
ITEM 70
DETAIL 24



SECTION A-A
ELEVATION
(LOOKING EAST)



SEC. A-A



- HOLE



- SECTION LOSS




- FULL SECTION


READINGS EQ. SP.

SP. 5
 S1 @ FB. 14 PAN. 14




099-0008
 ITEM 71
 DETAIL 25



ELEVATION
 (Looking East)




SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.


SPAN 5 @ L14W

099-0008
ITEM 73
DETAIL 26






C18 x 42.7#
d = 18.0
b_f = 3.95
t_w = 0.45
15" x 3/8"
PLATES TOP & BOT.
w/6" x 12"L HOLES


ELEVATION
(Looking East)



SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION


READINGS EQ. SP.




SEC. B-B

SP. 5
S3 PAN. 15

099-0008
ITEM 75
DETAIL 27



ELEVATION
(LOOKING EAST)



SEC. A-A

- HOLE
 - SECTION LOSS
 - FULL SECTION
- READINGS EQ. SP.

SPAN 5 @ L16E

099-0008
ITEM 83
DETAIL 28

C18 x 42.7#

$d = 18.0$



$b_f = 3.95$

$t_w = 0.45$

15" x $\frac{3}{8}$ "

PLATES TOP & BOT.

w/6" x 12"L HOLES



SEC. A-A



- HOLE



- SECTION LOSS




- FULL SECTION

READINGS EQ. SP.




SPAN 5 @ L17W
IS GUSSET PLATE

099-0008
ITEM 84
DETAIL 29



ELEVATION


(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.




SPAN 5 @ L17W

099-0008
ITEM 84
DETAIL 30



ELEVATION


(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION


READINGS EQ. SP.

SP. 5
 S9 @ FB. 16' PAN. 17'




099-0008
 ITEM 86
 DETAIL 31



ELEVATION
 (Looking East)



SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.

SPAN 5 @ L16'E

L16'E-U16'E

099-0008
ITEM 88
DETAIL 32

C18 x 42.7#

d = 18.0



b_f = 3.95

t_w = 0.45




15" x 3/8"

PLATES TOP & BOT.

w/6" x 12"L HOLES




SEC. A-A

-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.




SPAN 5 @ L15'W

099-0008
ITEM 90
DETAIL 33




ELEVATION

(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION




SPAN 5 @ L15'W

099-0008
ITEM 91
DETAIL 34




ELEVATION

(Looking East)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

SPAN 5 @ L15'E

099-0008
ITEM 92
DETAIL 35



ELEVATION

(Looking West)



- HOLE



- SECTION LOSS






- FULL SECTION



READINGS EQ. SP.

SPAN 5 @ L14'E


099-0008
ITEM 94
DETAIL 36

-  - HOLE
 -  - SECTION LOSS
 -  - FULL SECTION
- READINGS EQ. SP.

C18 x 42.7#
 $d = 18.0$
 $b_f = 3.95$
 $t_w = 0.45$
15" x $\frac{3}{8}$ "
PLATES TOP & BOT.
w/6" x 12" L HOLES





SEC. B-B






SEC. A-A

SP. 5
S1 @ FB. 13' PAN. 14'

099-0008
ITEM 96
DETAIL 37




SEC. A-A


-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

SP. 5
S9 PAN. 12'




099-0008
ITEM 107
DETAIL 38



ELEVATION
(Looking East)




SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.




SPAN 5 @ L12'W


099-0008
ITEM 108
DETAIL 39



ELEVATION

(Looking East)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION



ELEVATION

(Looking West)



- SECTION LOSS




- FULL SECTION


READINGS EQ. SP.

SP. 6
S1, MIDSPAN, PAN. 8'

099-0008
ITEM 120
DETAIL 41



ELEVATION
(Looking East)




 - SECTION LOSS

 - FULL SECTION

READINGS EQ. SP.

SPAN 6 @ L4'W

099-0008
ITEM 124
DETAIL 42



- HOLE




- SECTION LOSS




- FULL SECTION

SP. 6
S7 PAN. 4'

099-0008
ITEM 126
DETAIL 43




ELEVATION
(LOOKING EAST)






- HOLE
 - SECTION LOSS
 - FULL SECTION
- READINGS EQ. SP.

SPAN 6 @ L2'W

099-0008
ITEM 130
DETAIL 44



ELEVATION
(Looking West)


-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.




SPAN 5 L13E-L14E @ L14E


099-0008
ITEM 72
DETAIL 45

C18 x 42.7#
d = 18.0
bf = 3.95
tw = 0.45
tf = 0.625
15" x 3/8"
PLATES TOP & BOT.
w/6" x 12"L HOLES



ELEVATION
(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION





SEC. A-A



READINGS EQ. SP.

SPANSB. ⑤ L1'E
 FB. 17

099-0008
 ITEM 85
 DETAIL 46

⊕ W. TRUSS → A



-  - SECTION LOSS
-  - FULL SECTION


READINGS EQ. SP.

SP. 5
S7 PAN. 10


099-0008
ITEM 140
DETAIL 47

☉ FB 9




☉ FB 10



ELEVATION
(LOOKING EAST)




SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION READINGS EQ. SP.


SP. 4
S1 PAN. 8

099-0008
ITEM 53
DETAIL 48

☉ FB. 8



A ← ELEVATION
(Looking West)



SEC. A-A


 - SECTION LOSS

 - FULL SECTION

READINGS EQ. SP.




SPAN 4 @ L2E
IS GUSSET PLATE

099-0008
ITEM 138
DETAIL 49



ELEVATION


(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION


READINGS EQ. SP.

SP. 7
GIR. 3




099-0008
ITEM 151
DETAIL 50



ELEVATION
(Looking North)




SEC. A-A

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.

SPAN 6 @ LO'E




099-0008
ITEM 156
DETAIL 51




C18 x 42.7#
 $d = 18.0$
 $\phi = 3.95$
 $t = 0.45$
 15" x $\frac{3}{8}$ "
 PLATES TOP & BOT.
 w/6" x 12" L HOLES

ELEVATION

(Looking West)

-  - HOLE
-  - SECTION LOSS
-  - FULL SECTION

READINGS EQ. SP.



SEC. A-A



PHOTO 1

Span 3 looking South



PHOTO 2

Span 5 looking South



PHOTO 3

Span 6 looking South



PHOTO 4

Span 6 looking North



PHOTO 5 Span 3 looking North



PHOTO 6 Span 7 looking South



PHOTO 7

Span 5 looking North



PHOTO 8

Span 4 looking South



PHOTO 11

Span 3 looking Southeast



PHOTO 12

Span 5 looking Southeast



PHOTO 13



PHOTO 14 Span 6 looking Southeast




PHOTO 15



PHOTO 16



PHOTO 17



PHOTO 18



PHOTO 19



PHOTO 20



PHOTO 21



PHOTO 22



PHOTO 23



PHOTO 24



PHOTO 25



PHOTO 26



PHOTO 27



PHOTO 28



PHOTO 29



PHOTO 30



PHOTO 31



PHOTO 32



PHOTO 33



PHOTO 34



PHOTO 35



PHOTO 36



PHOTO 37



PHOTO 38



PHOTO 39



PHOTO 40



PHOTO 41



PHOTO 42



PHOTO 43



PHOTO 44



PHOTO 45



PHOTO 46



PHOTO 47



PHOTO 48



PHOTO 49



PHOTO 50



PHOTO 51



PHOTO 52



PHOTO 53



PHOTO 54



PHOTO 55



PHOTO 56



PHOTO 57



PHOTO 58



PHOTO 59



PHOTO 60



PHOTO 61



PHOTO 62



PHOTO 63




PHOTO 64



PHOTO 65



PHOTO 66



PHOTO 67



PHOTO 68



PHOTO 69



PHOTO 70



PHOTO 71



PHOTO 72



PHOTO 73



PHOTO 74



PHOTO 75



PHOTO 76



PHOTO 77



PHOTO 78



PHOTO 79



PHOTO 80



PHOTO 81



PHOTO 82



PHOTO 83




PHOTO 84



PHOTO 85



PHOTO 86



PHOTO 87



PHOTO 88



PHOTO 89



PHOTO 90



PHOTO 91



PHOTO 92



PHOTO 93



PHOTO 94



PHOTO 95



PHOTO 96



PHOTO 97



PHOTO 98



PHOTO 99



PHOTO 100



PHOTO 101



PHOTO 102



PHOTO 103



PHOTO 104



PHOTO 105



PHOTO 106



PHOTO 107



PHOTO 108



PHOTO 109



PHOTO 110



PHOTO 111



PHOTO 112



PHOTO 113



PHOTO 114



PHOTO 115



PHOTO 116



PHOTO 117



PHOTO 118



PHOTO 119



PHOTO 120



PHOTO 121



PHOTO 122



PHOTO 123



PHOTO 124



PHOTO 125



PHOTO 126



PHOTO 127



PHOTO 128



PHOTO 129



PHOTO 130



PHOTO 131



PHOTO 132



PHOTO 133



PHOTO 134



PHOTO 135



PHOTO 136



PHOTO 137



PHOTO 138



PHOTO 139



PHOTO 140



PHOTO 141



PHOTO 142



PHOTO 143



PHOTO 144



PHOTO 145



PHOTO 146



PHOTO 147



PHOTO 148



PHOTO 149



PHOTO 150



PHOTO 151



PHOTO 152



PHOTO 153



PHOTO 154



PHOTO 155



PHOTO 156



PHOTO 157



PHOTO 158



PHOTO 159



PHOTO 160



PHOTO 161



PHOTO 162



PHOTO 163 @Girder 1



PHOTO 164 @ Girder 6



PHOTO 165



PHOTO 166



PHOTO 167

Structure number: 099-0008

Date: 08/07/17

Date: TDB


By: CSE, JDD

By: 8/5/2019


Location	Reading	Tempature	Joint Type	Location	Location	Reading	Tempature	Joint Type	Location
North Abutment	2 ½"	73°	SSJ	W	North Abutment	2"	69°	SSJ	W
Pier 3	5 ¾"	73°	MJ	W	Pier 3	6"	69°	MJ	W
Panel Point 13	6"	75°	MJ	W	Panel Point 13	6"	69°	MJ	W
Panel Point 13'	2 ¼"	75°	SJS	W	Panel Point 13'	2 ½"	69°	SJS	W
Pier 6	1 ¾"	75°	SSJ	W	Pier 6	1 5/8"	69°	SSJ	W
South Abutment	1 ¾"	74°	SSJ	W	South Abutment	1 5/8"	69°	SSJ	W
All readings taken 1' from parapet, Curb or Guard Rail					all reading taken at centerline of lane 2				

Structure number: 099-0008


Date: 08/05/13					Date: 8/10/15				
By: SMS					By: TDB				
Location	Reading	Tempature	Joint Type	Location	Location	Reading	Tempature	Joint Type	Location
North Abutment	North /A	80°	North /A	W	North Abutment	2"	74°	SSJ	W
Pier 3	5 5/8"	80°	MJ	W	Pier 3	5 1/4"	74°	MJ	W
Panel Point 13	5 3/4"	80°	MJ	W	Panel Point 13	4 3/4"	74°	MJ	W
Panel Point 13'	2 1/4"	80°	SJS	W	Panel Point 13'	1 3/4"	74°	SJS	W
Pier 6	1 5/8"	80°	SSJ	W	Pier 6	1"	74°	SSJ	W
South Abutment	North /A	80°	North /A	W	South Abutment	1 1/2"	74°	SSJ	W
JOINTS at Abutments REMOVED for REPLACEMENT									
BEFORE INSPECTION									
All readings taken 1' from parapet, Curb or Guard Rail					all reading taken at centerline of lane 2				




FINGER PLATE (FP)




PREFORMED JOINT SEAL (PJS)




NEOPRENE JOINT (NJ)




SILICONE JOINT W/ STEEL R (SJS)




MODULAR JOINT (MJ)



SILICONE JOINT W/ CONCRETE R (CSJ)



STRIP SEAL JOINT (SSJ)



SLIDING STEEL JOINT (SSJ)