



<u>DETAIL 9</u> <u>TRUSS HANGER/POST WEB REPAIR</u>

NOTES:

- 1. See Sheets S-8 to S-14 of 35 for locations of proposed repair details and notes.
- 2. All structural steel plates and shapes used in proposed repair details shall be AASHTO M270 Gr 36 (ASTM A36).
- 3. All fasteners shall be $^{7}{8}$ " dia. AASHTO M164 (ASTM A325) high strength bolts in $^{15}{16}$ " dia. standard size holes.
- 4. Contact surfaces at bolted parts shall have Class B coating as specified in AASHTO Standard Specifications for Highway Bridges.
- Field drilling of existing members is required. The drilling cost shall be included with "Structural Steel Repair".
- 6. The repair plate and angle lengths shown are anticipated based on the latest field pates. Longer renair plates, angles may be required based upon field cond.
- field notes. Longer repair plates, angles may be required based upon field conditions. 7. $^{15}_{16}$ " ϕ standard size holes in the truss member are to be field drilled using the repair
- 7. 6 ₁₆" ϕ standard size holes in the truss member are to be field drilled using the repair plates and shapes as a template unless otherwise noted.

	DESIGNED - MEA	REVISED -
USER NAME = lkalita	DRAWN - LK	REVISED -
PLOT SCALE = 1:1	CHECKED - MRI	REVISED -
PLOT DATE = Ø8-FEB-2011	DATE - 2/8/2011	REVISED -



STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

STEEL REPAIR DETAILS 2
EASTBOUND FAI-80 OVER DES PLAINES RIVER
STRUCTURE NO. 099-0056

SHEET NO. S-16 OF 35 SHEETS