

SILICONE JOINT SEAL TREATMENT AT PARAPET

DESIGNED


CHECKED

CHECKED -


JJJ

AAY

AAY



SILICONE JOINT SEALER DETAIL



SCARIFICATION & OVERLAY DETAIL AT PARAPET

Notes:

- 1. Deck and approach slab repair areas are estimated based on an infrared thermographic deck survey (ITDS) report prepared by AECOM and visual inspection conducted in June of 2009. Actual repair areas and locations shall be determined by the Engineer and shown on As-Built plans.
- 2. Protective Shield required for full-depth repairs shall be installed according to Article 501.03 of the Standard Specifications. For limits of Protective Shield, see General Plan and Elevation.
- 3. Deck drains (downspouts, floor drains and scuppers) shall be cleaned with the bridge deck prior to application of the Concrete Sealer. Cost of cleaning the deck drains is included in Concrete Sealer.

BRIDGE DECK AND APPROACH SLAB REPAIRS STRUCTURE NO. 022-0092

benesch Engineers · Surveyors · Planners 205 North Michigan Avenue, Suite 2400 Chicago, Illinois 60601 312-565-0450 Job No. 10050

SHEET 10 SH

		_						
NO. 5	F.A.I. RTE.	SECTION				COUNTY	TOTAL SHEET	SHEET S NO.
	290 355	22(1, 1-1, 2&3)RS-7				DUPAGE	546	370
HEETS					C	ONTRACT	NO. 6	50G51
	FED. RC	DAD DIST. NO.	ILLINOIS	FED.	AID F	PROJECT		