


±9.82 m



## Note:

The quantities shown are for estimating purposes only. The actual area to be repaired will be determined by the Engineer at the time of construction. Actual repair locations shall be shown on the "As Built" plans.

## **LEGEND**

- Polymer Mi

Polymer Modified Portland Cement Mortar

- Structural Repair of Concrete (Depth Equal to or Less than 125mm)

m → Epoxy Crack Injection

m - Meter

sq. m. - Square Meter

## BILL OF MATERIAL - BOX CULVERT NO. 8

	Item	Unit	Total	
MX033694	Structural Repair of Concrete (Depth Equal to or Less than 125mm)	sq. m.	0.6	
M5900200	Epoxy Crack Injection	m	3.6	
MX032196	Polymer Modified Portland Cement Mortar	sq. m.	14.2	

Quantity increased by 20% to account for deterioration since field inspection.

SHEET S6 OF 19

REVISIONS									
NAME	DATE	ILLINOIS DEPARTMENT OF TRANSPORTATION							
		BOX CULVERT EXTENSIONS							
		CONCRETE REPAIR DETAILS							
		вох	CULV	. NO.	8,	STA.	5+7	50.192	
		SCALE	NONE			DRAWN	BY	MLB	
		DATE	DECEMBE	R 10, 20	06	CHECKE	D BY	MTH	

PLOT DATE = 3/20/2008