




SUGGESTED BEAM STRAIGHTENING METHODS

Straightening force shall be maintained on all lood transfer blocking during beam straightening.









SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct flange rotation.)



GRINDING DETAIL

Grind existing nicks, gouges and shallow cracks in the damaged beams as detailed. Ground surfaces shall be inspected for cracks using magnetic particle testing prior to initiating any beam straightening operations. Any cracks that cannot be removed by grinding approximately $\frac{1}{4}$ " deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. Ground surfaces shall be spot cleaned and painted with an aluminum epoxy mastic primer followed by a finish coat to match the color of the existing beam. Cost of grinding, testing and spot painting included with Beam Straightening,




SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct localized vertical flange deformations.)

* Edge of plate shall line up with edge of deformation.

Note

Braces and jack assembly shall be placed on same side of web. Bent bottom flange shall be straightened before starting any horizontal straightening operations.



EXISTING DEFORMATION TO BE STRAIGHTENED

(Looking East)
(Approximate max. deflections)
Deflected length of beam to be
straightened is approximately 4'-0''.

	REP-	<u>l</u> 1-14-2005
- 1	DESTONED	

DESIGNED DAB

CHECKED VP

DRAWN Daliva

CHECKED DAB VP

DATE JANUARY 9, 2013

ACTING ENGINEER OF STRUCTURES

ACTING ENGINEER OF BRIDGES AND STRUCTURES

REVISED

REVISED

REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

REPAIR DETAILS
SN 016-0545

SHEET NO. 2 OF 2 SHEETS