

Core Visual Inspection Report

Core #: 238 Contract #: 66A48
 Date Cored: 3/30/2011 County: LaSalle
 Station or M.M. 90.8 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 5.375" Lane Cored: PL
 Rut Measurement: N/A Offset: Center of PL

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 1.5 | X | | X | | | | | | | | |
| B | 2.125 | X | | X | | | | | | | | |
| C | 1.75 | X | | X | | | | | | | | |
| D | | | | | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 239 Contract #: 66A48
 Date Cored: 3/30/2011 County: LaSalle
 Station or M.M. 99.8 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 8.625" Lane Cored: Inside Shoulder
 Rut Measurement: N/A Offset: Center of Shoulder

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 2.125 | X | | X | | | | | | | | |
| B | 1.5 | X | | X | | | | | | | | |
| C | 2.5 | X | | X | | | | | | | | Rubble |
| D | 2.5 | X | | X | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 240 Contract #: 66A48
 Date Cored: 3/29/2011 County: LaSalle
 Station or M.M. 91.3 (Champaign St.) Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 2.625" Lane Cored: DL
 Rut Measurement: N/A Offset: Center of DL

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 1.125 | X | | X | | | | | | | | |
| B | 1.5 | X | | X | | | | | | | | |
| C | | | | | | | | | | | | |
| D | | | | | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 241 Contract #: 66A48
 Date Cored: 3/29/2011 County: LaSalle
 Station or M.M. 91.9 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 5.125" Lane Cored: DL
 Rut Measurement: N/A Offset: Center of DL

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 1.25 | X | | X | | | | | | | | |
| B | 1.875 | X | | X | | | | | | | | |
| C | 0.625 | X | | X | | | | | | | | |
| D | 1.375 | X | | X | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 242 Contract #: 66A48
 Date Cored: 3/29/2011 County: LaSalle
 Station or M.M. 91.9 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 8.625" Lane Cored: Outside Shoulder
 Rut Measurement: N/A Offset: 2' off EQP

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 2.125 | X | | X | | | | | | | | |
| B | 1.875 | X | | X | | | | | | | | |
| C | 2.125 | X | | X | | | | | | | | |
| D | 2.5 | X | | X | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 243 Contract #: 66A48
 Date Cored: 3/29/2011 County: LaSalle
 Station or M.M. 91.9 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 8.5" Lane Cored: Outside Shoulder
 Rut Measurement: N/A Offset: 2' off EOS

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 1.375 | X | | X | | | | | | | | |
| B | 1.625 | X | | X | | | | | | | | |
| C | 1.75 | X | | X | | | | | | | | |
| D | 1.25 | X | | X | | | | | | | | |
| E | 1 | X | | X | | | | | | | | |
| F | 1.5 | X | | X | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 244 Contract #: 66A48
 Date Cored: 3/30/2011 County: LaSalle
 Station or M.M. 92.3 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 5" Lane Cored: PL
 Rut Measurement: N/A Offset: Center of PL

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 3.5 | X | | X | | | | | | | | |
| B | 1.5 | X | | X | | | | | | | | |
| C | | | | | | | | | | | | |
| D | | | | | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

Core Visual Inspection Report

Core #: 245 Contract #: 66A48
 Date Cored: 3/29/2011 County: LaSalle
 Station or M.M. 92.3 Marked Route: FAI 80 (I-80)
 Coring Pattern Used: N/A Direction Cored: EB
 Total Core Thickness: 2.5" Lane Cored: DL
 Rut Measurement: N/A Offset: Center of DL

| Layer | Length | Material | | Condition | | Cracks | | | Voids | | | Comments |
|-------|--------|----------|---------|-----------|------|--------|------|------|-------|------|------|----------|
| | | PCC | Asphalt | Good | Poor | None | Some | Many | None | Some | Many | |
| A | 2.5 | X | | X | | | | | | | | |
| B | | | | | | | | | | | | |
| C | | | | | | | | | | | | |
| D | | | | | | | | | | | | |
| E | | | | | | | | | | | | |
| F | | | | | | | | | | | | |
| G | | | | | | | | | | | | |
| H | | | | | | | | | | | | |
| I | | | | | | | | | | | | |
| J | | | | | | | | | | | | |
| K | | | | | | | | | | | | |
| L | | | | | | | | | | | | |
| M | | | | | | | | | | | | |

Photographs Taken: _____ Logged By: Kyle Videgar
 Pavement surface at core area
 Core prior to testing

Remarks / Observations:

