

Core #36 – Westbound, Mile Marker 103.5 (Outside Shoulder)

1.25" Bit. Surface Course, Major Voids, Poor Condition
 0.75" Bit. Surface Course, Numerous Voids, Fair to Poor Condition
 1.50" Bit. Binder Course, Minor Voids, Good Condition
 1.25" Bit. Binder Course, Moderate Voids, Fair Condition
 1.25" Bit. Binder Course, Minor Voids, Good Condition
 1.75" Bit. Binder Course, Minor Voids, Good Condition

Core #37 – Westbound, Mile Marker 104.5 (Outside Shoulder)

1.50" Bit. Surface Course, Moderate Voids, Fair Condition
 1.00" Bit. Surface Course, Minor Voids, Fair to Good Condition
 2.00" Bit. Binder Course, Moderate Voids, Fair Condition
 2.00" Bit. Binder Course, Moderate Voids, Fair Condition
 3.25" Bit. Binder Course, Moderate Voids, Fair Condition

Core #38 – Westbound Passing Lane (Under Structure #0052)

1.75" Bit. Surface Course, Minor Voids, Fair to Good Condition
 1.50" Bit. Surface Course, Minor Voids, Fair to Good Condition
 8.75" PCC, Minor Voids, No Cracks, Good Condition

Core #39 – Westbound Passing Lane (Under Structure #0114)

1.25" Bit. Surface Course, Minor Voids, Fair to Good Condition
 9.75" PCC, Minor Voids, No Cracks, Good Condition

Core #40 – Westbound Passing Lane (Under Structure #0135)

1.25" Bit. Surface Course, Minor Voids, Good Condition
 1.25" Bit. Surface Course, Minor Voids, Fair to Good Condition
 10.00" PCC, Minor Voids, No Cracks, Good Condition

Core #41 – Westbound Passing Lane (Under Structure #0133)

1.25" Bit. Surface Course, Minor Voids, Fair to Good Condition
 0.75" Bit. Surface Course, Minimal Voids, Good Condition
 9.75" PCC, Minor Voids, Small Hairline Fracture @ 1.5" Below Asphalt, Fair to Good Condition

Core #42 – Westbound Passing Lane (Under Structure #0105)

1.50" Bit. Surface Course, Minimal Voids, Good Condition
 1.75" Bit. Surface Course, Minor Voids, Fair to Good Condition
 9.50" PCC, Minor Voids, No Cracks, Good Condition

Core #43 – Westbound Passing Lane, Mile Marker 99.5

1.50" Bit. Surface Course, Minor Voids, Fair Condition
 1.50" Bit. Surface Course, Minor Voids, Fair Condition
 1.00" Bit. Surface Course, Moderate Voids, Fair Condition
 1.50" Bit. Binder Course, Minor Voids, Fair to Good Condition
 10.25" PCC, Minor Voids, Hairline Fracture @ 1.5" from Bottom, Fair to Good Condition

Core #44 – Westbound Passing Lane (Under Structure #0053)

1.25" Bit. Surface Course, Minor Voids, Fair to Good Condition
 1.25" Bit. Surface Course, Moderate Voids, Fair Condition
 9.25" PCC, Minor Voids, No Cracks, Good Condition

Core #45 – Westbound Passing Lane (Under Structure #0134)

1.00" Bit. Surface Course, Minor Voids, Fair to Good Condition
 1.00" Bit. Surface Course, Partially Broken, Difficult to Evaluate
 9.00" PCC, Minor Voids, No Cracks, Good Condition

Core #46 – Westbound Passing Lane, Mile Marker 101.5

1.00" Bit. Surface Course, Minor Voids, Good Condition
 0.75" Bit. Surface Course, Minor Voids, Fair to Good Condition
 1.25" Bit. Surface Course, Moderate Voids, Fair Condition
 1.50" Bit. Binder Course, Moderate Voids, Fair to Poor Condition
 10.00" PCC, Minor Voids, Moderate Cracks in Various Places, Poor Condition

Core #47 – Westbound Passing Lane, Mile Marker 102.5

1.50" Bit. Surface Course, Moderate Voids, Fair Condition
 1.50" Bit. Surface Course, Moderate Voids, Fair Condition
 1.50" Bit. Binder Course, Moderate Voids, Fair Condition
 9.50" PCC, Minor Voids, No Cracks, Good Condition

Core #48 – Westbound Passing Lane, Mile Marker 104.5

1.75" Bit. Surface Course, Moderate Voids, Fair Condition
 2.00" Bit. Binder Course, Moderate Voids, Fair Condition
 9.50" PCC, Minor Voids, No Cracks, Good Condition

Core #49 – Westbound Passing Lane, Shoulder, Mile Marker 101.5

1.50" Bit. Surface Course, Moderate Voids, Fair Condition
 1.75" Bit. Surface Course, Minor Voids, Fair Condition
 2.00" Bit. Binder Course, Partially Crumbled, Poor Condition

Core #50 – Eastbound Lane, (Under Structure #0133)

2.00" Bit. Surface Course, Minor Voids, Fair to Good Condition
 9.50" PCC, Minor Voids, No Cracks, Good Condition

Core #51 – Eastbound Lane, Mile Marker 98.5

1.25" Bit. Surface Course, Minor Voids, Fair to Good Condition
 2.25" Bit. Binder Course, Minor Voids, Good Condition
 10.00" PCC, Minor Voids, No Cracks, Good Condition

Core #52 – Eastbound Lane, Shoulder, Mile Marker 98.5

1.50" Bit. Surface Course, Many Voids, Fair Condition at Best
 1.25" Bit. Surface Course, Numerous Voids & Crumbled, Good Condition
 1.75" Bit. Binder Course, Moderate Voids, Fair to Poor Condition

Core #53 – Eastbound Lane, Mile Marker 100.5

1.25" Bit. Surface Course, Moderate Voids, Fair to Good Condition
 1.25" Bit. Surface Course, Moderate Voids, Fair to Good Condition
 0.75" Bit. Surface Course, Moderate Voids, Fair to Good Condition
 10.25" PCC, Minor Voids, No Cracks, Good Condition

Core #54 – Eastbound Lane, (Under Structure #0134)

1.75" Bit. Surface Course, Moderate Voids, Fair Condition
 0.75" Bit. Surface Course, Partially Collapsed, Difficult to Evaluate
 9.75" PCC, Minor Voids, No Cracks, Good Condition

FILE NAME =	USER NAME = corcoranlm	DESIGNED -	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	PAVEMENT CORE RESULTS				F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
ca:\pwork\pwork\corcoranlm\0180581\d	66A08-sht-PvmtCores.DGN	DRAWN -	REVISED -		80	(50-5,6&32-1,2)RS-3	*	76	50				
	PLOT SCALE = 50,0000' / IN.	CHECKED -	REVISED -		* LASALLE & GRUNDY				CONTRACT NO. 66A08				
	PLOT DATE = Mar 11, 2010 - 04:20:12 PM	DATE -	REVISED -		SCALE:	SHEET NO.	OF	SHEETS	STA.	TO STA.	ILLINOIS FED. AID PROJECT		