





**CONTROL POINTS**



**CENTERLINE CONTROL POINTS**

LOCATION	SIA	O/S	NORTHING	EASTING
BEGIN IMPROVEMENTS	25+14.28	0.00'	3504.096	4962.177
END IMPROVEMENTS	44+67.21	0.00'	5457.020	4961.083

**BENCHMARKS**

B.M.	SIA	O/S	ELEV.	DESCRIPTION
1	42+57.74	88.17' RT	615.38	PK NAIL IN PARKING LOT (A.K.A. CONTROL POINT #1)
2	33+67.39	43.50' RT	561.40	CHISLED "X" IN SIDEWALK
3	36+76.38	43.27' RT	579.82	CHISLED "X" IN SIDEWALK
4	24+33.66	99.07' LT	510.19	LAG BOLT IN POWER POLE NW QUADRANT OF STERLING AND MAGNOLIA