


EAST FACE ELEVATION (Looking West)



## WEST FACE ELEVATION (Looking East)

## NOTES:

1. Actual quantities of repairs shall be approved by the Engineer.

## LEGEND

— Epoxy Crack Injection

## BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Epoxy Crack Injection	Foot	71

OWMAN, BARRETT & ASSOCIATES INC.  CONSULTING ENGINEERS Chicago, Illinois 312.228.0100 www.bbandainc.com
---

USER NAME =	DESIGNED - TL	REVISED -	
	CHECKED - BAK	REVISED -	
PLOT SCALE =	DRAWN - MTR	REVISED -	
PLOT DATE = 11/08/2012	CHECKED - TL	REVISED -	

PIER 10 REPAIR DETAILS	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
STRUCTURE NO. 016-2437	94	2012-060-BR	соок	285	221
3111001011E NO. 010-2437			CONTRACT	NO. 6	0V61
SHEET NO. S-58 OF S-83 SHEETS		ILLINOIS FED. A	ID PROJECT		