

DETAIL G COLUMN BASE REPAIR

4. Furnishing and operation of epoxy injection shall be paid by "Column Repair".

SN 016-1116, Pier 2 (1 Location)

SUPPORTING REACTIONS & MINIMUM JACKING CAPACITY

S/N	Pier	(LL+I) (k)	Min. Jack. Capacity (k) (Each)
016 - 1116	2	640	480

BILL OF MATERIAL

Extra heavy stainless — hinge ±4". ³16" min

thickness

Item	Unit	Quantity
Structural Steel Repair	Pound	380
Column Repair	Lump Sum	1

assemblies shall be included in "Structural Steel Repair".

DETAIL G-1 ACCESS DOOR REPLACEMENT

6" Gap for

VIEW C-C

sealing gasket

SN 016-1116, Pier 2 (4 Locations)

REVISIONS NAME DATE	ILLINOIS DEPARTMENT	OF TRANSPORTATION
	F.A.I. 94/90 (DAN I DAN RYAN ELE BEARING REPLACEMEN	
	STEEL REPAIRS -	DETAIL G & G-1
	SCALE: NTS DATE: 3/7/2008	DRAWN BY: LAM CHECKED BY: BLU

BOWMAN, BARRETT & ASSOCIATES INC. CONSULTING ENGINEERS
Chicago, Illinois
312.228.0100