



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION




(Looking Southeast)







(Looking Southwest)



BILL OF MATERIAL

Epoxy Crack Injection

Structural Repair of Concrete

Unit Total

Foot

PIER NO. 2 REPAIR

STRUCTURE NO. 084-0078

SOUTHEAST ELEVATION (Looking Northwest) DESIGNED JML

CHECKED MSW DRAWN DJM NOTE: CHECKED MGO/MSW

Crack widths are $^{l}_{8}$ " ($^{\pm}_{l6}$ ") unless otherwise noted.

HEET NO.B39	F.A.I. RTE.	SECTION
	7:2	(84-3HB-5)BR
42 SHEETS	SN 084-0078	

TOTAL SHEET NO. COUNTY 8.4 SANGAMON CONTRACT NO. 72C70 FED. ROAD DIST. NO. 6 | ILLINOIS | FED. AID | PROJECT

08/09/10