



MEDIAN JOINT REPLACEMENT

DECK PLAN

Notes:
 Part of the underside deck is obstructed from view. Additional damage to the underside deck may exist. Contractor to field verify amount of damage and repair what is needed. Contractor to confirm all related quantities.

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Protective Shield	Sq. Yd.	34
Joint or Crack Routing (PC Concrete Pavement and Shoulder)	Ft.	266.0
Joint or Crack Filling	Pound	2200

BENTON & ASSOCIATES, INC.

FILE NAME = P:\10e2166-2\Design\Plans\082-0166	USER NAME =	DESIGNED - MBH	REVISED -
0820166-76022-004-Deck.dgn	PLOT SCALE =	CHECKED - SJH	REVISED -
	PLOT DATE =	DRAWN - MBH	REVISED -
		CHECKED - SJH	REVISED -

**STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION**

**DECK REPAIRS
 STRUCTURE NO. 082-0166**

SHEET NO. 5 OF 11 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
64	82-3HB-1	ST. CLAIR	208	191
CONTRACT NO. 76022				
FED. ROAD DIST. NO. 8 ILLINOIS FED. AID PROJECT				