

| Repair Detail No. | 09/16/13 NIBS Inspection Deficiency Item No. | Location | Sheet No. |
|-----------------------------|--|---|-----------|
| Structural Painting | 1 | 5' Either Side of Deck Joints, Main Spans Splash Zone | S88 |
| Drainage System | 368 | Span W, South side Deck Drains | S128 |
| Drainage System | 369 | Bent 1, North Column | S128 |
| Drainage System | 309 | Span 4, 20' from Bent 3 at Girder 1 | S128 |
| Drainage System | - | Span 4, midspan at Girder 4 | S128 |
| Drainage System | 372 | Span 9, South side Deck Drains | S128 |
| Drainage System | - | Span 9, Panel 3 near Stringer 1 | S128 |
| Drainage System | - | Span 9, Panel 6 near Stringer 1 | S128 |
| Drainage System | 144 | Span 9, Panel 7 and Panel 8 near Stringer 1 | S128 |
| Drainage System | - | Span 9, Panel 8 near Stringer 1 and Stringer 7 | S128 |
| Drainage System | 305 | Bent 31 at North Column | S128 |
| Miscellaneous Steel Repairs | 100 | Span W, under Stringer 5 at Bent W | S87 |
| Miscellaneous Steel Repairs | - | Bent W, 6' above base of North Column | S87 |
| Miscellaneous Steel Repairs | 103 | Span X, between Stringer 1 and Stringer 2 at Midspan | S87 |
| Miscellaneous Steel Repairs | 104 | Span X, between Stringer 3 and Stringer 4 at Midspan | S87 |
| Miscellaneous Steel Repairs | 106 | Bent 1 at Stringer 6 | S87 |
| Miscellaneous Steel Repairs | 107 | Bent 1 at Stringer 4 | S87 |
| Miscellaneous Steel Repairs | - | Bent 1, 4' above base of North Column | S87 |
| Miscellaneous Steel Repairs | - | Bent 1, 4' above base of South Column | S87 |
| Miscellaneous Steel Repairs | 108 | Span 2, Stringer 7, 5' from Bent 1, 5' from Bent 2, and at Bent 2 | S87 |
| Miscellaneous Steel Repairs | 109 | Span 2, Stringer 1 at Bent 2 | S87 |
| Miscellaneous Steel Repairs | - | Bent 3, South Column | S87 |
| Miscellaneous Steel Repairs | 66 | Bent 3, North Column | S87 |
| Miscellaneous Steel Repairs | - | Bent 4, North Column | S87 |
| Miscellaneous Steel Repairs | - | Bent 6, North Column | S87 |
| Miscellaneous Steel Repairs | - | Bent 6, South Column | S87 |
| Miscellaneous Steel Repairs | 119 | Bent 7 at Stringer 4 | S87 |
| Miscellaneous Steel Repairs | 371 | Bent 7 at South Column Long. Bracing | S87 |
| Miscellaneous Steel Repairs | 311 | Span 9, Stringer 7, 6' East of Floorbeam 0 | S87 |
| Miscellaneous Steel Repairs | 125 | Span 9, Floorbeam 1 at Stringer 3 | S87 |
| Miscellaneous Steel Repairs | 41 | Span 9, L4N - U4N, 4' and 20' above Deck | S87 |
| Miscellaneous Steel Repairs | - | Span 9, L4S - U4S, 4' above Deck | S87 |
| Miscellaneous Steel Repairs | - | Span 9, L10S - U10S, 4' above Deck | S87 |
| Miscellaneous Steel Repairs | 75 | Span 9/10, M14N - M14S, 20' above Deck | S87 |
| Miscellaneous Steel Repairs | 48 | Span 10, Floorbeam 18 between Stringer 1 and Stringer 2 | S87 |
| Miscellaneous Steel Repairs | - | Span 10, L18S - U18S, 4' and 30' above Deck | S87 |
| Miscellaneous Steel Repairs | 50 | Span 10, L23N - U23N, 4' above Deck | S87 |
| Miscellaneous Steel Repairs | 51 | Span 10, L23N - U23N, 30' above Deck | S87 |
| Miscellaneous Steel Repairs | 177 | Span 10, Floorbeam 24' at Stringer 2 | S87 |
| Miscellaneous Steel Repairs | 21 | Span 10, L23'S - U23'S, 30' above Deck | S87 |

| Repair Detail No. | 09/16/13 NIBS Inspection Deficiency Item No. | Location | Sheet No. |
|-----------------------------|--|---|-----------|
| Miscellaneous Steel Repairs | 181 | Span 10, Floorbeam 23' at Stringer 3 | S87 |
| Miscellaneous Steel Repairs | 182 | Span 10, Floorbeam 23' at Stringer 4 | S87 |
| Miscellaneous Steel Repairs | 183 | Span 10, Floorbeam 23' at Stringer 4 | S87 |
| Miscellaneous Steel Repairs | - | Span 10, L21'N - M21'N, 12' above Deck | S87 |
| Miscellaneous Steel Repairs | 187 | Span 10, Floorbeam 21' at Stringer 2 | S87 |
| Miscellaneous Steel Repairs | - | Span 10, M19'N, outside Gusset Plate | S87 |
| Miscellaneous Steel Repairs | - | Span 10, L18'N - U18'N, 4' and 25' above Deck | S87 |
| Miscellaneous Steel Repairs | 190 | Span 10, Lower Lateral Connection at L15'N | S87 |
| Miscellaneous Steel Repairs | 192 | Span 10/11, L14'N, outside Gusset Plate | S87 |
| Miscellaneous Steel Repairs | - | Span 11, L13'S - M13'S, 4' above Deck | S87 |
| Miscellaneous Steel Repairs | 54 | Span 11, L13'S - M13'S, 40' above Deck | S87 |
| Miscellaneous Steel Repairs | 361 | Span 11, L11'N inside Gusset Plate | S87 |
| Miscellaneous Steel Repairs | 362 | Span 11, L11'S inside Gusset Plate | S87 |
| Miscellaneous Steel Repairs | 200 | Span 11, Stringer 2 at L11' | S87 |
| Miscellaneous Steel Repairs | - | Span 11, L10'N - U10'N, 4' and 30' above Deck | S87 |
| Miscellaneous Steel Repairs | 207 | Span 11, Floorbeam 8' at L8'N | S87 |
| Miscellaneous Steel Repairs | 60 | Span 11, Floorbeam 5', North end | S87 |
| Miscellaneous Steel Repairs | - | Span 11, L4'S - U4'S, 4' above Deck | S87 |
| Miscellaneous Steel Repairs | 61 | Span 11, L4'S - U4'S, 30' above Deck | S87 |
| Miscellaneous Steel Repairs | 214 | Span 11, L4'N - U4'N, at L4'N | S87 |
| Miscellaneous Steel Repairs | 220 | Span 11, Floorbeam 4' at Stringer 7 | S87 |
| Miscellaneous Steel Repairs | 221 | Span 11, L4'S - U4'S, at L4'S | S87 |
| Miscellaneous Steel Repairs | 62 | Span 11, Floorbeam 3' at North end | S87 |
| Miscellaneous Steel Repairs | 247 | Span 12, U0'S - U1'S at U0'S | S87 |
| Miscellaneous Steel Repairs | 339 | Span 13, U3N - L4N at 5' from U3N | S87 |
| Miscellaneous Steel Repairs | 341 | Span 13, Floorbeam 2' at South end | S87 |
| Miscellaneous Steel Repairs | 32 | Span 21, Stringer 1 at West Splice | S87 |
| Miscellaneous Steel Repairs | 33 | Bent 22 Tower Bracing | S87 |
| Miscellaneous Steel Repairs | 284 | Bent 22 at Stringer 2 | S87 |
| Miscellaneous Steel Repairs | 289 | Bent 23 Cap at South end | S87 |
| Miscellaneous Steel Repairs | 367 | Span 23, Stringer 1 at Bent 23 | S87 |
| Miscellaneous Steel Repairs | 346 | Span 27, Stringer 7 at Midspan | S87 |
| Miscellaneous Steel Repairs | 348 | Span 30, Stringer 6 at Bent 30 | S87 |
| Concrete Median Repair | 349 | Span X, 12' East of Bent W | S87 |
| Concrete Median Repair | - | Span Y, 12' West of Bent Y | S87 |
| Concrete Median Repair | - | Span 7, at Bent 7 | S87 |
| Concrete Median Repair | - | Span 8, 24' West of Pier 8 | S87 |
| Concrete Median Repair | - | Span 10, at Panel 22 | S87 |
| Decorative Lighting | 5 | Spans 9 - 13 | S12 |

Note:
If repair details encompass multiple sheets,
the first sheet number has been referenced.



| | | |
|------------------------|----------------|---------|
| USER NAME = | DESIGNED - CDB | REVISED |
| | CHECKED - ZJB | REVISED |
| PLOT SCALE = | DRAWN - PRC | REVISED |
| PLOT DATE = 03/20/2014 | CHECKED - JMH | REVISED |

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

2013 NIBS REFERENCE TABLE - 2
S.N. 082-6001 MLK BRIDGE OVER MISSISSIPPI RIVER

SHEET NO. 55 OF 5138 SHEETS

| | | | | |
|--------------------|--------------------|------------------|---------------------------|--------------|
| F.A.P. RTE. 799 | SECTION 1BR, ORS-2 | COUNTY ST. CLAIR | TOTAL SHEETS 156 | SHEET NO. 23 |
| CONTRACT NO. 76B03 | | | ILLINOIS FED. AID PROJECT | |