
STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION




SYMBOL.	ITEM	UNIT	QUANTITY
	Deck Slab Repair (Partial)	Sq.· Yd.	468.2 [▲]
	Deck Slab Repair (Full Depth - Type I)	Sq. Yd.	62.4
	Deck Slab Repair (Full Depth - Type II)	Sq. Yd.	87.3
	Cleaning & Painting Exposed Rebar (Special)	Sq. Ft.	61
	Approach Slab Repair (Partial Depth)	Sq. Yd.	5:9
	Protective Shield	Sq. Yd.	2,420
	Bridge Deck Hydro- Scarification, 2 ¹ ₄ "	Sq. Yd.	2,164
	Bridge Deck Latex Concrete Overlay, 21/4"	Sq. Yd.	2,164
	Protective Coat	Sq. Yd.	2,210
	Bridge Deck Grooving	Sq. Yd.	2,098

▲ For information only to assist the Contractor in bidding. See Special Provision for "Bridge Deck Latex Concrete Overlay".

	MFB
-	KWS
-	RMG
-	KWS

PLANExist. Floor Drain



CONCRETE OVERLAY AT FLOOR DRAIN

SCARIFICATION & OVERLAY

DETAIL AT PARAPET

Remove exist.

2" overlav

into deck

benesch Engineers · Surveyors · Planners 205 North Michigan Avenue, Suite 2400 Chicago, Illinois 60901 312-565-0480 Job No. 10050

alfred benesch & company

** Contractor shall increase scarification thickness or

Exist. overlay removal

reduce overlay thickness as directed by the Engineer to ensure this dimension is never less than O".

New 2¼" Latex — Concrete overlay

Notes:

- 1. Deck and approach slab repair areas are estimated based on visual inspection completed in June 2009. Actual repair areas and locations shall be determined by the Engineer and shown on As-Built plans.
- 2. Protective Shield, required for deck slab and/or parapet repairs, shall be installed according to Article 501.03 of the Standard Specifications. For limits of Protective Shield, see General Plan and Elevation sheet.
- 3. Deck drains (downspouts, floor drains, and scuppers) shall be cleaned prior to placement of the Latex Concrete Overlay. Cost of cleaning the deck drains is included in Bridge Deck Hydro-Scarification, $2\frac{1}{4}$ ".
- 4. The Engineer shall determine the type and quantity of Class A patching and the quantity of Mixture for Cracks, Joints and Flangeways. Estimated quantities are included in the overall Summary of Quantities in
- 5. Gaps caused by distress around floor drains shall be filled with epoxy as specified in the Special Provision "Epoxy Injection". Cost included with Bridge Deck Latex Concrete Overlay, 214".

BRIDGE DECK AND APPROACH SLAB REPAIRS STRUCTURE NO. 022-0096

TOTAL SHEE SHEETS NO. F.A.I. RTE. SECTION COUNTY SHEET NO. 4 22(1, 1-1, 2&3)RS-7 546 312 DUPAGE 9 SHEETS CONTRACT NO. 60G51 FED. ROAD DIST. NO. | ILLINOIS FED. AID PROJECT