



PIER 2 - ELEVATION
(Looking West)

PIER 3 - ELEVATION
(Looking West)

PIER 2 - ELEVATION
(Looking East)

PIER 3 - ELEVATION
(Looking East)

LEGEND

- Formed Concrete Repair (Depth < 5")
- Epoxy Crack Sealing
- Hair Line Crack

BILL OF MATERIAL

| ITEM | UNIT | TOTAL |
|-------------------------------------|-------|-------|
| Epoxy Crack Sealing | FOOT | 32 |
| Formed Concrete Repair (Depth < 5") | SQ FT | 889 |

TYLIN INTERNATIONAL

| REVISIONS | |
|-----------|------|
| NAME | DATE |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

ILLINOIS DEPARTMENT OF TRANSPORTATION
F.A.I. 94 (DAN RYAN EXPRESSWAY)
SUBSTRUCTURE REPAIR FOR BELT RAILWAY EXISTING PIER 2 & PIER 3

S.N. 016-0143 DESIGNED BY: MAF, DJR
SCALE: N.T.S. DRAWN BY: MAF, DJR
DATE: MARCH 1, 2006 CHECKED BY: MI