COBE-049925 HERISTERED PROFESSIONAL ENCINEER OF Nobel Chatrane June 14, 2012 Gyp 11/2013

Prepared for:

Illinois Department of Transportation, District 2 819 Depot Avenue Dixon, Illinois 61021

Structure Designer:

Modjeski and Masters, Inc. #4 Sunset Hills Professional Center Edwardsville, Illinois 62088 (618) 659-9102

Prepared By:

Hanson Professional Services Inc. 1525 South Sixth Street Springfield, Illinois 62703 (217) 788-2450

Structure Geotechnical Report

F.A.I. Route 74 Section 81-1HVB Rock Island County Job No. P-92-032-01 Contract No. 64C08 PTB No. N/A Retaining Wall IL-RW16 Structure Number 081-6018

September 2011 / Revised June 2012



Table of Contents

| 1. Project Description | 3 |
|---|----|
| 2. Location | |
| 3. Proposed Structure | |
| 4. Site Investigation | |
| 5. Laboratory Investigation | |
| 6. Subsurface Profile | |
| 7. Geotechnical Evaluations | 6 |
| 8. Design Recommendations | 7 |
| 9. Construction Considerations | 8 |
| References | 10 |
| Appendix | 11 |
| Tables | |
| Table 6.1. Groundwater Elevations | 5 |
| Table 8.1. Estimated Bottom of Unsuitable Material | 8 |
| Figures | |
| Figure 8.1. Lateral Limits of Unsuitable Material Removal and Replacement | 7 |

Copyright © 2012 by Hanson Professional Services Inc. All rights reserved. This document is intended solely for the individual or the entity to which it is addressed. The information contained in this document shall not be duplicated, stored electronically, or distributed, in whole or in part, by anyone other than the recipient without the express written permission of Hanson Professional Services Inc., 1525 S. Sixth St., Springfield, IL 62703, (217) 788-2450, www.hanson-inc.com. Unauthorized reproduction or transmission of any part of this document is a violation of federal law. Any concepts, designs and project approaches contained herein are considered proprietary. Any use of these concepts and approaches by others is considered a violation of copyright law.



1. Project Description

This report provides geotechnical data and recommendations for the proposed Retaining Wall IL-RW16, which is part of the Central Section of the I-74 over the Mississippi River Project. The project includes reconstruction of I-74 between 14th Avenue in Moline, Illinois and Lincoln Road in Bettendorf, Iowa. The retaining wall covered by this structure geotechnical report will be a new structure, constructed to retain fill for the proposed Eastbound I-74 roadway.

Nearby project features that have an impact on the design or construction of the proposed retaining wall include the I-74 Mississippi River Bridge, the Ramp RD-H retaining wall (IL-RW01, S.N. 081-6010), the Ramp RD-G retaining wall (IL-RW02, S.N. 081-6011) and the I-74 mainline and ramps. Geotechnical recommendations for the river bridge are presented in a soils design package prepared by Hanson Professional Services Inc. (Hanson) in January 2011. Geotechnical recommendations for Retaining Walls IL-RW01 and IL-RW02 are presented in separate structure geotechnical reports prepared by Hanson. Geotechnical recommendations for the roadways are contained in a soil survey report currently being prepared by Hanson.

This report supersedes the structure geotechnical report prepared by CH2M HILL in September 2009.

2. Location

The proposed Retaining Wall IL-RW16 is located in the north central portion of Rock Island County, within Section 32 of Township 18 North, Range 1 West. The wall is adjacent to and parallel to the right shoulder of Eastbound I-74 and Ramp 6th-C. The wall separates the interstate and Ramp 6th-C on the high side from Ramp RD-G on the low side. The wall begins at I-74 Sta. 25+75.00 and traverses 371 ft. southward to Ramp 6th-C Sta. 322+81.72.

3. Proposed Structure

Prior to the final planning for this structure, the Benesch Team completed a value engineering study for the portion of the project between the south abutment of the river bridge and the north abutment of the Illinois Viaduct. Estimated construction costs, maintenance requirements, local access, and aesthetics were compared for three alternatives. The study concluded that a plug fill, comprised of earth embankment and mechanically stabilized earth (MSE) retaining walls, was the preferred alternative. Meeting minutes summarizing the value engineering study are included in the Appendix.

After the value engineering study was completed, the grading for the plug fill was further refined and the foundation conditions were more thoroughly analyzed. Some of the retaining walls were replaced with earth slopes and the estimated foundation treatment quantities were reduced.

The proposed structure will be a mechanically stabilized earth (MSE) wall, as determined by a previous value engineering study. A wall using precast panels with the minimum reinforced soil mass width is preferred for cost and construction schedule. The wall will have a height, measured from the theoretical top of leveling pad to the finished grade line, between 3.7 and 15.1 ft. With this range of heights a typical MSE wall section would have an equivalent uniform bearing pressure varying from 700 to 3,100 psf along the length of the wall.

The wall is located within the 22 to 25 ft. high approach embankment to the Mississippi River Bridge. The base of the wall will be founded on the embankment, approximately 10 to 15 ft above existing grade. The north end of the wall will terminate in the embankment, while the south end terminates at the west wingwall of the Illinois Viaduct's south abutment. The MSE wall is approximately 15.1 ft. tall at the connection to the bridge wingwall.



Construction of the wall will be governed by a performance specification. The MSE wall supplier will be responsible for the internal stability of the reinforced soil mass. This report provides geotechnical recommendations for external stability and global stability, which are the responsibility of the wall designer.

4. Site Investigation

The field exploration completed for this structure was completed in three phases. The first two phases were completed in November 2005 and September 2007 by another consultant. IDOT provided the data collected from those two phases. The third phase was completed in July 2010 by Hanson. The primary purpose of the third phase was to collect additional soil samples for strength and consolidation testing. A representative from Hanson logged the borings and performed a general site reconnaissance during the third phase.

The alignment for the proposed retaining wall passes through a former foundry site. The area is now mostly now vacant land. Remnants of floor slabs and other evidence of the past industrial use are visible throughout. At the time of the July 2010 site investigation, significant quantities of random material had been dumped in the area. The random material consists of fine to coarse grained soils, construction debris, dead branches, and metal scraps. The topography is generally flat, with the elevation of the natural ground between 566 ft. and 570 ft. Mounds of the random material up to 8 ft. above the surrounding grade were tightly spaced at the north end of the site.

Six borings were drilled in the first two phases and three borings were drilled in the third phase. Locations of the borings were selected to avoid the numerous obstructions currently occupying the site. The maximum spacing between borings was approximately 90 ft. Standard Penetration Test samples were collected at 2.5 ft. to 5.0 ft. intervals in all borings between the ground surface and bedrock. Several Shelby tube samples were collected at representative locations in cohesive strata. A 10 to 26.5 ft. long core sample of the bedrock was collected in Borings ILR0201-S, ILR1603, and VIAIL-104. The boring depths ranged from 13.7 to 40.5 ft.

The boring locations are shown on the Boring Location Plan included in the Appendix. Boring logs are included in the Appendix.

5. Laboratory Investigation

Soil samples from the first and second phase borings were tested by others. Most of the testing consisted of index testing of representative samples. Three organic content tests and a consolidated-undrained triaxial test were completed.

The soil samples obtained from the third phase borings were delivered to Hanson's soils laboratory and subjected to a testing program. Natural moisture content and visual classification tests were competed on all samples. Unconfined compressive strength tests, using a Rimac spring tester, were also completed when possible. Two consolidated undrained triaxial tests, one consolidation tests, and two organic content test were performed on Shelby tube samples. Index testing was completed on five representative samples to help correlate the strength and consolidation testing data with the other borings drilled for the project.

The locations of the index tests, triaxial tests, and consolidation tests are indicated on the subsurface data profile. The results of index tests are shown on the subsurface data profile. Test reports from triaxial and consolidation testing are included in the Appendix.

6. Subsurface Profile

A subsurface data profile has been developed from the boring logs. It is presented in the Appendix for use by the structure designer.



The subsurface profile consists of fill materials overlying natural soil and bedrock strata. The fill was found over the entire wall alignment from the ground surface to depths of 3 to 17 ft. The depth of fill generally increases from the south to the north. Natural soils were encountered below the fill. These soils can be categorized into three distinct strata – weathered till (gumbotil), glacial till, and alluvium. Bedrock was encountered at depths of 7 to 21 ft.

The fill consists of a random mix of sands, gravels, silts, clays, and debris, including, but not limited to brick, dead branches, concrete, lumber, and metal scraps. Many of the samples recovered from the borings north of Sta. 25+75 had a large quantity of rotting wood matter with a consistency similar to mulch. The fill at the south end of the wall had more soil-like characteristics.

Strata of weathered till and glacial till were encountered in most of the borings. These strata were typically composed of medium stiff to stiff sandy clays.

A 1 to 7 ft. thick layer of granular alluvial soils was encountered under the glacial soils at the north and south ends of the site. The gradation and consistency of these soils varied considerably.

Cyclic deposits of sandstone, shale, limestone, and coal were found in the core borings. The shallow bedrock was generally towards the south end of the site.

Groundwater was encountered in all of the borings where measurements were taken. The groundwater elevation measured at first encounter and at the end of boring varied between Elevation 554.3 and Elevation 562.8 as shown in Table 6.1. For comparison, the water level in the Mississippi River, approximately 100 ft to the north of the site, is usually about Elevation 561.0.

Table 6.1 Groundwater Elevations

| | | | * |
|------------|--------------------|---------------------|--------------------|
| Boring No. | During Drilling | At End of Boring | 24-hour Reading |
| ILR0201-S | 562.4 | | - |
| ILR0203 | - | | - |
| ILR1603 | 562.3 | | |
| ILR0205 | 559.9 | - | - |
| RW1503 | 554.3 | - | - |
| RW1504 | 558.0 | - | - |
| RW16-1 | - | 559.1 | - |
| RW16-2 | - | 558.4 | - |
| RW16-3 | - | 562.8 | - |
| | | | |

The Illinois State Geological Survey Directory of Coal Mines does not list any mines in the immediate vicinity of the site.

Although an environmental investigation was beyond the scope of this report, evidence of potential contamination was encountered during the geotechnical investigation. Petroleum odors and construction debris were encountered in the borings.



7. Geotechnical Evaluations

Considering the proposed maximum height of the wall and the existing ground configuration, the most feasible wall type is an MSE wall. Although MSE wall systems are extremely flexible and can tolerate significant total and differential settlements without undue distress, they require good foundation soils to provide acceptable factors of safety against bearing capacity or global stability failures.

The miscellaneous fill, generally found north of Sta. 25+75, is not a suitable subgrade for the retaining wall or the roadway embankment. The poor compaction and heterogeneous nature of this material would result in localized instability and unpredictable settlement, if it used to support any significant load. Settlement could continue for many years after construction due to further decay within the large pockets of organic matter.

In-situ treatment of this material is not feasible. Many of the more common ground improvement techniques are not suited for the conditions found at this site. The construction debris would present a significant obstruction to any of the techniques where a probe or auger is inserted into the ground. Organics and groundwater can be problematic for vibratory and compaction techniques.

Removal and replacement of the unsuitable material is a feasible solution, if the support of the Mississippi River Bridge approach embankment and the three retaining walls are considered. The site has sufficient right-of-way to allow laid back excavation slopes and efficient large-scale earth-moving operations. It is estimated that up to 11,000 cubic yards of unsuitable material must be excavated, removed from the site, and replaced with suitable backfill. The approximately \$500,000 cost to remove the unsuitable material and replace it with granular embankment material is very economical when compared to the substitution of additional bridge spans for the proposed embankment.

The external stability of the retaining wall will be greatly influenced by the strength of the embankment material that supports it. Compacted granular embankment material would provide sufficient support for the proposed wall. A cohesive fill material with an unconfined strength of at least 1.6 tsf would also provide suitable bearing. Soft, but otherwise suitable, native materials have little effect on the allowable bearing capacity of the compacted fill at the wall's footing level. The proposed wall would meet the Standard Specifications for Highway Bridges (AASHTO) requirements for bearing pressure and sliding stability, if it is constructed on a properly compacted structural fill. This will require somewhat more stringent material and compaction provisions than are typically used for highway embankments.

A slope stability analysis of the wall's critical section near Sta. 29+00 was completed to determine the overall stability of the wall. Results of this analysis are included in the Appendix. The computed factor of safety exceeds the minimum value of 1.3 required by AASHTO.

Once the objectionable fill material and excessively soft soils are removed, the remaining native soils are overconsolidated and exhibit fairly low compressibility. The estimated total settlement of the native soils under the weight of the proposed wall and embankment ranges from 0.5 to 5.0 inches. Some of this settlement will occur during embankment construction – prior to placement of the first lift of wall backfill. Settlement of the lower portion of the new roadway embankment is estimated at 0.5 to 1.5 inches under the weight of the proposed wall. The estimated net settlement to be experienced by the wall is 0.5 to 4.5 inches. Primary consolidation of the native soils is estimated to be 90 percent complete after 15 months. Less than 0.5 inches of primary consolidation would remain 9 months after completion of the retaining wall's backfill. This magnitude and duration of settlement is acceptable for construction of an MSE wall.



8. Design Recommendations

Removal and replacement is the recommended treatment option for the unsuitable subgrade soils. Existing soils with significant woody material, large chunks of demolition debris, moisture contents greater than 50 percent, or organic contents greater than 5 percent should be excavated and removed from the area of retaining wall and embankment construction. The lateral limits of the unsuitable material removal should cover the area bounded by the Mississippi River Bridge south abutment, Ramp RD-H, the Illinois Viaduct north abutment, and Ramp RD-G. It is anticipated that the unsuitable material will extend to depths up to 20 feet below the ground surface. Due to the presence of granular layers and the close proximity to the river, dewatering of the excavation would be very difficult. The contractor should be allowed to excavate through groundwater. The excavation should be backfilled with porous granular embankment in accordance with the IDOT Standard Specifications for Road and Bridge Construction (IDOT Standard Specifications).

The miscellaneous fill material is not expected to extend under the footprint of this wall. If this material is encountered, it should be removed within the lateral limits shown in Figure 8.1. Backfill should be with porous granular embankment and embankment as shown in the figure.




Figure 8.1 Lateral Limits of Unsuitable Material Removal and Replacement

The estimated vertical removal limits for the unsuitable material and soft cohesive soils are provided in Table 8.1. An estimated base of removal elevation is provided at each boring drilled in the vicinity. It is believed that the debris found in Borings RW16-1 and ILR0201 does not extend under the wall's footprint. For plan quantities, it may be assumed that no removal of unsuitable material is required for this wall. The actual limits of removal will be determined during construction based on the materials encountered.



| Boring No. | Station | Base of Removal Elevation | Objectionable Material |
|------------|---------|---------------------------------|---------------------------|
| RW16-1 | 25+10 | 553.10 | debris |
| ILR0201-S | 25+40 | 555.39 | debris |
| ILR0203 | 26+30 | - | - |
| RW16-2 | 26+33 | - | - |
| RW1503 | 26+79 | - | - |
| RW16-3 | 27+87 | - | - |
| ILR1603 | 28+33 | - | - |
| RW1504 | 28+83 | - | - |
| VIAIL-104 | 29+66 | - | - |

Table 8.1 Estimated Bottom of Unsuitable Material

It is recommended that the removal, disposal, and replacement of the large volume of miscellaneous fill, generally found north of Sta. 25+75, be treated as a roadway item per Section 202 of the IDOT Standard Specifications. The limits of the miscellaneous fill removal will extend under the I-74 embankment a considerable distance beyond the footprint of this retaining wall.

A conventional precast panel MSE wall is feasible. The theoretical top of leveling pad or base of reinforced soil mass may be located at the minimum embedment required by IDOT (3'-6" below finished grade). Compacted structural fill should be used to raise the grade. The minimum limits of the structural fill should be defined as shown in Figure 8.1. Other fill, outside the limits of the required structural fill and the reinforced soil mass, may be embankment fill in accordance with the IDOT Standard Specifications.

When designing for the external stability of the MSE wall, it should be assumed that the reinforced soil mass will be composed of a granular select backfill and the fill behind the reinforced soil mass will be embankment material as defined by the IDOT Standard Specifications. Both materials should be assumed to have a total unit weight of 125 pcf. The active earth pressure coefficient of the embankment fill could vary greatly depending on the actual material used, but should be assumed to be 0.36 for design.

The structural fill and the underlying soils, when prepared according to the recommendations herein, have an allowable bearing capacity of 3,500 psf. The structural fill, if composed of cohesive soils, has an undrained sliding resistance of 1,600 psf. The drained sliding resistance is 0.53 times the effective vertical stress for cohesive fill subgrade or 0.62 times the effective vertical stress for a compacted granular fill.

The MSE wall should be detailed to accommodate 0 to 5 inches of settlement after the first facing panel is placed. The parapet and anchorage slab details that are shown in the IDOT Bridge Manual will satisfy this requirement.

9. Construction Considerations

The construction of MSE walls are not covered by the IDOT Standard Specifications. Guide Bridge Special Provision No. 38, Mechanically Stabilized Earth Retaining Walls (Revised: April 19, 2012), should be included in the construction documents. This special provision requires that the contractor take responsibility for the final design of portions of the structure.

It should be anticipated that groundwater will influence the excavation of unsuitable material and the backfill with granular material. A dragline or long-reach excavator will be needed to complete the deeper portions of the



excavation. The contractor must stage the work so that the excavated material can be inspected and sorted, as necessary. Compaction of porous granular embankment placed below the water will not be required; however, the material should be carefully placed in a manner to achieve the highest density practicable. Compaction should begin as soon as the backfill has reached a level where it can support compaction equipment.

Some of the excavated unsuitable material has the potential to be classified as special waste due to the presence of petroleum residue and other potentially hazardous substances. Material that is considered special waste must be handled and disposed of in accordance with applicable laws and regulations. Further environmental investigation will be required prior to or during construction.



References

- American Association of State Highway and Transportation Officials (2002). *Standard Specifications for Highway Bridges*, 17th Edition.
- CH2M HILL (2009, September). Structure Geotechnical Report I-74 Mainline Retaining Wall Structure Number 081-6018.

Illinois Department of Transportation (2009). Bridge Manual.


Illinois Department of Transportation (1999). Geotechnical Manual.

- Illinois Department of Transportation (2012). Standard Specifications for Road and Bridge Construction.
- Illinois State Geological Survey, Rock Island County coal data, Retrieved July 30, 2010 from <u>http://www.isgs.illinois.edu/maps-data-pub/coal-maps/counties/rockisland.shtml.</u>
- U.S. Department of Transportation, Federal Highway Administration (1997, August). *Mechanically Stabilized Earth Walls and Reinforced Soil Slopes Design and Construction Guidelines* (Publication No. FHWA-SA-96-071).



Appendix

Boring Location Plan Subsurface Data Profile Boring Logs Soils Laboratory Test Results Summary of Slope Stability Analysis I-74 Illinois Retaining Walls and Bridges Value Engineering Study



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

| RW16-1 Sta. 25+10, 81' RT | | | | | | | |
|---|---|---|--------------------------------------|--------------------------------------|----------------|---|--------------------------------------|
| 570.10 <u>N</u> Qu wX FILL - Dark to very dark brown, moist to wet, soft a loose, silt, fine- to coarse-grained sand and gravel, w degrading plywood, particle board, timber, lumber, bitum materials, metal scraps, cinder blocks, and brick fragm | vith Sta. 130+16, 11' LT minous ments, 566.39 <u>N Qu w</u> | | ILI Sta. 131- 567.93 567.43 | R0203 +05, 13' LT 3 <u>NQU</u> | | Concrete - Surface: 3" of concre. Silty Sand (SM) - dark brown and | |
| 27 8 petroleum odor 50/1" 18 | 565.39 563.39 <u>13</u> 562.4 DD <u>30</u> | Concrete - 7" slab with rebar Fill: Fine to Medium Sand With Silt (SP-SM) - Very dark brown, dry to moist, medium dense, little gravel, fine to medium sands, trace coarse sands [0] Fill: Sandy Lean Clay (CL) - Very dark gray mottled with greenish gray, moist to wet, stiff, finint petroleum odor, trace medium to fine gravel, with sand seams (LL=28 PI=5) | 56 <i>1</i> .93 | 4 4 1.5P | 27.0 | loose, fine to medium grained, low | plasticity |
| 0h 12 1.75P 17 559.10 V 0 | 7 <i>1.8P</i> | [0] Fill: wood matter with fine to coarse sand, strong petroleum odor, saturated, possible old railroad ties | 559.93 | 5 | | Sand Silt and Clay (ML) - Black, n grain size analysis performed Clay (CH) - black, sliabtly moist fu | |
| 559.10 — O O | 558.39 5 40 | Fill: Silty Sand Trace Gravel (SM) - Top 5": Brown, wet, root matter with petroleum odor and root matter throughout Remainder: Silty Sand trace gravel, dark to medium gray, wet, non plastic, medium to fine sands, trace subrounded fine gravels, loose, faint petroleum odor, Encountered WT at 10' bgs | | 8 1.0P | 25.0 23.0 | Clay (CH) - black, slightly moist, f sand, moderate plasticity; Rimac: F NOTE: Sample 4 Atterberg limits; | Pu = 94 lbs (LL=63, PI=46) |
| | 555.39 | sands, trace subrounded fine gravels, loose, faint pétroleum odor, Encountered WT at 10' bgs Sitty Fine to Coarse Sand (SM) - trace gravel, brown, wet, very loose to medium dense, faint petroleum odor, occasional root, possible native soil, non odorous | | 5 0.5P | | Rimac: Pu = 28 lbs brown, very dense, fine to medium | arained. Same as above. |
| 553.10 <u>50/0" 6</u> 551.60 <u>50/0" Gray, fine-grained, LIMESTONE</u> | 553.39 <u>3 11.</u> 50/2" | Sandy Silt With Clay And Gravel (CL) - Top 2", Dark brown followed by vellowish orange and | 55 <i>1.</i> 93 | 37 3 | | brown, very dense, fine to medium sandy gravel in tip, brown, very de angular gravel <1" diameter | |
| Bottom of hole = 18.5 feet | 550.56 | then light gray at bottom 2", wet, non plastic, very angular flat coarse to fine gravels (possible rock fragments), some medium to fine sands with silt and few clay, possible gumbo/residual soil. Driller began set up for rock coring at 0950 | | | | Sandy Gravel (GP) - light gray, we medium angular gravel, fine to coa | rt, very dense, tine to arse sand |
| | RUD = 41% 381.7 tsf | Sandstone - with Limestone and bands of coal towards bottom of sample, light brown with light gray, rough texture at top 32", remainder has smooth texture, medium to fine grained with little coarse grains, slightly weathered to unweathered, medium to strong, top 32"; | | | | Bottom of hole = 18.0 feet | |
| | Rec. = 95% RQD = 67% | sandstone, remainder Limesfoné with coal bands 15.83′ - Horizontal to 15° fractures, rough planar fractures at top 32″ of sample, remainder fractures are irregular and undulated, little hard areenish aray impermeable clay infilling throuahout top 13″ of sample, remainder: | | | | | |
| | RUD = 67% | gumbo/residual soil. Driller began set up for rock coring at 0950 Sandstone - with Limestone and bands of coal towards bottom of sample, light brown with light gray, rough texture at top 32", remainder has smooth texture, medium to fine grained with little coarse grains, slightly weathered to unweathered, medium to strong, top 32"; sandstone, remainder Limestone with coal bands 15.83' - Horizontal to 15° fractures, rough planar fractures at top 32" of sample, remainder fractures are irregular and undulated, little hard greenish gray impermeable clay infilling throughout top 13" of sample, remainder: no infilling, surface stains only, surfaces stained greenish gray at top 16", 16" to 30" no stains, 30" to bottom dark gray and brown coal stains, top 30": no rock wall contact due to crushed rock, remainder tightly healed with coal strands, sound to moderate fractures, very close to moderate discontinuities 23'-86" = top of run, 1/2-1/2-1/4-3/4-3/4 light gray milky water, brown water 2.5' down and 7'-4' dark brown to dark green 23'-31.5" = end run | | | | | |
| | | very close to moderate discontinuities 23'-86" = top of run, 1/2-1/2-1/4-3/4-3/4 light gray milky water, brown water 2.5' down and 7'-4' dark brown to dark green 23'-315" = end run | | | | | |
| | | Medium to fine grained, smooth texture, slightly weathered to unweathered, medium strong 21.42' - 15° to 45° dearee fractures, irregular, undulating, slickensided at 11", 15" 51". | | | | | |
| | 534.97 | Medium to fine grained, smooth texture, slightly weathered to unweathered, medium strong 21.42′ - 15° to 45° degree fractures, irregular, undulating, slickensided at 11″, 15″ 51″, 67″ and 88″ from top, hard impermeable clay infilling 1/8″ to 1/2″ thick that has tightly healed at most fractures except from 45″ to 51″ from top, dark gray surface stains, no infilling and surface stains from 45″ to 51″, from 57″ to bottom thinly bedded throughout, we the state of the infilling and surface states from 45″ to 51″, from 57″ to bottom thinly bedded throughout, we state of the st | | | | | |
| | | stiff to very stiff gray clay infilling that is 1/2" to 1/4" thick at fracture, sound to moderate fractures, close to wide discontinuities, Average 1-1/4 minute per foot for top 5 feet, 10-20-30 (3/4-3/4') | | | | | |
| | | Bottom of hole = 31.42 feet | | | | | |
| | | | | | | | |
| | | | | | | <u>LEGEND</u> Standard Penetration Test N (blows | s/ft) |
| | | | | | | Unconfined Strength (tsf) | |
| | | | | | | Natural Moisture Content (%) Unconsolidated Undrained Triaxial 7 | Test |
| | | | | | | Consolidated Undrained Triaxial Tes | |
| | | | | | | Consolidation Test Organic Content Test | |
| | | | | | ממ | Water Surface Elevation Encounter | red in Boring |
| | | | | 558.10 | o V | DD = during drilling 24h = 24 hours after completio | n |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | SUBSURFACE DAT | |
| | | PROFESSIONAL DESIGN FIRM LICENSE #184-00108 | 84 | | | <u>STRUCTURE NO.</u> | 001-0010 |
| | | C Copyright Hanson Professional Services Inc. 2011 | | | F.A.I RTE. | SECTION | COUNTY TOTAL S SHEETS |
| | | 08h | <i>40120E</i> S | SHEET NO.1 | INTE. | | SHEE IS |



| T NO.1 | F.A.I RTE. | | SECTION | | | | | | CO | UNTY | TOTAL SHEETS | SHEET NO. |
|--------|---------------|-----|---------|----|--|----------|------|----|--------|--------|-----------------|--------------|
| | 74 | | 81-1HVB | | | | | | ROCK | ISLAND | - | |
| HEETS | | | | | | | | | CON | TRACT | NO. 64 | IC08 |
| | FED. R | OAD | DIST. | NO | | ILLINOIS | FED. | AI |) PROJ | IECT | | |

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

| RW1 Sta. 26+3 | | RT | | |
|--------------------------------|----------|-----------|-----------|---|
| 567.40 | <u>N</u> | <u>Qu</u> | <u>w%</u> | |
| 567.15= | 8 | 2.25F | 9 19 | TOPSOIL FILL - Very dark brown, wet, stiff to very stiff, sandy SILT with trace gravel, brick fragments |
| | 5 | 1.25P | 22 | |
| - 561.90 | | | 16 27 | \fbox{R} Dark brown, moist, lean CLAY with silt \fbox{R} (LL=43 PI=24) |
| 558.40 ↓ 556.90- | Oh | 1.10B | 27 24 | C Gray, moist, stiff, CLAY with silt (LL=50 PI=30) |
| | 16 | 0.92B | 28 | Gray, moist, medium stiff, CLAY with very fine-grained sand |
| 553.90- | 50/5 | n | 30 | —/ Brown, wet, very dense, silty, coarse-grained SAND and GRAVEL |
| 552 . 90- 551.30- | 50/1' | ı | 23 | Brown, WEATHERED LIMESTONE |
| 551 . 50- | | | | Bottom of hole = 16.1 feet |

| | | | | Sta. 27+87 | | |
|--------------|--------------------|------------------------------|---|--------------------------------------|----------------------|-----------------|
| | RW1: Sta. 26+79 | 503 2 104' RT | | 569.80- | | <u>w%</u> |
| | 567.80- | <u>N</u> <u>Qu</u> <u>w%</u> | | 568.30 | 50/0" 1.76B | <u>12</u> |
| , sandy | 567.80 | 18 | Fill (GC) - Clayey gravel to clayey sand, trace brick, dark brown, dry to moist, stratified | 567.80- | 30 1.50P | 24 |
| , sandy | | 6 2.3P | Sandy to Silty Clay (CL, CL-ML) - trace to little gravel and silt, trace organics, dark brown to brown, dry to moist, | 563.80 562.80 562.30 562.30 | 01 | |
| | 561.80- | 7 2.5P | very stiff | 562.80 | 1.55B | <u>23</u> 29 |
| | 559.80- | 4 0.5P 30.0 | Sandy Clay (CL) trace to little gravel, dark brown to gray brown, dry to moist, soft to firm, encountered hard material at 6', moved borehole 3' west and started sampling again at 6' (LL=46 PI=21) | | | |
| | | 7 1.5P | | 557.60 | | 26 27 |
| nained sand | DD 554.3⊥√ | 8 1.8P 24 0.5P | Silty Clay (CL-ML) - Silty clay, trace gravel, gray brown, dry to moist to wet, homogeneous, stirf | 556.30⊥ 556.10 | <u>15072 1.25P .</u> | 21 |
| | 553.80 | 42 | Poorly Graded Sand with Silt (SP-SM) little gravel, light gray and brown, wet, homogeneous, dense | | | |
| | | | | | | |
| | 546.80 | 50/5" | | | | |
| | 546.00- | | Bottom of hole = 21.0 feet | | | |
| | | | $\sim O$ | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | XU | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| $, \bigcirc$ | 7 | | | | | |
| | | | | | | |
| | | | | | | |

PROFESSIONAL DESIGN FIRM LICENSE #184-001084



RW16-3 Sta. 27+87, 82′ RT

| <u>Qu</u> | <u>w%</u> | |
|-----------------|----------------|--|
| ' <i>1.76B</i> | 12 | FILL - Dark brown, moist, medium, sandy SILT - CONCRETE |
| 1.50P | 24 23 | FILL - Dark brown, moist, silty SAND and GRAVEL (LL=26 PI=10) |
| 1.55B | 23 29 26 | FILL - Very dark brown, moist, soft, SILT with metal scraps, brick and concrete fragments (LL=44 PI=20) Gray, moist, stiff, CLAY with trace silt (LL=59 PI=28) |
| 1.36B | 23 26 | (LL=25 PI=7) _/ Gray, moist, very stiff, CLAY with trace silt, sand and gravel |
| " 1. 25P | 27 | Gray, WEATHERED LIMESTONE |
| | | Bottom of hole = 13.7 feet |

<u>LEGEND</u>

- N Standard Penetration Test N (blows/ft)
- Qu Unconfined Strength (tsf)
- w% Natural Moisture Content (%)
- 0 Unconsolidated Undrained Triaxial Test
- R Consolidated Undrained Triaxial Test
- С Consolidation Test
- 0 Organic Content Test
- DD Water Surface Elevation Encountered in Boring

 $558.10 \frac{1}{24h} = 24 \text{ hours after completion}$

SUBSURFACE DATA PROFILE STRUCTURE NO. 081-6018

| F.A.I RTE. SECTION COUNTY TOTAL SHEETS SHEET NO. HEETS 74 81-1HVB ROCK ISLAND _ FED. ROAD DIST. NO ILLINOIS FED. AID PROJECT FED. ROAD DIST. NO ILLINOIS FED. AID PROJECT | | | | | | | | | | | | | | |
|--|---------|---------|-------|-------|-----|------|----------|------|----|--------|--------|-------|----|-----|
| HEETS 74 81-1HVB ROCK ISLAND _ CONTRACT NO. 64C08 | T NO. 2 | | | | SI | ECT | ION | | | CO | UNTY | | | |
| | | 74 | | | 8 | 1-11 | ΗVB | | | ROCK | ISLAND | - | | |
| FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT | HEETS | | | | | | | | | CON | TRACT | NO. 6 | 64 | C08 |
| | | FED. RC |) DAC | DIST. | N0. | _ | ILLINOIS | FED. | ΑI |) PROJ | ECT | | | |

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

| | 21603 33. 80' RT | | RW150 Sta. 28+83, | | |
|--|-------------------------------------|---|----------------------|------------------|--|
| 568.27 ₌ 568.02 ⁼ | <u><u>N</u> <u>Qu</u> <u>w%</u></u> | Fill Concrete underlain with 3" concrete, silt and gravel, dark gray to black, dry, | 567.96 | <u>N Qu w%</u> | |
| 500.02 | 0 | hole offset 3 feet west of proposed boring location | 566.96 | | <u>Concrete - 1' of concrete and crushed rock</u> Clayey Sand (SC) - Clayey Sand, few gravel. |
| 565.27 - | 8 | Fill Silty Fine to Coarse Sand With gravel (SM) - Very dark gray, dry, loose, occasional \backslash reddish brick fragments | 564.96 | 10 | Clayey Sand (SC) - Clayey Sand, few gravel, brown, dry to moist, homogeneous. |
| DD 52.27 🔽 | | | 500.00 | 5 0.7P 4 0.2P | Sandy Clay (CL) Sandy Clay, some silf, few brown, dry to moist, homogeneous. Sandy Clay, some silt, trace gravel, black, d homogeneous. |
| | 1.5 23.0 | Possible Fill Sandy Fat Clay (CH) - dark gray to greenish gray, wet, stiff to very stiff, trace gravel, Sample 3: (8 - 10'): Atterberg limits (LL=59, PI=28) test performed | 560.96 558 96 | | Clayey Silt to Silty Clay (MH-CL) - Clayey S. trace gravel, gray brown, dry to moist, stro |
| 557.27 - | 6 2.5P 26.0 | Weathered Sandstone - Brown with gray, wet, coarse to fine sands with, coarse to fine gravels, some silt and clay, dense to very dense, Bottom 2": Sandy Silt, uniform gray, dry, nonplastic, silt with fine sands, possible complete weathered sandstone, Driller reports rough drilling and chatter 12.0' bgs, possible weathered rock Completely weathered sandstone, dry, uniform gray, medium to fine sands with silt Possible top of rock at 13'6" bgs, Sample 4 (11'-13'): grain size analysis and Atterberg limits (LL=25, PI=7) tests performed | 558.96 558.0 VD | D 50/0" | Sand to Shale (ŚC) - Sand to Shale, gray, Water at 10' while drilling |
| 551.21 | 49 26.0 | gray, dry, nonplastic, silt with fine sands, possible complete weathered sandstone, | 556.96 | 50/0" | Shale - Poss. shale |
| | 50/4" | Completely weathered sandstone, dry, uniform gray, medium to fine sands with silt | 553.96 | | Auger refusal at 14'; end of borehole. |
| 552.60- | Rec. = 92% RQD = 51% | Possible top of rock at 13'6" bgs, Sample 4 (11'-13'); grain size analysis and $_{\!$ | | | Bottom of hole = 14.0 feet |
| | | Sandstone - Light brown and light gray, medium to fine grained, trace coarse grains at top 16" of sample, smooth to rough texture, slightly vuggy at top 24" of sample indicate. little water action, slightly weathered, weak to medium to strong, light gray with greenish gray blotches at bottom 15" of sample 15.67' - Slightly to moderately fractured, very close to close discontinuities, horizontal to 30° fractures, varying rough and irregular fracture surfaces, undulated, greenish gray, stiff to very stiff clay infilling that is 1/8" to 1" thick at 80% of fractures surfaces, stained green and gray, possibly due to clay infilling, zones containing clay seam thick enough to prevent back wall contact at 80" and 86", other fractures tightly healed with impermeable infilling and varying discontinuous joints and slightly altered joint walls, Started coring at 11:00 AM. | > | | |
| 542.60- | | Bottom of hole = 25.67 feet | | | |
| | | | 2 | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 1 | <u>LEGEND</u> | | | | |
| | Standard Penetration | Test N (blows/ft) | | | |
| | Inconfined Strength (| | | | |
| | 5 | | | | |
| w% N | Vatural Moisture Conte | ent (%) | | | |

| RW1 Sta, 28+8 | | RT | | | VIAIL Sta. 29+6 | L-104 6,74′ |
|------------------|------------|-----------|-----------|---|--------------------|----------------|
| 567.96- | <u>N</u> | <u>Qu</u> | <u>w%</u> | | 568.20_ | <u>N</u> |
| 566.96- | | | | Concrete - 1' of concrete and crushed rock. | 567.70- | |
| 564.96- | 10 | | | Clayey Sand (SC) - Clayey Sand, few gravel, dark brown and brown, dry to moist, homogeneous. | 565.20- | 2. |
| 564.90- | 5 | 0.7P | | Sandy Clay (CL) Sandy Clay, some silf, few gravel, dark brown, dry to moist, homogeneous. Sandy Clay, some silt, trace gravel, black, dry to moist, | 500.20 | 6 |
| 560.96- | 4 | 0.2P | | homogeneous. | 561.10- | 7 |
| 558.96 | 7 | 1.1P | | Clayey Silt to Silty Clay (MH-CL) - Clayey Silt to Silty Clay, trace gravel, gray brown, dry to moist, stratified. | 559.70 V | |
| 558.0 V | DD 50/0 | n | | Sand to Shale (ŚC) - Sand to Shale, gray, wet, stratified. Water at 10' while drilling | 557.20- | 4 |
| 556.96- | 50/0 | | | Shale - Poss. shale | 557.20- | 50/4 |
| 553.96- | | | | Auger refusal at 14'; end of borehole. | 554.20- | Re |
| | | | | Bottom of hole = 14.0 feet | | Re |

- Standard Penetration Test N (blows/ft) Ν
- Unconfined Strength (tsf) Qu
- Natural Moisture Content (%) w%
- 0 Unconsolidated Undrained Triaxial Test
- RConsolidated Undrained Triaxial Test
- С Consolidation Test
- 0 Organic Content Test
- DD Water Surface Elevation Encountered in Boring 558.10
 - DD = during drilling 24h = 24 hours after completion

PROFESSIONAL DESIGN FIRM LICENSE #184-001084



F

F

F

527.90 527.70

8/24/11

| 4 4′ RT | |
|--------------------------------------|--|
| <u>N Qu w%</u> | |
| 23 | ASPHALT + BASE COURSE - (3" to 6" thick) SILT - black, sandy, and gravel, moist (FILL) |
| 6 1.0P 17.0 | CLAY - reddish brown to greenish brown, silty, medium plastic, medium stiff to soft, moist. |
| <u>7 0.3B 18.9</u> — | SHALE - medium gray, with sand partings, friable, stiff. |
| 4 17.0 | SAND - medium brown, fine to medium, some silt, loose, saturated. - moderately well consolidated in 2" seam at 10' |
|)/4" 18.9 Rec. = 100% | SANDSTONE - moderate to severely weathered. - augered through 11.3' to 14' (LL=31 PI=19) |
| ROD = 51% Rec. = 85% ROD = 21% | SANDSTONE - light to medium gray, with numerous shale partings with fracture at partings, soft to very soft, moderately well cemented, non-distinct bedding at thin to occasionally medium bedded spacing, fractures at partings are horizontal to 10° planar and smooth, fractures in sandstone are planar to slightly irregular and sandy rough. localized high angle to vertical fractures, fresh to slightly |
| Rec. = 73% ROD = 40% | localized high angle to vertical fractures, fresh to slighty weathered. - near-vertical fracture in sandstone at 19.7', sandy rough - thin beds of medium to dark gray shale with numerous sand partings at 20.3'-21.5' |
| Rec. = 98% ROD = 38% | |
| Rec. = 98% RQD = 87% | medium to dark gray shale with numerous sand partings at 30.5'-32.5' occasional shale partings from 32.5' to 35.5' |
| Rec. = 98% RQD = 62% | brownish gray with occasional shale clasts, increasing to numerous clast at 40.0'-40.3', rough horizontal fractures with localized 70° rough fracture at 39.9' |
| | SHALE - medium to dark gray. |
| | Bottom of hole = 40.5 feet |

SUBSURFACE DATA PROFILE STRUCTURE NO. 081-6018

| SHEET NO.3 | F.A.I RTE. | SEC | TION | | CO | UNTY | TOTAL SHEET | SHEET NO. |
|------------|---------------|-------------|----------|---------|--------|--------|----------------|--------------|
| | 74 | 81-1 | HVB | | ROCK | ISLAND | - | |
| 3 SHEETS | | | | | CON | TRACT | NO. 6 | 4C08 |
| | FED. RC | AD DIST. NO | ILLINOIS | FED. AI | D PROJ | ECT | | |

| Illinois Department of Transportation | |
|--|--|
| Division of Highways CH2M HILL | |

SOIL BORING LOG

Page $\underline{1}$ of $\underline{2}$

Date <u>9/19/07</u>

| ROUTE | I-74 | DF | SCR | ΙΡΤΙΟ | Ne N | w I-74 | Bridge Over Mississippi | River - Illinois | OGGED BY | (F 4 | hreu |
|--------------------------|--|--------------|-------------|-------------------|-------------|--------------|--|-----------------------------------|--------------------------|----------------|------------------|
| | I-74 Bridge over Miss | Sissippi | | | | | , approach | | | <u> </u> | |
| SECTION | River | | _ I | _OCA ⁻ | TION _ | <u>(N=56</u> | 5232.456, E=2459065.7 | 32), SEC. 32, TWP , | <u>. 18N, RNG</u> | <u>. 1W, 4</u> | th PM |
| COUNTY | Rock Island DF | RILLING | g me | THO |) | ŀ | HSA, CME 55 | HAMMER TYPE | CME AU | TOMA | TIC |
| STRUCT. Station | NO | | D E P | | U C S | M O I | Surface Water Elev Stream Bed Elev | ft ft | DB EL PO | U C S | M O I |
| Station _ Offset | IO. ILR0201-S | | T H | S | Qu | S T | Groundwater Elev.: First Encounter Upon Completion | ft | | Qu | S T |
| | Surface Elev. 566.39 | ft | (ft) | (/6") | (tsf) | (%) | After Hrs | ft | (ft) (/6") | (tsf) | (%) |
| Concrete 7" slab with | | 565.39 | | - | | | | | | | |
| Fill: Fine t | o Medium Sand With | | | 4 | | | | | | | |
| Very dark l | brown, dry to moist, | | | 8 5 | | | | | | | |
| medium de | ense, little gravel, fine to | 563.39 | | 4 | | | | | _ | | |
| sands | ands, trace coarse | 505.59 | | 2 | | | | | | | |
| Fill: Sand | y Lean Clay(CL) | I | ▼_ | 4 | 1.8 | 30.0 | | | | | |
| | gray mottled with | | | 3 | P | | X | | | | |
| | ray, moist to wet, stiff, eum odor, trace | | 5 | 2 | | | | | -25 | | |
| medium to | fine gravel, with sand | | | - | | | | | | | |
| seams | matter with fine to | | | 2 | | | | | | | |
| | nd, strong petroleum | | | 1 | | | | | | | |
| odor, satur | rated, possible old | | | 2 | | | | | | | |
| railroad tie | S | 558.39 | | 2 | | | | | | | |
| Fill: Silty S | Sand Trace Gravel(SM) | 000.00 | | 2 | | | - | | | | |
| | own, wet, root matter | | | 1 | | 40.0 | | | | | |
| matter thro | eum odor and root | | | 2 | | | | | | | |
| Remainde | r: Silty Sand trace | X | -10 | _1 | | | | | -30 | | |
| gravel, dar | k to medium gray, wet, | | _ | | | | | | _ | | |
| trace subro | c, medium to fine sands, bunded fine gravels, | 555.39 | | 2 | | | | | | | |
| loose, faint | t petroleum odor | | _ | 1 | | 11.0 | End of Boring | | | | |
| | ed WT at 10' bgs | | | 2 | | | | | | | |
| | to Coarse Sand(SM) el, brown, wet, very | 553.39 | | 15 | | | | | | | |
| loose to m | edium dense, faint | | | 30 | | | | | | | |
| | odor, occasional root, | | | 50/2 | | | | | | | |
| | ative soil, non odorous t With Clay And Gravel | | _ | | | | | | | | |
| (CL) | | | -15 | - | | | | | -35 | | |
| Top 2": Da | ark brown followed by | 550.56 | | - | | | | | _ | | |
| | brange and then light tom 2", wet, non plastic, | | | - | | | | | | | |
| very angul | ar flat coarse to fine | | | - | | | | | | | |
| | ossible rock fragments), | | | 1 | | | | | | | |
| | ium to fine sands with v clay, possible | | | 1 | | | | | | | |
| gumbo/res | idual soil Driller began | | |] | | | | | | | |
| to set up fo | or rock coring at 0950 | | | - | | | | | | | |
| | | | | - | | | | | | | |
| | | | -20 | 1 | | | | | -40 | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

| Illinois Department of Transportation ROCK COF | | Page _2 | _ of _2 |
|--|-----------------------------------|-------------------------------|------------------------------|
| Division of Highways CH2M HILL | | Date | 9/19/07 |
| ROUTE I-74 DESCRIPTION Approach | ippi River - Illinois | LOGGED BY _F | . Abreu |
| I-74 Bridge over Mississippi SECTION | 5.732), SEC. 32, TW | P. 18N, RNG. 1V | /, 4 th PM |
| COUNTY Rock Island CORING METHOD Double tube, 10 ft core barrel, N | | E R | S T |
| STRUCT. NO CORING BARREL TYPE & SIZE Station | D C 0 | | RE |
| Core Diameter In BORING NO. ILR0201-R Top of Rock Elev. 550.56 ft | PR | V.M EDE R. | N G T |
| Station Begin Core Elev550.56 ft Offset Ground Surface Elev566.39 ft | н | Y %) (%) (min/ft | H |
| Sandstone | NQ-R1 7 | | , ((3)) |
| with Limestone and bands of coal towards bottom of sample, light brown with light gray rough texture at top 32", remainder has smooth texture, medium to fine grained with | | | |
| little coarse grains, slightly weathered to unweathered, medium to strong, top 32": Sandstone, remainder Limestone with coal bands 15.83' - Horizontal to 15° fractures, | | | |
| rough planar fractures at top 32" of sample, remainder fractures are irregular and undulated, little hard greenish gray impermeable clay infilling throughout top 13" of | | | |
| sample, remainder: no infilling, surface stains only, surfaces stained greenish gray at top 16", 16" to 30" no stains, 30" to bottom dark gray and brown coal stains, top 30": | | | |
| no rock wall contact due to crushed rock, remainder tightly healed with coal strands, sound to moderate fractures, very close to moderate discontinuities 23'-86" = top of | 20 | | |
| run 1/2-1/2-1/4-3/4-3/4 | | | |
| light gray milky water, brown water 2.5' down and 7'-4' dark brown to dark green 23'-31.5" = end of run | NQ-R2 9 | 95 67 | |
| Medium to fine grained, smooth texture, slightly weathered to unweathered, medium strong 21.42' - 15° to 45° degree fractures, irregular, undulating, slickensided at 11", | _ | | |
| 15", 51 ", 67 " and 88" from top, hard impermeable clay infilling $1/8$ " to $1/2$ " thick that has tightly healed at most fractures except from 45" to 51 " from top, dark gray surface | | | |
| stains, no infilling and surface stains from 45" to 51", from 57" to bottom thinly bedded throughout, stiff to very stiff gray clay infilling that is 1/2" to 1/4" thick at fracture, sound | | | |
| to moderate fractures, close to wide discontinuities Average 1-1/4 minute per foot for top 5 feet, | -25 | | |
| 10-20-30 (3/4-3/4') | | | |
| | | | |
| | _ | | |
| | | | |
| | | | |
| | | | |
| | 534.97 | | |
| End of Boring | | | |
| | | | |
| | | | |
| | | | |
| | 35 | | |
| | | | |

Color pictures of the cores _____ Cores will be stored for examination until_____ The "Strength" column represents the uniaxial compressive strength of the core sample (ASTM D-2938)

| Illinois Depa of Transpor | artr tati | ne | nt | | SO | Page <u>1</u> of <u>1</u> |
|---|--------------|------|-------------|-------------|--------------------|---|
| Division of Highways CH2M HILL | lall | | • | | | Date <u>9/18/07</u> Bridge Over Mississippi River - Illinois |
| ROUTEI-74 | DES | SCR | ΙΡΤΙΟΙ | N | W I / I | Approach LOGGED BY KB |
| I-74 Bridge over Missis SECTION River | sippi | _ L | OCA1 | | <u>(N=56</u> | 5145.331, E=2459082.04), SEC. 32, TWP. 18N, RNG. 1W, 4 th PM |
| COUNTY Rock Island DRII | LLING | ME | THOD |) | ŀ | ISA, CME 55 HAMMER TYPE CME AUTOMATIC |
| STRUCT. NO Station | _ | | B L O | U C S | M O I | Surface Water Elev ft Stream Bed Elev ft |
| BORING NO. ILR0203 | _ | | W | 0 | S | Groundwater Elev.: |
| | - | н | S | Qu | Т | First Encounter ft Upon Completion ft |
| Offset Ground Surface Elev. 567.93 | ft | (ft) | (/6") | (tsf) | (%) | Upon Completion ft After Hrs ft |
| Concrete 5 | 67.43 | | | | | |
| Surface: 3" of concrete | - | _ | | | | |
| dark brown and black, slightly | | | | | | |
| moist, very loose, fine to medium grained, low plasticity | - | | 2 | | | |
| g | - | | 2 | | | |
| | | | 2 | | | |
| | - | | 4 | | | |
| | | -5 | 2 | 1.5 | | |
| | - | | 2 | Р | | |
| 5 | 61.93 | | | | | |
| Sand Silt and Clay(ML) Black, moist | | | 0 | | 07.0 | |
| NOTE: Sample 3 grain size | - | | 2 3 | | 27.0 | |
| analysis performed | 59.93 | | 5 | | | |
| Clay (CH) | 33.33 | | 2 | | | |
| black, slightly moist, firm to stiff, trace fine sand, moderate plasticity | - | | 3 | 1.8 | 25.0 | |
| race fine sand, moderate plasticity Rimac: Pu = 94 lbs | | | 3 | Р | | |
| NOTE: Sample 4 Atterberg limits: | X. | -10 | | | | |
| LL=63, PI=46 | | H | 3 | 1.0 | 23.0 | |
| | - | | 5 | P 1.0 | 23.0 | |
| | | | | | | |
| Rimac: Pu = 28 lbs | | | 1 | | | |
| | - | | 2 | 0.5 | | |
| | | | 3 | P | | |
| brown, very dense, fine to medium | - | | 5 | | | |
| grained, Same as above, sandy | | -15 | 15 | | | |
| gravel in tip, brown, very dense, fine to medium angular gravel <1" | - | | 22 | | | |
| diameter 5 | 51.93 | | F0/0" | | | |
| Sandy Gravel (GP) | | | 50/3" | | \mid | |
| light gray, wet, very dense, fine to medium angular gravel, fine to | - | | | | | |
| coarse sand | 49.93 | | | | | |
| End of Boring | | | | | | |
| | - | | | | | |
| | | | | | | |
| | | -20 | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

| Illinois Department of Transportation | |
|--|--|
| Division of Highways CH2M HILL | |

SOIL BORING LOG

Page $\underline{1}$ of $\underline{2}$

Date <u>9/24/07</u>

| | | | Ne | w I-74 | Bridge Over Mississippi | River - Illinois | |
|--|-------------------|-------------------|-------|--------|-------------------------|---------------------------------|--|
| ROUTE I-74 | DESCF | RIPTIO | N | | Approach | L | OGGED BY F. Abreu |
| I-74 Bridge over Mississ | | | | | | | |
| SECTION River | | LOCA ⁻ | ΓΙΟΝ | (N=56 | 4956.216, E=2459158.4 | 8), SEC. 32, TWP. | 18N, RNG. 1W, 4 th PM |
| | | | | | | | |
| COUNTY Rock Island DRIL | LING M | ETHO |)(| ŀ | HSA, CME 55 | HAMMER TYPE | CME AUTOMATIC |
| | | 1 | 1 | | - | | |
| STRUCT. NO | D | В | U | м | Surface Water Elev. | ft | |
| Station | - E | L | С | ο | Stream Bed Elev. | ft | |
| | - P | 0 | S | I | | N | |
| BORING NO. ILR1603 | Т | w | | S | Groundwater Elev.: | | |
| Station | | S | Qu | Т | First Encounter | 562 3 ft 🔻 | |
| Offset | - | | | | Upon Completion | | |
| Ground Surface Elev. 568.27 | ft (ft) | (/6") | (tsf) | (%) | After Hrs | | |
| | | | (101) | () | | n | |
| Fill Concreteunderlain with 3" 56 concrete, silt and gravel, dark gray | 8.02 _ | _ | | | | | |
| to black, dry, hole offset 3 feet | | | | | | | |
| west of proposed boring location | | 13 | | | | | |
| Fill Silty Fine to Coarse Sand | _ | 5 | | | | | |
| With Gravel (SM) | | 3 | | | | | |
| | 5.27 [—] | 3 | | | | | |
| occasional reddish brick fragments | | 2 | | | | | |
| Silty to Clayey Fine Sand(SM, | _ | 1 | 1.0 | 24.0 | | | |
| SC) | | 1 | P | | | | |
| Dark brown with dark gray, moist, | _ | | ' | | | | |
| stiff, possible fill, weak | { | 5 2 | | | | | |
| cementation | _ | _ | | | | | |
| Sample 2: grain size analysis and 56 | 52.27 T | _ | | | | | |
| Atterberg limits (LL=26, PI=10) test performed | _ | | | | | | |
| | | | 1.5 | 23.0 | | | |
| Possible Fill Sandy Fat Clay(CH) dark gray to greenish gray, wet, | | | | | * | | |
| stiff to very stiff, trace gravel | _ | | | | | | |
| Sun to very sun, trace graver | | 2 | | | | | |
| Sample 3 (8'-10'): Atterberg limits | _ | 3 | 2.5 | 26.0 | | | |
| (LL=59, PI=28) test performed | | 3 | P | | | | |
| | - 1 < | 3 | ' | | | | |
| | <u>-1(</u> | | | | | | |
| | _ | _ | | | | | |
| 55 | 57.27 | | | | | | |
| Weathered Sandstone | | 25 | | | | | |
| Brown with gray, wet, coarse to | _ | 33 | | 26.0 | | | |
| fine sands with, coarse to fine gravels, some silt and clay, dense | | 16 | | | | | |
| to very dense, Bottom 2": Sandy | _ | 50/5 | | | | | |
| Silt, uniform gray, dry, nonplastic, | | 50/4 |] | | | | |
| silt with fine sands, possible | _ | 1 | | | | | |
| complete weathered sandstone, | | - | | | | | |
| Driller reports rough drilling and | - | - | | | | | |
| chatter 12.0' bgs, possible | <u>-15</u> | 5 | | | | | |
| weathered rock 55 | <u>52.60</u> – | - | | | | | |
| Completely weathered sandstone, | | 4 | | | | | |
| dry, uniform gray, medium to fine | _ | 4 | | | | | |
| sands with silt Possible top of rock at 13'6" bgs | | | | | | | |
| Sample 4 (11'-13'): grain size | | | | | | | |
| analysis and Atterberg limits | | | | | | | |
| (LL=25, PI=7) tests performed | | | | | | | |
| Borehole continued with rock | _ | 1 | | | | | |
| coring. | | - | | | | | |
| | _ | - | | | | | |
| | -20 |) | 1 | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

| A | Illinois Dep | partment | Page <u>2</u> of _ |
|--|--|--|--------------------------------|
| | Illinois Dep of Transpo Division of Highways CH2M HILL | rtation ROCK CORE LOG | Date 9/24/07 |
| ROUTE | | New I-74 Bridge Over Mississippi River - Illinois DESCRIPTION Approach LOG | |
| | I-74 Bridge over Miss | | |
| | Rock Island CC | DRING METHOD Double tube, 10 ft core barrel, NQ wireline, diamond bit | CORE S |
| Station | | Top of Pook Flow 552.60 ft P R E | R T R Q I E M N D E G |
| Station | | Begin Core Elev. <u>552.60</u> ft T E R H Y | T H |
| Ground Su | irface Elev. 568.27 | ft (ft) (#) (%) | (%) (min/ft) (tsf) |
| sample, smo water action, gray blotches close to clos fracture surfa 1" thick at 80 infilling, zone and 86", othe discontinuou | both to rough texture, sl s slightly weathered, we s at bottom 15" of samp e discontinuities, horizo aces, undulated, green 9% of fractures surfaces as containing clay seam er fractures tightly heal is joints and slightly alte | to fine grained, trace coarse grains at top 16" of lightly vuggy at top 24" of sample indicates little eak to medium to strong, light gray with greenish ple 15.67' - Slightly to moderately fractured, very ontal to 30° fractures, varying rough and irregular ish gray, stiff to very stiff clay infilling that is 1/8" to s, stained green and gray, possibly du to clay ed with impermeable infilling and varying ered joint walls Started coring 11:00 AM. | 51 472.0 |
| End of Borin | g | | |

Color pictures of the cores _____ Cores will be stored for examination until_

The "Strength" column represents the uniaxial compressive strength of the core sample (ASTM D-2938)

| Illinois Depa of Transport | artme tatior | ent 1 | | SC | | g log | Page | e <u>1</u> | of <u>1</u> |
|--|-----------------|-------------|-------------|--------------|--|---------------------------------|----------------|------------------|------------------|
| Division of Highways CH2M HILL | | | | | | 5 | Date | 10/2 | 25/05 |
| ROUTE I-74 | DESCR | IPTIO | Ne N | w I-74 | Bridge Over Mississippi Approach | River - Illinois | OGGED B | Y_L.H | Hunt |
| I-74 Bridge over Mississ SECTIONRiver | sippi I | | | <u>(N=56</u> | 5101.511, E=2459102.0- | 47), SEC. 32, TWP | . 18N, RNG | i . 1W, 4 | th PM |
| COUNTY Rock Island DRIL | LING ME | THOD |) | ŀ | ISA, CME 55 | HAMMER TYPE | CME AU | JTOMA | TIC |
| STRUCT. NO Station | D E P | B L O | U C S | M O I | Surface Water Elev Stream Bed Elev | | DB EL PO | U C S | M O I |
| BORING NO | H | W S | Qu | S T | Groundwater Elev.: First Encounter Upon Completion | | T W H S | Qu | S T |
| Ground Surface Elev. 567.80 | ft (ft) | (/6") | (tsf) | (%) | After Hrs | | (ft) (/6") | (tsf) | (%) |
| Fill (GC) Clayey gravel to clayey sand, trace brick, dark brown, dry to moist, stratified. | | 3 9 9 | | | Auger refusal at 20' End of Boring | 546.80 | | | |
| | | 3 | | | | | | | |

3

3

3

4

3

3 -5

4

4

1

2

2

2

2

3

4

5 3

4

4 6 6

9

15

16

10 -15

9

33 36

3 -20 50/5

T

553.80

561.80

<u>559.</u>80

2.3

Ρ

2.5

Ρ

0.5

P

1.5

Ρ

1.8

Р

0.5

Ρ

30.0

Sandy to Silty Clay (CL, CL-ML)

trace to little gravel and silt, trace

Sandy Clay(CL) trace gravel,

dark brown to gray brown, dry to

moist, soft to firm, encountered

hard material at 6', moved

sampling again at 6'

borehole 3' west and started

Silty Clay (CL-ML) Silty clay,

trace gravel, gray brown, dry to

Poorly Graded Sand with Silt (SP-SM) little gravel, light gray

and brown, wet, homogeneous,

dense

moist to wet, homogeneous, stiff

to moist, very stiff

organics, dark brown to brown, dry

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

-40

<u>1</u> of <u>1</u>

| Illinois Department | |
|----------------------|--|
| of Transportation | |
| Division of Highways | |

SOIL BORING LOG

Page $\underline{1}$ of $\underline{1}$

Date 10/27/05

| ROUTE I-74 DE | SCR | | Ne | w I-74 | Bridge Over Mississippi Approach | River - Illinois | LOGGED BY L. Hunt |
|--|----------------|----------------------------|-------------|---------------|---|----------------------------------|--|
| I-74 Bridge over Mississippi SECTION River | | LOCA | | <u>(N=56</u> | 4902.45, E=2459144.51 | 7), SEC. 32, TWP . | . 18N, RNG. 1W, 4 th PM |
| COUNTY Rock Island DRILLIN | g me | ETHO |) | ŀ | HSA, CME 55 | HAMMER TYPE | CME AUTOMATIC |
| STRUCT. NO Station | P | B L O | U C S | M O I | Surface Water Elev Stream Bed Elev | ft ft | 14 |
| BORING NO. RW1504 Station Offset Ground Surface Elev. 567.96 ft | T H (ft) | | Qu (tsf) | S T (%) | Groundwater Elev.: First Encounter _ Upon Completion _ After Hrs | ft | |
| Concrete 1' of concrete and | | , | (101) | (70) | | n | |
| Clayey Sand(SC) Clayey Sand, few gravel, dark brown and brown, dry to moist, homogeneous. | | 5 5 5 5 | | | | | |
| 564.96 Sandy Clay(CL) Sandy Clay, some silt, few gravel, dark brown, dry to moist, homogeneous. | | 4 3 2 | 0.7 P | | × O | | |
| Sandy Clay, some silt, trace gravel, black, dry to moist, homogeneous. 560.96 | <u>-5</u> | 2 2 2 2 2 2 | 0.2 P | | 2 | | |
| Clayey Silt to Silty Clay(MH - CL) Clayey Silt to Silty Clay, trace gravel, gray brown, dry to moist, stratified. | | 2 3 4 | 1.1 P | | | | |
| Sand to Shale(SC) Sand to Shale, gray, wet, stratified. Water at 10' while drilling | <u>▼-10</u> | 4 2 21 50/0 | | | | | |
| Shale Poss. shale | | 50/0 | | | | | |
| Auger refusal at 14'; end of borehole. 553.96 End of Boring | | | | | | | |
| | | - | | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)



CHANSON SOIL BORING LOG

| | | | | | | | | Date6/29/10 |
|--|--|---------------------------------------|---------------------------------------|----------------------------|------------------------------|---|-------------------|--------------|
| ROUTE | F.A.I. 74 | DESC | RIPTION | ۱ | | I-74 Over Mississippi F | River LC | IGGED BY JMB |
| SECTION | 81-1HVB | | LOCAT | | NE¼ (| of SEC. 32, TWP. 18N, | RNG. 1W, 4th P.M. | |
| COUNTY | Rock Island | | IETHOD | | Hol | low Stem Auger | _ HAMMER TYPE _ | Auto |
| Station BORING NO Station Offset Ground Surfa | 081-6018 RW 16-1 25+10 81' Rt. ace Elev. 570.1 | E F T T ft | D B L O W H S t) (/6") | U C S Qu (tsf) | M O I S T (%) | Surface Water Elev. Stream Bed Elev. Groundwater Elev.: First Encounter Upon Completion After Hrs. | ft ft ⊻ | |
| moist to wet, s fine- to coarse- gravel, with de particle board, bituminous ma | blocks, and brick | 2 | - 6 - 8 - 8 | | 10 | | | |
| | | 4 6 10 <u>\scrime 12</u> | 12 12 15 woh 50/1" | 1.75P | 8 18 17 17 | | | |
| Gray, fine-grain End of Boring | ned, LIMESTONE | 14 16 <u>553.10</u> 551.60 | 8 8 50/0" | | 6 | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)



CHANSON SOIL BORING LOG

| | | | | | | | | | Date | 6/29/10 |
|-----------------------------------|-------------------------------------|----------------------|-----------------------|--------|----------|--------|---|----------------|--------------|---------|
| ROUTE | F.A.I. 74 | DE | SCR | IPTION | ۱ | | I-74 Over Mississippi | River | LOGGED BY | JMB |
| SECTION | 81-1HVB | | _ I | | | NE¼ (| of SEC. 32, TWP. 18N, | RNG. 1W, 4th F | P.M. | |
| | Rock Island C | RILLING | 6 ME | THOD | | Hol | llow Stem Auger | _ HAMMER TYP | PE <u>Au</u> | to |
| STRUCT. NO. Station | 081-6018 | | D E | B L | U C | M O | Surface Water Elev. Stream Bed Elev. | | | |
| BORING NO. | RW 16-2 | | P T | O W | S | I S | | | | |
| Station | 26+33 | | H | S | Qu | T | Groundwater Elev.: | | | |
| Ground Surf | 82' Rt. ace Elev. 567.4 | ft | | | | | First Encounter Upon Completion | ft ft | ∇ | |
| | | n | (ft) | (/6") | (tsf) | (%) | After Hrs. | ft | <u> </u> | |
| TOPSOIL | rk brown, wet, stiff | _/ 567.15 | | - | | | | | | |
| | andy SILT with trace | ; | | 8 | 2.25P | 19 | - | | | |
| gravel, brick fr | agments | - | _ 2 | 5 3 | 2.25 | 19 | | | | |
| | | | | 2 | 1.25P | 22 | | | | |
| | | | 4 | 23 | 1.25F | 22 | | | | |
| | | 561.90 | | | | | | | | |
| | oist, lean CLAY | | 6 | | | | | | | |
| with silt | | | U _ | | | 16 | | | | |
| | | | | | | 27 | | | | |
| | | 40 | | | | | - | | | |
| Grav. moist. st | tiff, CLAY with silt | 559.40 | 8 | | 2.22B | 27 | - | | | |
| ,, , | , | | $\nabla \overline{7}$ | | | 24 | - | | | |
| | | | | | | | - | | | |
| | | X | - 10 | | | | | | | |
| | | 556.90 | | | | | | | | |
| Gray, moist, m with very fine- | nedium stiff, CLAY | | | | 0.000 | 00 | - | | | |
| with very line- | graineu sanu | | - | 5 | 0.92B | 28 | | | | |
| | | | 12— | 9 | | | | | | |
| | | | _ | | | | | | | |
| | | 553.90 | | 1 | | | | | | |
| Brown, wet, ve | ery dense, silty, | | 1/_ | 50/5" | | 30 | | | | |
| coarse-grained GRAVEL | d SAND and | 552.90 | 14 | | | | | | | |
| Brown, WEAT | HERED | | | - | | | | | | |
| LIMESTONE | · · · · · · · · · · · · · · · · · · | | _ | - | | | | | | |
| | | 551.30 | .16 — | 50/1" | <u> </u> | 23 | | | | |
| End of Boring | | | | 30/1 | / | 23 | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)



SOIL BORING LOG

| | | | | | | | Date | 6/29/10 |
|---|------------------------------------|-----------------------|-------------------|-----------------------|---|------------------|-----------|---------|
| ROUTE F.A.I. 74 | | | I | | I-74 Over Mississippi | River I | LOGGED BY | JMB |
| SECTION81-1HVB | | LOCAT | | NE¼ (| of SEC. 32, TWP. 18N, | RNG. 1W, 4th P.M | И. | |
| COUNTY Rock Island DR | ILLING ME | THOD | | Hol | low Stem Auger | _ HAMMER TYPE | Auto |) |
| STRUCT. NO. 081-6018 Station | D P T H ft | B L O W S | U C S Qu | M O I S T | Surface Water Elev. Stream Bed Elev. Groundwater Elev.: First Encounter Upon Completion | ft | 17 | |
| | (ft) | (/6") | (tsf) | (%) | After Hrs. | ft | - | |
| | 568.30 567.80 2- | 5 \50/0"/ | 1.76B | 12 | | | | |
| | | 6 12 18 | 1.50P | 23 | XIO | | | |
| FILL - Very dark brown, moist, soft, SILT with metal scraps, brick and concrete fragments | 563.80 6 ∑ 562.30 | | | C | 0 | | | |
| Gray, moist, stiff, CLAY with trace silt | 8- | 5 | 1.55B | 29 | | | | |
| Gray, moist, very stiff, CLAY with trace silt, sand and gravel | <u>557.60</u> 12 - | 5 7 10 | 1.36B | 23 | | | | |
| - | <u>556.30</u> 556.10 | 50/2" | 1.25P | 27 | | | | |
| | | | | | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

| Division of Highways CH2M HILL | | | | | | | Date 8/28/0 |
|--|---------------|------------------|-------------------|-----------------------|---|-----------------------------------|--|
| CH2M HILL CH2M H | DESCR | IPTION | Ne | w I-74 | Bridge Over Mississippi | River - Illinois | |
| I-74 Bridge over Miss | issippi | | | | | | |
| ECTION River | | LOCAT | | <u>(N=564</u> | 827.741, E=2459192.0 | 7), SEC. 32, TWP. 1 | 8N, RNG. 1W, 4 ^m PN |
| COUNTY Rock Island DR | | THOD | | H | ISA, CME 55 | HAMMER TYPE | CME AUTOMATIC |
| STRUCT. NO. Station 29+40 SORING NO. VIAIL-104 Station | — Н | L O W S | U C S Qu | M O I S T | Surface Water Elev. Stream Bed Elev. Groundwater Elev.: First Encounter Upon Completion | ft ft ⊻ | 17 |
| Ground Surface Elev. 568.20 | | (/6") | (tsf) | (%) | After Hrs | | |
| SPHALT + BASE COURSE - (3" o 6" thick) | 567.70 | | | | | | |
| b 6" thick) SILT - black, sandy, and gravel, noist (FILL) | | 3 11 12 | | | \$ | | |
| | 565.20 | _ | | | | | |
| CLAY - reddish brown to greenish rown, silty, medium plastic, nedium stiff to soft, moist. | | 3 3 3 | 1.0 P | 17.0 | × O | | |
| | | 3 | | | 2 | | |
| SHALE - medium gray, with sand artings, friable, stiff. | <u>561.10</u> | 34 | 0.3 B | 18.9 | | | |
| SAND - medium brown, fine to nedium, some silt, loose, aturated. | 559.70 ¥ | 3 2 2 | | | | | |
| moderately well consolidated in " | 557.20 | | | | | | |
| SANDSTONE - moderate to everely weathered. | | 50/4" | | | | | |
| augered through 11.3' to 14' | 554.20 | - | | | | | |
| Borehole continued with rock oring. | <u>-15</u> | - | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer) The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

| Illinois Department of Transportation ROCK CORE L | ~ | | | Р | age <u>2</u> | of <u>3</u> |
|--|-----------------------|------------------|----------|-------------|------------------|------------------|
| Division of Highways CH2M HILL | | | | D | ate <u>8</u> , | /28/07 |
| ROUTE I-74 DESCRIPTION Approach | r - Illi | inois | LO | GGED | BY | SL |
| I-74 Bridge over Mississippi SECTION River LOCATION _(N=564827.741, E=2459192.07), SE | | | | | | |
| COUNTY Rock Island CORING METHOD NQ Core | | | R E | R | CORE | S T |
| STRUCT. NO. 29+40 Station 29+40 BORING NO. VIAIL-104 Station 557.20 Begin Core Elev. 554.20 | D E P T H | C O R E | | R Q D | T J M E | - R E N G T H |
| Offset | | (#) | ' (%) | (%) | (min/ft) | (tsf) |
| SANDSTONE - light to medium gray, with numerous shale partings with fracture at 554.20 partings, soft to very soft, moderately well cemented, non-distinct bedding at thin to occasionally medium bedded spacing, fractures at partings are horizontal to 10° planar | | | 100 | 51 | 2.7 | () |
| and smooth, fractures in sandstone are planar to slightly irregular and sandy rough, localized high angle to vertical fractures, fresh to slightly weathered. | | Run 2 | 85 | 21 | 1.2 | |
| | | | | | | 305.0 |
| | -20 | | | | | |
| - near-vertical fracture in sandstone at 19.7', sandy rough | | Dura | 70 | 40 | 1.0 | |
| - thin beds of medium to dark gray shale with numerous sand partings at 20.3'-21.5' | | Run 3 | 73 | 40 | 1.6 | |
| | | | | | | |
| | -25 | Dun | 98 | 38 | 1.2 | |
| | | Run 4 | 90 | 30 | 1.2 | |
| | -30 | | | | | |
| - medium to dark gray shale with numerous sand partings at 30.5'-32.5' | | Run 5 | 98 | 87 | 1 | |
| - occasional shale partings from 32.5' to 35.5' | | | | | | |

Color pictures of the cores Yes
Cores will be stored for examination until

The "Strength" column represents the uniaxial compressive strength of the core sample (ASTM D-2938)

| Illinois Department | | | Page <u>3</u> | of <u>3</u> |
|---|--------------------------------|---------------|--------------------|---------------------------|
| Illinois Department of Transportation ROCK COR | E LOG | Ì | B (| 100/07 |
| Division of Highways CH2M HILL New I-74 Bridge Over Mississip | ni River - Illinois | | Date 8 | |
| ROUTE I-74 Bridge over Mississippi | | LO(| GGED BY | SL |
| SECTION River LOCATION _(N=564827.741, E=2459192 | .07), SEC. 32, 1 | WP. 18 | N, RNG. 1W, | 4 th PM |
| COUNTY Rock Island CORING METHOD NQ Core | | RE | R CORE | S T |
| STRUCT. NO. CORING BARREL TYPE & SIZE NQ Wireli Station 29+40 Core Diameter 1.8 in | E O | C O V | . T Q I . M | R E N |
| BORING NO.VIAIL-104Top of Rock Elev.557.20ftStationBegin Core Elev.554.20ft | P R T E H | E R V | D E | G T H |
| Offset | (ft) (#) | (0/) | (%) (min/ft) | |
| Ground Surface Elev. 568.20 ft | (11) (#) | (%) | (76) (11111/11) | ((5)) |
| SANDSTONE - light to medium gray, with numerous shale partings with fracture at partings, soft to very soft, moderately well cemented, non-distinct bedding at thin to occasionally medium bedded spacing, fractures at partings are horizontal to 10° planar and smooth, fractures in sandstone are planar to slightly irregular and sandy rough, localized high angle to vertical fractures, fresh to slightly weathered. (continued) | <u>-35</u> | 98 | 62 0.6 | |
| | 6 | | | |
| - brownish gray with occasional shale clasts, increasing to numerous clast at 40.0' - 40.3', rough horizontal fractures with localized 70° rough fracture at 39.9' | | | | |
| | 527.90 <u>-40</u> | | | |
| | 527.70 | | | |
| End of Boring | | | | |
| | | | | |
| \$O* | | | | |
| | -45 | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |


Color pictures of the cores <u>Yes</u> Cores will be stored for examination until

Summary of Laboratory Test Results, I-74 Corridor, Wall 081-6018


| Boring | Soil | Depth to Top of Sample (ft) | Sample # | Unified Classification | AASHTO Classification | IDH Classification | Gravel (%) | Sand (%) | Silt (%) | Clay (%) | rganic C (%) LL | PL | IJ | #10 (%) | #40 (%) | #200 (%) | In-Situ WC (%) | Dry Density (pcf) | Compressive Strength (tsf) | Undrained Shear Strength Su (psf) | Total Stress Friction Angle (deg.) | Total Stress Cohesion (psf) | Effective Stress Friction Angle (deg.) | Effective Stress Cohesion (psf) | Cc | Cr | e Preconsol. Press. | (tsf) Remarks |
|---------|-----------------------|--------------------------------|----------|---------------------------|--------------------------|--------------------|------------|----------|----------|----------|-----------------------|----|----|---------|---------|----------|----------------|-------------------|-------------------------------|--------------------------------------|--|--------------------------------|--|------------------------------------|----|----|------------------------|------------------|
| | Sandy Lean Clay | 3-5 | 2 | SM-SC | A-4(0) | | 10 | 48 | 2 | 42 9 | 9.49 28 | 23 | 5 | 90 | 75 | 42 | 30 | | | | | | | | | | | |
| ILR0201 | Silty Sand Tr. Gravel | 8 | 4 | SM | | | 11 | 68 | 2 | 21 9 | 9.59 | | | 89 | 72 | 21 | 40 | | | | | | | | | | | |
| | Silty Sand | 11-13 | 5 | | | | | | | | | | | | | | 11 | | | | | | | | | | | |
| | Sand,Silt&Clay | 6 | 3 | SM | | SA.CL.LO. | 1 | 56 | 18 | 25 | | | | 99 | 95 | 43 | 27 | | | | | | | | | | | |
| ILR0203 | Clay | 8 | 4 | CH | | | | | | | 63 | 17 | 46 | | | | 25 | | | | | | | | | | | |
| | Clay | 10 | 5 | CH | | SI.CL. | 1 | 4 | 64 | 31 | | | | 99 | 98 | 95 | 23 | | | | | | | | | | | |
| | Clayey Silt with Sand | 3-5 | 2 | SC | A-4(0) | | 1 | 64 | 3 | 35 | 26 | 17 | 10 | 99 | 85 | 35 | 24 | | | | | | | | | | | |
| | Clay | 6-8 | T1 | CL | | | | | | | 44 | 24 | 20 | | | | 23 | 102.1 | 1.5 | 1540 | | | | | | | 0.65 | |
| ILR1603 | Clay | 8-10 | 3 | MH | | | | | | | 59 | 31 | 28 | | | | 26 | | | | | | | | | | | |
| | H.Wthd. sandstone | 11-13 | 4 | SM-SC | A-4(0) | SA.LO. | 27 | 46 | 19 | 8 | 25 | 18 | 7 | 73 | 48 | 27 | 26 | | | | | | | | | | | |
| | Limestone | 16 | | | | | | | | | | | | | | | 2 | 157.6 | 472 | | | | | | | | | |
| | Silty Sand | 6.0 | 4 | SM | | | 14 | 58 | 2 | 28 | | | | 86.0 | 79.0 | 28.0 | 18.6 | | | | | | | | | | | |
| RW1501 | Clay | 8.0 | S-1 | CL | | | | | | | 50 | 27 | 23 | | | | 55.6 | 62.1 | | | 14 | 14 | 26.4 | 0 | | | | |
| | Clayey Sand | 12.0 | 7 | SC | | | 16 | 42 | 4 | 42 | | | | 84.0 | 74.0 | 42.0 | 48.4 | | | | | | | | | | | |
| RW1503 | Sandy Clay | 6.0 | 4 | CL | | | | | | | 46 | 25 | 21 | | | | 30.1 | | | | | | | | | | | |

| | | S. | Hanson | | | | | | | | | | |
|---------------------------------------|---------------------|-----------|---------------------------------------|-----------|---------------------------------------|--|--|--|--|--|--|--|--|
| ORGANIC CONTENT | | | | | | | | | | | | | |
| Project: | I-74 Over Mississip | pi River | Job Number: | 08H0120E | | | | | | | | | |
| Client: | Iowa DOT | | Date: | 8/23/2010 | | | | | | | | | |
| Checked by: | SLS | | Date: | 8/23/2010 | - | | | | | | | | |
| Boring/ | Oven Dry | Fired | | | <u> </u> | | | | | | | | |
| Sample | Weight of | Weight of | Weight of | Loss On | Furnace | | | | | | | | |
| Number | Soil+Tare | Soil+Tare | Tare | Ignition | Temperature | | | | | | | | |
| | (grams) | (grams) | (grams) | (%) | (C) | | | | | | | | |
| I-74 01 ST4-2 8.5'-9.0' | 121.34 | 120.03 | 81.55 | 3.3 | 440.0 | | | | | | | | |
| RW01-2 ST2-1 3.0'-3.5' | 93.11 | 92.54 | 79.37 | 4.1 | 440.0 | | | | | | | | |
| RW01-3 ST2-1 3.0'-3.5' | 136.56 | 135.47 | 79.37 | 1.9 | 440.0 | | | | | | | | |
| RW01-3 ST3-2 6.5'-7.0' | 118.23 | 116.79 | 81.55 | 3.9 | 440.0 | | | | | | | | |
| RW02-4 ST2-1 6.0'-6.5' | 142.60 | 140.28 | 79.37 | 3.7 | 440.0 | | | | | | | | |
| RW16-1 ST5-1 11.0'-11.5' | 104.58 | 95.74 | 79.38 | 35.1 | 440.0 | | | | | | | | |
| RW16-1 ST6-1 13.0'-13.5' | 99.40 | 91.88 | 81.56 | 42.2 | 440.0 | | | | | | | | |
| RW135-04 SPT-5 7.0'-7.5' | 87.08 | 85.49 | 81.56 | 28.8 | 440.0 | | | | | | | | |
| | | | | 20.0 | 110.0 | | | | | | | | |
| | | | <u> </u> | i | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | · | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | <u> </u> | | | | | | | | | |
| | | · | · · · · · · · · · · · · · · · · · · · | | | | | | | | | | |
| · · · · · · · · · · · · · · · · · · · | | | <u>+</u> | | | | | | | | | | |
| | | | ╂─────┤ | | | | | | | | | | |
| | | | | | · · · · · · · · · · · · · · · · · · · | | | | | | | | |
| | | | L | | L | | | | | | | | |
| | | | | | | | | | | | | | |


,




Thu, 16-SEP-2010 13:49:44



Thu, 16-SEP-2010 13:46:52




· Columbia is not to 100% for a base order (at)



CONSOLIDATION TEST DATA

SUMMARY REPORT



| | | | | Before Test | After Test |
|--------------------------------|---------------|----------|----------------------|-------------|------------|
| Overburden Pressure: 0 tsf | | | Water Content, % | 26.48 | 22.97 |
| Preconsolidation Pressure: 0 t | sf | | Dry Unit Weight, pcf | 97.88 | 107.6 |
| Compression Index: 0 | | | Saturation, % | 101.68 | 113.25 |
| Diameter: 2.5 in | Height: 0.994 | in | Void Ratio | 0.69 | 0.54 |
| LL: 0 PL: 0 | PI: 0 | GS: 2.65 | | | |

| | Project: 174 | Location: Quad Cities | Project No.: 08H0120E |
|---------------|-------------------------------|-----------------------|-----------------------|
| | Boring No.: RW16-2 | Tested By: RIN | Checked By: JCC |
| | Sample No.: 4-1 | Test Date: 7/16/10 | Depth: 8.2-8.5 |
| HANSON | Test No.: 1 | Sample Type: Tube | Elevation: |
| \sim | Description: Gray silty clay. | | |
| | Remarks: | | |
| | | | |

Location: Quad Cities Tested By: RIN Test Date: 7/16/10

Sample Type: Tube


Project: I74 Boring No.: RW16-2 Sample No.: 4-1 Test No.: 1

IESC NO. · I

Soil Description: Gray silty clay. Remarks:

| | Applied | Final | Void | Strain | T50 F: | itting | Coeffi | cient of Con | solidation |
|----|---------|--------------|-------|--------|--------|--------|-----------|--------------|------------|
| | Stress | Displacement | Ratio | at End | Sq.Rt. | Log | Sq.Rt. | Log | Ave. |
| | tsf | in | | 00 | min | min | in^2/sec | in^2/sec | in^2/sec |
| | | 0 000454 | 0 604 | 0.05 | | | | | |
| 1 | 0.064 | -0.002461 | 0.694 | -0.25 | 0.0 | 0.0 | 0.00e+000 | 0.00e+000 | 0.00e+000 |
| 2 | 0.125 | -0.003623 | 0.696 | -0.36 | 0.0 | 0.0 | 0.00e+000 | 0.00e+000 | 0.00e+000 |
| 3 | 0.25 | -0.003582 | 0.696 | -0.36 | 0.1 | 0.0 | 6.66e-003 | 2.12e-002 | 1.01e-002 |
| 4 | 0.5 | -0.002012 | 0.694 | -0.20 | 0.9 | 0.0 | 9.04e-004 | 0.00e+000 | 9.04e-004 |
| 5 | 1 | 0.002695 | 0.686 | 0.27 | 3.4 | 0.0 | 2.42e-004 | 0.00e+000 | 2.42e-004 |
| б | 2 | 0.01677 | 0.662 | 1.69 | 7.7 | 0.0 | 1.04e-004 | 0.00e+000 | 1.04e-004 |
| 7 | 4 | 0.04393 | 0.616 | 4.42 | 16.0 | 12.5 | 4.77e-005 | 6.09e-005 | 5.35e-005 |
| 8 | 8 | 0.08699 | 0.542 | 8.75 | 27.9 | 0.0 | 2.54e-005 | 0.00e+000 | 2.54e-005 |
| 9 | 2 | 0.07601 | 0.561 | 7.65 | 7.5 | 0.0 | 9.15e-005 | 0.00e+000 | 9.15e-005 |
| 10 | 0.5 | 0.05633 | 0.594 | 5.67 | 44.7 | 0.0 | 1.58e-005 | 0.00e+000 | 1.58e-005 |
| 11 | 0.125 | 0.03336 | 0.634 | 3.36 | 120.4 | 0.0 | 6.15e-006 | 0.00e+000 | 6.15e-006 |
| 12 | 0.064 | 0.02754 | 0.643 | 2.77 | 194.8 | 0.0 | 3.92e-006 | 0.00e+000 | 3.92e-006 |
| 13 | 0.125 | 0.02682 | 0.645 | 2.70 | 0.4 | 0.0 | 2.06e-003 | 0.00e+000 | 2.06e-003 |
| 14 | 0.25 | 0.02735 | 0.644 | 2.75 | 3.9 | 0.0 | 1.95e-004 | 0.00e+000 | 1.95e-004 |
| 15 | 0.5 | 0.02995 | 0.639 | 3.01 | 7.3 | 0.0 | 1.05e-004 | 0.00e+000 | 1.05e-004 |
| 16 | 1 | 0.03525 | 0.630 | 3.55 | 15.8 | 11.8 | 4.81e-005 | 6.45e-005 | 5.51e-005 |
| 17 | 2 | 0.04727 | 0.610 | 4.76 | 16.2 | 0.0 | 4.62e-005 | 0.00e+000 | 4.62e-005 |
| 18 | 4 | 0.06839 | 0.574 | 6.88 | 27.9 | 0.0 | 2.58e-005 | 0.00e+000 | 2.58e-005 |
| 19 | 8 | 0.09394 | 0.530 | 9.45 | 28.0 | 25.6 | 2.45e-005 | 2.68e-005 | 2.56e-005 |
| 20 | 16 | 0.1338 | 0.463 | 13.46 | 36.0 | 26.7 | 1.77e-005 | 2.39e-005 | 2.03e-005 |
| 21 | 32 | 0.1906 | 0.366 | 19.17 | 68.3 | 0.0 | 8.33e-006 | 0.00e+000 | 8.33e-006 |
| 22 | 8 | 0.1774 | 0.389 | 17.85 | 15.2 | 0.0 | 3.54e-005 | 0.00e+000 | 3.54e-005 |
| 23 | 2 | 0.154 | 0.428 | 15.49 | 62.4 | 0.0 | 9.04e-006 | 0.00e+000 | 9.04e-006 |
| 24 | 0.5 | 0.1155 | 0.494 | 11.62 | 232.5 | 0.0 | 2.61e-006 | 0.00e+000 | 2.61e-006 |
| 25 | 0.125 | 0.09645 | 0.526 | 9.70 | 363.6 | 0.0 | 1.78e-006 | 0.00e+000 | 1.78e-006 |
| 26 | 0.064 | 0.08977 | 0.538 | 9.03 | 393.7 | 0.0 | 1.69e-006 | 0.00e+000 | 1.69e-006 |

Project No.: 08H0120E Checked By: JCC Depth: 8.2-8.5 Elevation:



Name: 2 - NEW Embankment Fill Model: Mohr-Coulomb Unit Weight: 125 pcf Cohesion: 1000 psf

- Model: Mohr-Coulomb Unit Weight: 120 pcf Cohesion: 1000 psf Name: 3 - Existing Fill Phi: 0 °
- Model: Mohr-Coulomb Unit Weight: 118 pcf Cohesion: 1000 psf Phi: 0 ° Name: 4 - Silty Clay
- Name: 5 Limestone/Sandstone Model: Bedrock (Impenetrable)
- Name: 7 Sand(W/Material) Unit Weight: 125 pcf Model: Mohr-Coulomb Cohesion: 0 psf Phi: 32 °

Name: 9 - Structural Fill Model: Mohr-Coulomb Unit Weight: 125 pcf Cohesion: 1600 psf Phi: 0 °

SN 081-6018 IL-RW16 Case 1 - Sta 29+00 (E/E) File Name: I-74 RW16 MSE Wall_2.gsz Last Edited By: Robert Chantome Date: 10/20/2011 4:30:15 PM

I-74 OVER THE MISSISSIPPI RIVER CENTRAL SECTION FINAL DESIGN ILLINOIS DEPARTMENT OF TRANSPORTATION **ROCK ISLAND COUNTY, ILLINOIS**





Meeting Minutes

| Project Name: | -74 over the Mississippi | | | | |
|--|---|--|--|--|--|
| Project Number: | M-74-1(185)513-82 | | | | |
| Current Date: | March 15, 2011 | | | | |
| Date of Meeting: | November 16, 2010 | | | | |
| Time of Meeting: | 1:00 p.m 2:30 p.m. | | | | |
| Meeting Location: | Conference Call and WebEx | | | | |
| Regarding: | I-74 FHWA VE Illinois Retaining Walls and Bridges – Status Update | | | | |
| Participant's Name See Attached Sign in Sheet | Title and Company Name | | | | |

1. Purpose of Meeting:

The purpose of the meeting was to discuss the Benesch Team's findings regarding the evaluation of the FHWA's VE Recommendations for the Plug Fill and several retaining walls on the Illinois side. These minutes reflect discussions pertaining to the following:

- Plug Fill which includes retaining walls RW01 (SN 081-6010), RW02 (SN 081-6011), RW16 (SN 081-6018) and RW15
- Retaining wall RW03 (SN 081-6012), which retains Proposed Ramp 6th–D
- Retaining wall RW04 (SN 081-6013), which is east of 19th Street
- Retaining wall RW14, which is east of proposed Ramp 7th-A

David Morrill opened the meeting at 1 p.m. The attendees were identified and added to the attached Attendance Roster.

David noted that Benesch presented our initial findings regarding the plug fill to District 2 on October 25, 2010. The preliminary conclusion from that meeting was to adopt the Structure option. This was based on the Illinois DOT's understanding of the City of Moline's concerns with the Plug Fill option. Subsequent to the October meeting, Benesch refined the cost analysis; specifically the special waste costs. The results remain the same, namely the Plug Fill option is less expensive than the Structure option. The analysis and results are summarized in a PowerPoint presentation (see Attachment A) that was presented during the conference call via WebEx.

With respect to the Plug Fill retaining walls, Benesch's intent was to present the initial findings and recommendations to make sure everyone is on the same page before the Benesch Team proceeds with completing the TSLs and SGRs. The walls presented included retaining wall RW03, an MSE wallwith temporary wire facing and retaining walls RW04 and RW14, soldier pile and lagging walls with permanent CIP concrete facing.

Minutes of Meeting Date of Meeting: November 16, 2010 Page 2 of 5

As noted in Tim's previous comments on the unapproved retaining wall TS&Ls, the D5 preliminary studies did not fully address the soils issues. Therefore those TSLs with soil issues were not approved. Hanson reviewed the D5 SGRs along with additional soil borings and/or analysis to verify these soil concerns. They concluded that some type of soil remediation is required for the Plug Fill area and for RW03 which validates Tim's concerns.

2. Plug Fill Alternatives:

David walked the group through the PowerPoint presentation (see Attachment A) which included the following discussion items:

- Review Preliminary Engineering (Phase I) Design
- Review Existing Soil Conditions
- Review Alternatives
- Review Costs
- Present Renderings
- Advantages and Limitations
- Recommendations
- Next Steps

The existing soils conditions have a wide range of variability with no consistent section. There are significant settlement issues requiring a long time period (over 400 days) for consolidation.

Three alternatives were explored in detailed:

- Plug Fill included the removal and replacement and strengthening of existing soils
- Structure for mainline and ramps
- Structure for mainline only

The City of Moline/Renew Moline expressed concerns with the Plug Fill alternative, a large mass of earth framed by concrete walls that would block views and access.

To assist in the evaluation of the alternatives, visual renderings were created with views looking to the east, the northeast, the north and the northwest.

The advantages of the Plug Fill alternative are:

- Easily accommodates the I-74 MOT crossover and sag;
- Less maintenance;
- Lessens the industrial feeling; and
- Provides opportunity for incorporating aesthetics on the walls.

The limitations of the Plug Fill alternative are:

- Less open vista; and
- Limits east-west access

The advantages of the Structure alternatives are:

• More open vista; and

Minutes of Meeting Date of Meeting: November 16, 2010 Page 3 of 5

Accommodates east-west access,

The limitations of the Plug Fill alternative are:

- Crossover on Structure adds complications;
- Sags on bridges are not generally favored by the Bridge Office;
- More structure to maintain;
- Openness is more of an industrial feel; and
- Does not permit clear view of the river

The cost for the Plug Fill alternative is approximately \$19.0 million while the Mainline and Ramp Structure alternative is approximately \$3.1 million more, i.e. \$22.1 million. The cost for the Mainline only Structure alternative is approximately \$23.5 million which is more than the structure only alternative due to an inefficient combination of bridge and wall. Therefore this alternative was removed from further consideration. If the City of Moline requests that the DOTs build the Mainline and Ramp Structure alternative, then the additional \$3 million cost would be attributed to aesthetics.

The next step is for the Illinois DOT to present these findings to the City of Moline and Renew Moline. Until a decision is made, the Benesch Team is on hold with Phase I tasks such as the completion of TS&L's and SGR's for the Plug Fill alternative or the development of new TS&Ls and SGR's for the Structure alternative. Repercussions affecting the adjacent Illinois Viaduct and the Mississippi River South Approach Structures are unknown and therefore work on these structures is also on hold.

3. Retaining Wall RW03 (SN 081-6012):

Retaining wall RW03 is a mechanically stabilized earth (MSE) wall with precast concrete panels which retains the fill for the proposed Ramp 6th– D roadway. The wall continues in a straight line past the Ramp 6th– D Bridge (SN 081-0187) abutment, terminating at the toe of slope of the abutment spill slope. Piles for the bridge pass through the reinforced soil mass. The unapproved D5 RW03 SGR identified insufficient bearing capacity at the higher segment of the wall.

As the result of these issues, the TSL and SGR for RW03 were not approved. Hanson's preliminary results support the bearing capacity issue and also identified global slope stability issues. Their recommendation is to incorporate soil remediation to the D5 solution as a means to minimize and/or eliminate these concerns.

Benesch considered the following alternatives:

- Alternative A: D5 solution + Strengthen the existing soils
- Alternative B: Reduce the length of wall

Alternative A with modifications to the soils, such as aggregate column ground improvement would increase the D5 cost by at least \$100,000. Alternative B incorporates an embankment with 3:1 slopes resulting in the reduction of the wall by 167 ft and a reduction of the D5 costs by approximately \$250,000. This alternative would still require modifications to the soils. Thus the overall cost savings is expected to be \$150,000 (\$150,000 - \$250,000).

It was agreed to pursue alternative B. Refer to Attachment B for exhibits.

Minutes of Meeting Date of Meeting: November 16, 2010 Page 4 of 5

4. Retaining wall RW04 (SN 081-6013):

Retaining wall RW04 is a hybrid wall retaining both cut and fill soil. The wall is located on the east side of 19th Street. The D5 recommended a soldier pile and lagging wall with permanent cast in place facing. Both the SGR and TS&L were approved for RW04. However, the FHWA VE study identified potential cost savings through reduction and/or elimination of the wall.

Benesch considered the following alternatives:

- Alternative A: D5 solution
- Alternative B: Reduce length of wall by removing the extra 7 ft shoulder.

Alternative B would reduce the length of wall by 100 ft and reduce the height of wall by an average of 3 ft reducing the D5 solution by \$230,000. It was agreed to pursue Alternative B. Refer to Attachment C for exhibits.

5. Retaining Wall RW14

Retaining wall RW14 is a hybrid wall retaining both cut and fill soil. The wall is east of proposed Ramp 7th– A. The D5 recommended an anchored soldier pile and lagging wall with permanent cast in place facing. Both the SGR and TS&L were approved for RW14. However, the FHWA VE study identified potential cost savings through reduction and/or elimination of the wall.

Benesch considered the following alternatives:

- Alternative A: D5 solution
- Alternative B: Replace wall with a concrete barrier adjacent to 19th Street (w/sidewalk behind the concrete barrier)
- Alternative C: Keep the wall but reduce the buffer from 5 ft to 2 ft

Alternative B would replace wall with concrete barrier adjacent to 19th Street (sidewalk behind concrete barrier). However, this alternative would result in potential sight issue with barrier adjacent to the roadway. A sight analysis would be required to determine if the concrete barrier is an obstruction. In addition, Alternative B would require drainage structures on both side of the concrete barrier. On the sidewalk side, the structure cannot be within the walking surface. Finally, this alternative would have a concrete barrier blunt end near the intersection of 19th Street and 11th Avenue that would require guardrail to protect the motorists. Ideally the guardrail would wrap around the curb return, but due to the pedestrian movement across 11th Avenue, this cannot happen. A Terminal Type 1 would need to be used.

Alternative C would reduce the buffer from 5 ft to 2 ft giving a total width from face of wall to back of curb of 7 ft. Potential cost savings would be approximately \$65,000; however the Benesch Team would need to revise and resubmit the already approved TS&L. It was agreed to keep the D5 design. Refer to Attachment D for exhibits.

Minutes of Meeting Date of Meeting: November 16, 2010 Page 5 of 5

6. Conclusions and next steps:

The Benesch Team will proceed with the following actions:

- Complete the unapproved SGR and TS&L for retaining wall RW03 based on Alternative B.
- Revised the approved TS&L for retaining wall RW04 based on Alternative B.
- Keep the D5 solution for retaining wall RW14.

The Illinois DOT will present the Plug Fill and Structure Alternatives to the City of Moline.

The Meeting adjourned at 2:30 p.m.

Closure:

The above constitutes our understanding of the issues discussed and the conclusions reached. If there are any misunderstandings or omissions, please forward comments/corrections within five business days to the undersigned.

Respectfully submitted,

and & Monil

David J. Morrill, S.E., P.E. Vice President Project Manager

DJM/DMC:qmf

ere M Canquere

Diane M. Campione, S.E., P.E. Deputy Project Manager

cc: All Attendees Benesch Team Members



Millinois Department of Transportation

ATTENDANCE ROSTER

I-74 Final Design-FHWA VE Recommendation Review Meeting MEETING LOCATION: <u>WebEx and Star Conference Call</u>

< or

DATE: November 16, 2010

| LAST | FIRST | POSITION/OFFICE | TELEPHONE | CELL PHONE | E-MAIL ADDRESS | |
|------------------|---------|---|--------------|--------------|-------------------------------|--|
| | | | | | | |
| | | | | | | |
| THE ILLINOIS DOT | | | | | | |
| Craven | Tim | Illinois DOT BBS | | | Tim.Craven@illinois.gov | |
| Marruffo | Rebecca | Project Engineer Illinois DOT – District 2 | 815-284-5902 | | Rebecca.Marruffo@illinois.gov | |
| | | | X | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| BENESCH | | | | | | |
| Campione | Diane | Deputy Project Manager | 312-565-0450 | 312-925-0997 | dcampione@benesch.com | |
| Morrill | David | Project Manager | 312-565-0450 | 312-560-7947 | dmorrill@benesch.com | |
| | | | | | 1 | |
| ······ | | | 1 | | | |
| | | | | | | |

ATTACHMENT A

PLUG FILL POWERPOINT PRESENTATION (includes retaining walls RW01 (SN 081-6010), RW02 (SN 081-6011), RW16 (SN 081-6018) and RW15)

I-74 Final Design Plug Fill VE Study Results

November 16, 2010




Agenda

- Review Preliminary Engineering (Phase I) Design
- Review Existing Soil Conditions
- Review Alternatives
- Review Costs
- Present Renderings
- Advantages and Limitations
- Recommendations
- Next Steps




Preliminary Engineering (Phase I) Design - Plug Fill



I-74/Mississippi River

Preliminary Engineering (Phase I) - Plug Fill MOT Crossover (Year 5 Stage 2)



Existing Soil Conditions in Plug Fill Area

Subsurface Profile (top to bottom)

- Random fill (varies 6 12 ft)
- Loose sand filled with debris (varies 2 6 ft; one location 20 ft)
- Soft to very soft clay with organic (4 10 ft)
- Weathered sandstone, shale or weathered shale bedrock



Existing Soil Conditions in Plug Fill Area

Soil Analysis Results

- Stability Analysis of abutment end slope
 - Low Factor of Safety
- Settlement Analysis (primary)
 - differential settlement
 - 90% consolidation within 60 days near abutment
 - 90% consolidation within 420 days elsewhere
- Settlement Analysis (secondary/creep)
 - 1.8 inches after 5 years
 - 2.4 inches after 25 years

after construction of embankment



Plug Fill Alternative Recommendations

@ North End (north of Sta. 26+00)

- Remove soft clay, organic materials and random fill down to bedrock
- Replace with PGE

@ South End

- Remove Special Waste (estimated at 10%) and replace with PGE
- Use Aggregate Column Ground Improvement (AGCI) to strengthen the existing soil




Plug Fill Final Condition


- Acceptable factor of safety for abutment slope
- Primary consolidation concerns addressed
- Secondary consolidation concerns addressed
- Eliminate down drag on piles



Plug Fill: Depths of Required Soil Removal


O







Longitudinal Section Along I-74













Alternative A: Structure (mainline and ramp)





Alternative B: Structure (mainline only)






Cost Summary

- Plug Fill
 \$19.0 Million
- Alternative A Structure: Mainline and Ramp
 \$22.1 Million
- Alternative B Structure: Mainline only
 \$23.5 Million






View 1 - Plug Fill From River Drive: West of Ramp RD-G



View 1 - Alternative A (Structure) From River Drive: West of Ramp RD-G



View 2 - Plug Fill From River Drive: East of Ramp RD-H





View 2 - Alternative A (Structure) From River Drive: East of Ramp RD-H






View 3 - Plug Fill (looking west)



22

View 3 - Alternative A (Structure) (looking west)





View 4 - Plug Fill (looking NE from River Drive)





View 4 - Alternative A (Structure) (looking NE from River Drive)




I-74/Mississippi River

View 5 - Plug Fill (looking East)



View 5 - Alternative A (Structure) (looking East)




I-74/Mississippi River

Plug Fill - Advantages

- Accommodates (MOT) crossover
- Accommodates sag
- Less maintenance
- Lessens the industrial "feeling"
- Opportunity for creative aesthetics (on wall segments)
- Opportunity to achieve required consolidations (work offline in early stages)








Structure - Limitations


- Crossover on structure adds complications
- Sag on Bridge not favored by Bridge Office
- More structure to maintain
- Openness is more of industrial feel
- Not clear view of river




MOT: Crossover (Year 5 Stage 2)



MOT Crossover (Year 5 Stage 2)



33



Recommendations

Build Structure for Mainline and Ramps??

• Extra \$3 million cost attributed to aesthetics

