



## **REMOVE AND REERECT STEEL PLATE BEAM GUARDRAIL**








WOOD POST CONSTRUCTION





12

¾ Dia. hole

rail element and block-out at non-splice mounting points only when steel block-outs are used.

121/4

PLATE A

HIBM 4415 HEST HARRISON ST. ENGINEERING GROUP LLC SUITE 231 COSPECTION & A REVING RESEARCH & TESTING FAX: (TOB) 235-0900 RESEARCH & TESTING		DESIGNED - DISTRICT 2	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	DISTRICT 2 STANDARD – 53.1 EB US ROUTE 20 OVER PECATONICA RIVER STRUCTURE NO. 089–0042	F.A.P.	SECTION	COUNTY S	TOTAL SHEE
		CHECKED - MI	REVISED -			0301	(177-4B-1)M	STEPHENSON	43 15
		DRAWN - DISTRICT 2	REVISED -					CONTRACT	NO. 64J2
	DATE - 03/13/2013	CHECKED - JMG, MAI	REVISED -		SHEET NO. 2 OF 4 SHEETS	ILLINOIS FED. AID PROJECT			
	DATE - 03/13/2013	CHECKED - JMG, MAI	REVISED -		SHEET NO. 2 OF 4 SHEETS	ILLINOIS FED. AID PROJECT			