

3

LOAD RATING INSPECTION REPORT

3

Date: 10/22/2015

3

Structure Number:		16-0195	District:	1	Date:		
Carried/Crossed:		1 over IHB RR		Proposed Year of Improvement:			
Inspection Date:		0/21/15	Inspector(s):	B.Vegrzyn-V	<u>3</u> Re [.]	viewed by: <u>I</u>	Burke-V3
Initial NBIS Ratings				Recommended NBIS Ratings			
58	59	60	62	58	59	60	62

5


Remarks: The expansion joints are in very poor condition. The east and west columns of Pier 8 are in very poor condition.

Forwarded to: W.Beisner-IDOT BBS


5


Additional Comments:

6





016 - 0195 D1 10/21/15








BEAM 9 NORTH END SPAN 2 AT PIER 2 PHOTO 17 (LOOKING WEST)
















































8 INENd SP BI 00 62

