


* 3" below abutment seat or 1" min. below existing transverse reinforcement; whichever is greater. Existing exposed reinforcement shall be cleaned and incorporated into the new construction. Cost included with concrete removal.



SECTION D-D

LEGEND

Concrete Removal

Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Slope Wall Removal (See Note 4)

NOTES:

- 1. Actual quantities of repairs shall be approved by the Engineer.
- 2. Existing vertical reinforcement shall be cut flush with the the concrete removal surface, except as noted. Cost included with "Concrete Removal".
- 3. See Sheet SA2 for Pay Limits of "Structure Excavation".
- 4. Replace Slope Wall in-kind up to front face of Proposed Wingwall. Re-use existing Welded Wire Fabric. Cost to re-use fabric is included with "Slope Wall 4 inch".

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structure Excavation	Cu. Yd.	98
Granular Backfill for Structures	Cu. Yd.	96
Concrete Removal	Cu. Yd.	26.2
Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)	Sq. Ft.	2
Slope Wall Removal	Sq. Yd.	2
Slope Wall 4 inch	Sq. Yd.	2

CHECKED -DJM REVISED 161000_60J16_033_NAbutRepair_NB.dgn MAK REVISED CHECKED REVISED PLOT DATE = 12/20/2012 RMM

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** NORTH ABUTMENT CONCRETE REMOVAL AND REPAIR DETAILS STRUCTURE NO. 016-1000/1001 SHEET NO. SA33 OF SA40 SHEETS

SECTION COUNTY COOK 821 281 372 2013-038B-R CONTRACT NO. 60J16