



**ELEVATION**  
(Showing Inside Face of East Wall)

*Note:*  
The limits of Epoxy Crack Injection shown are approximate. The limits of Epoxy Crack Injection may vary in the field. Changes in the quantity of Epoxy Crack Injection shall be approved by the Engineer.

~~~~~ Indicates Epoxy Crack Injection Required

FILE NAME = 300-0162-76789-004.dgn



|                                        |               |           |
|----------------------------------------|---------------|-----------|
| USER NAME = jdirkeimann                | DESIGNED - JD | REVISED - |
| Illinois Design Firm Number 184.001670 | CHECKED - BB  | REVISED - |
| PLOT SCALE =                           | DRAWN - WS    | REVISED - |
| PLOT DATE = 8/8/2014                   | CHECKED - CJF | REVISED - |

STATE OF ILLINOIS  
DEPARTMENT OF TRANSPORTATION

EXISTING BOX CULVERT REPAIR DETAILS  
STRUCTURE NUMBER 042-2473

SHEET NO. 4 OF 4 SHEETS

| F.A.S. RTE.               | SECTION   | COUNTY | TOTAL SHEETS       | SHEET NO. |
|---------------------------|-----------|--------|--------------------|-----------|
| 752                       | 101-2R5-1 | JERSEY | 438                | 233       |
| ILLINOIS FED. AID PROJECT |           |        | CONTRACT NO. 76789 |           |