

Repair collapsed and undermined section

Repair 2 PGL EB I-80

Repair 2 PGL EB I-80

Repair 2 PGL EB I-80

Repair 3 PGL EB I-80

Repair 3 PGL EB I-80

Repair 4 PGL EB I-80


Repair 5 PGL EB I-80

Repair 5 PGL EB I-80

Repair 5 PGL EB I-80


PLAN - WEST SLOPEWALL

PLAN - EAST SLOPEWALL




SECTION A-A


SECTION C-C



SECTION B-B



SECTION D-D



SECTION E-E

BILL OF MATERIAL

ITFM	LIMITE !	TOTAL
II EM	UNIT	IOIAL
Porous Granular Embankment	Cu.Yd.	39
Slope Wall Removal	Sq.Yd.	78
Slope Wall 4 Inch	Sq.Yd.	78

LEGEND:



Slopewall Remove and Replace

NOTES:

- Areas of proposed slopewall removal and replacement are estimated.
 Actual location and dimensions are to be determined by the Engineer during construction.
- 2. Cost of saw cuts and PJF included in the cost of Slope Wall 4 Inch.

	DESIGNED - PCA	REVISED -	
USER NAME = lsupencheck	DRAWN - LK	REVISED -	
PLOT SCALE = 1:1	CHECKED - MEA	REVISED -	
PLOT DATE = 20-JAN-2011	DATE - 01/21/2011	REVISED -	



STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SLOPEWALL REPAIRS
EASTBOUND FAI-80 OVER RAILROADGARDNER STREET
STRUCTURE NO. 099-0060

SHEET NO. S-7 OF 15 SHEETS

FILE NAME = IP_PWPidms34575\Ø99ØØ6Ø-6ØM64-ØØ7-SLOPEW.DGN