



SOUTH BOUND LANES SOUTH ABUTMENT EAST CORNER (Looking South)




NORTH BOUND LANES
SOUTH ABUTMENT
EAST CORNER

(Looking South)




SOUTH BOUND LANES
SOUTH ABUTMENT
WEST CORNER
(Looking South)



NORTH BOUND LANES
SOUTH ABUTMENT
WEST CORNER

(Looking South)




SOUTH BOUND LANES

NORTH ABUTMENT

WEST CORNER

(Looking North)




NORTH BOUND LANES

NORTH ABUTMENT

WEST CORNER

(Looking North)




SOUTH BOUND LANES

NORTH ABUTMENT

EAST CORNER

(Looking North)



NORTH BOUND LANES

NORTH ABUTMENT

EAST CORNER

(Looking North)

NOTES

Hatched area indicates area of Structural Repair of Concrete, Exact repairs are to be determined by the Engineer.

BILL OF MATERIAL

Item	Unit	Total
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	64

<u>ABUTMENT REPAIR DETAILS</u> S.N. 082-0241 (NB) & 082-0242 (SB)

FILE NAME : DESIGNEO - REVISED - CHECKEO - CHE



Allen Henderson & Associates, Inc. Civil and Structural Engineers Springfield, IL. 62703 Phone: (217)544-8033 IL. Design Firm No. 184-001907

ABUTMENT REPAIR DETAILS

SHEET NO. 21 OF 22 SHEETS

F.A.I. SECTION COUNTY TOTAL SHEETS NO. 255 82-2HB-2-1 ST. CLAIR 54 53 CONTRACT NO. 76B21