

Repair Detail No.	09/16/13 NIBS Inspection Deficiency Item No.	Location	Sheet No.
Structural Painting	1	5' Either Side of Deck Joints, Main Spans Splash Zone	S88
Drainage System	368	Span W, South side Deck Drains	S128
Drainage System	369	Bent 1, North Column	S128
Drainage System	309	Span 4, 20' from Bent 3 at Girder 1	S128
Drainage System	-	Span 4, midspan at Girder 4	S128
Drainage System	372	Span 9, South side Deck Drains	S128
Drainage System	-	Span 9, Panel 3 near Stringer 1	S128
Drainage System	-	Span 9, Panel 6 near Stringer 1	S128
Drainage System	144	Span 9, Panel 7 and Panel 8 near Stringer 1	S128
Drainage System	-	Span 9, Panel 8 near Stringer 1 and Stringer 7	S128
Drainage System	305	Bent 31 at North Column	S128
Miscellaneous Steel Repairs	100	Span W, under Stringer 5 at Bent W	S87
Miscellaneous Steel Repairs	-	Bent W, 6' above base of North Column	S87
Miscellaneous Steel Repairs	103	Span X, between Stringer 1 and Stringer 2 at Midspan	S87
Miscellaneous Steel Repairs	104	Span X, between Stringer 3 and Stringer 4 at Midspan	S87
Miscellaneous Steel Repairs	106	Bent 1 at Stringer 6	S87
Miscellaneous Steel Repairs	107	Bent 1 at Stringer 4	S87
Miscellaneous Steel Repairs	-	Bent 1, 4' above base of North Column	S87
Miscellaneous Steel Repairs	-	Bent 1, 4' above base of South Column	S87
Miscellaneous Steel Repairs	108	Span 2, Stringer 7, 5' from Bent 1, 5' from Bent 2, and at Bent 2	S87
Miscellaneous Steel Repairs	109	Span 2, Stringer 1 at Bent 2	S87
Miscellaneous Steel Repairs	-	Bent 3, South Column	S87
Miscellaneous Steel Repairs	66	Bent 3, North Column	S87
Miscellaneous Steel Repairs	-	Bent 4, North Column	S87
Miscellaneous Steel Repairs	-	Bent 6, North Column	S87
Miscellaneous Steel Repairs	-	Bent 6, South Column	S87
Miscellaneous Steel Repairs	119	Bent 7 at Stringer 4	S87
Miscellaneous Steel Repairs	371	Bent 7 at South Column Long. Bracing	S87
Miscellaneous Steel Repairs	311	Span 9, Stringer 7, 6' East of Floorbeam 0	S87
Miscellaneous Steel Repairs	125	Span 9, Floorbeam 1 at Stringer 3	S87
Miscellaneous Steel Repairs	41	Span 9, L4N - U4N, 4' and 20' above Deck	S87
Miscellaneous Steel Repairs	-	Span 9, L4S - U4S, 4' above Deck	S87
Miscellaneous Steel Repairs	-	Span 9, L10S - U10S, 4' above Deck	S87
Miscellaneous Steel Repairs	75	Span 9/10, M14N - M14S, 20' above Deck	S87
Miscellaneous Steel Repairs	48	Span 10, Floorbeam 18 between Stringer 1 and Stringer 2	S87
Miscellaneous Steel Repairs	-	Span 10, L18S - U18S, 4' and 30' above Deck	S87
Miscellaneous Steel Repairs	50	Span 10, L23N - U23N, 4' above Deck	S87
Miscellaneous Steel Repairs	51	Span 10, L23N - U23N, 30' above Deck	S87
Miscellaneous Steel Repairs	177	Span 10, Floorbeam 24' at Stringer 2	S87
Miscellaneous Steel Repairs	21	Span 10, L23'S - U23'S, 30' above Deck	S87

Repair Detail No.	09/16/13 NIBS Inspection Deficiency Item No.	Location	Sheet No.
Miscellaneous Steel Repairs	181	Span 10, Floorbeam 23' at Stringer 3	S87
Miscellaneous Steel Repairs	182	Span 10, Floorbeam 23' at Stringer 4	S87
Miscellaneous Steel Repairs	183	Span 10, Floorbeam 23' at Stringer 4	S87
Miscellaneous Steel Repairs	-	Span 10, L21'N - M21'N, 12' above Deck	S87
Miscellaneous Steel Repairs	187	Span 10, Floorbeam 21' at Stringer 2	S87
Miscellaneous Steel Repairs	-	Span 10, M19'N, outside Gusset Plate	S87
Miscellaneous Steel Repairs	-	Span 10, L18'N - U18'N, 4' and 25' above Deck	S87
Miscellaneous Steel Repairs	190	Span 10, Lower Lateral Connection at L15'N	S87
Miscellaneous Steel Repairs	192	Span 10/11, L14'N, outside Gusset Plate	S87
Miscellaneous Steel Repairs	-	Span 11, L13'S - M13'S, 4' above Deck	S87
Miscellaneous Steel Repairs	54	Span 11, L13'S - M13'S, 40' above Deck	S87
Miscellaneous Steel Repairs	361	Span 11, L11'N inside Gusset Plate	S87
Miscellaneous Steel Repairs	362	Span 11, L11'S inside Gusset Plate	S87
Miscellaneous Steel Repairs	200	Span 11, Stringer 2 at L11'	S87
Miscellaneous Steel Repairs	-	Span 11, L10'N - U10'N, 4' and 30' above Deck	S87
Miscellaneous Steel Repairs	207	Span 11, Floorbeam 8' at L8'N	S87
Miscellaneous Steel Repairs	60	Span 11, Floorbeam 5', North end	S87
Miscellaneous Steel Repairs	-	Span 11, L4'S - U4'S, 4' above Deck	S87
Miscellaneous Steel Repairs	61	Span 11, L4'S - U4'S, 30' above Deck	S87
Miscellaneous Steel Repairs	214	Span 11, L4'N - U4'N, at L4'N	S87
Miscellaneous Steel Repairs	220	Span 11, Floorbeam 4' at Stringer 7	S87
Miscellaneous Steel Repairs	221	Span 11, L4'S - U4'S, at L4'S	S87
Miscellaneous Steel Repairs	62	Span 11, Floorbeam 3' at North end	S87
Miscellaneous Steel Repairs	247	Span 12, U0'S - U1'S at U0'S	S87
Miscellaneous Steel Repairs	339	Span 13, U3N - L4N at 5' from U3N	S87
Miscellaneous Steel Repairs	341	Span 13, Floorbeam 2' at South end	S87
Miscellaneous Steel Repairs	32	Span 21, Stringer 1 at West Splice	S87
Miscellaneous Steel Repairs	33	Bent 22 Tower Bracing	S87
Miscellaneous Steel Repairs	284	Bent 22 at Stringer 2	S87
Miscellaneous Steel Repairs	289	Bent 23 Cap at South end	S87
Miscellaneous Steel Repairs	367	Span 23, Stringer 1 at Bent 23	S87
Miscellaneous Steel Repairs	346	Span 27, Stringer 7 at Midspan	S87
Miscellaneous Steel Repairs	348	Span 30, Stringer 6 at Bent 30	S87
Concrete Median Repair	349	Span X, 12' East of Bent W	S87
Concrete Median Repair	-	Span Y, 12' West of Bent Y	S87
Concrete Median Repair	-	Span 7, at Bent 7	S87
Concrete Median Repair	-	Span 8, 24' West of Pier 8	S87
Concrete Median Repair	-	Span 10, at Panel 22	S87
Decorative Lighting	5	Spans 9 - 13	S12

Note:  
If repair details encompass multiple sheets,  
the first sheet number has been referenced.