



LEGEND

Deteriorated asphalt wearing surface (assumed Deck Slab Repair-Partial)

Notes:
Deck Condition Survey performed 12/22/2010 (by IDOT-D6).
Repair areas are estimated, the Engineer shall determine actual repair locations and record them on the As-Built plans.

BILL OF MATERIAL

Item	Unit	Total
Deck Slab Repair (Partial)	Sq. Yd.	30
Silicone Joint Sealer, 2 3/4"	Foot	59

FILE: J:\IDOT\102004_IL-DBV\7-1-12_ILopolis\KentFarm\0840160-72C88-002-deck.dgn
SAVE DATE: 4/2/2013

FILE NAME =	USER NAME = DCD	DESIGNED - CMV	REVISED -
... \0840160-72C88-002-deck.dgn		CHECKED - DCD	REVISED -
PLOT SCALE =		DRAWN - P. Ray	REVISED -
PLOT DATE = 04/02/2013 17:14:26		CHECKED - CMV/DCD	REVISED -

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**DECK REPAIRS
STRUCTURE NO. 084-0160**

SHEET NO. 2 OF 2 SHEETS

PART B - SHEET 47 of 67

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
72	(84-10-3)RS-5	SANGAMON	95	75
STA. 561+60.58		CONTRACT NO. 72C88		
ILLINOIS FED. AID PROJECT				