STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

ROUTE NO.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
F.A.P. 309	16R-2	WHITESIDE	547	194
FED. ROAD DIST. NO. 4	ILLINOIS	FED. AID PROJECT-		

SHEET NO. 7
7 SHEETS

Contract # 64969

Illinois Department of Transportation
Division of Highways
IDOT

SOIL BORING LOG

Page 1 of 2

Date 4/30/02

ROUTE FA 309 DESCRIPTION P92-140-00 Culvert on US 30, 150' E. of Bishop Road in Morrison LOGGED BY C. Jenkins

SECTION 16RS LOCATION Mt. Pleasant Twp. - SW, SEC. 16, TWP. 21N, RNG. 5E

COUNTY Whiteside DRILLING METHOD Hollow Stem Auger HAMMER TYPE B-53 Diedrich Automatic

STRUCT. NO.
Station 1158+15

BORING NO. B-2c
Station 1158+00
Offset 13.00ft Lt CL
Ground Surface Elev. 641.7 ft

Surface Water Elev. 633.4 ft
Stream Bed Elev. 633.1 ft

Groundwater Elev.:
First Encounter 626.7 ft ▼
Upon Completion Wash ft
After Hrs. ft

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)	DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
Road Rock				LOOSE gray coarse SAND 621.20	1 2 6		
MEDIUM brown SILTY LOAM 639.20		0.5 P	20				
MEDIUM brown SILTY LOAM 637.70	2 3 2	0.7 P	31	MEDIUM gray SAND & GRAVEL 617.70	5 10 7		
MEDIUM black SILTY LOAM 638.20	1 2 3	0.8 P	33	Begin Wash MEDIUM gray SAND & GRAVEL 615.20	5 7 11		
MEDIUM blue/grey SILTY LOAM 632.70	1 1 3	0.7 P	33	Wash MEDIUM tan SAND with some GRAVEL 612.70	5 8 9		
SOFT gray/green SILT 630.20	2 2 3	0.3 B	29	Wash MEDIUM tan fine grained SAND 610.20	8 9 20		
MEDIUM gray/brown SILT with 13% ORGANICS 627.70	2 2 3	0.7 B	43	Wash MEDIUM tan fine grained SAND 607.70	5 11 12		
MEDIUM gray/brown SILT 625.20	0 2 4	0.9 B	32	Wash Same as above 605.20	2 5 7		
STIFF gray SANDY SILT with ORGANICS 622.70	1 3 5	1.1 B	20	Wash VERY SOFT gray/tan SANDY SILT 602.20	1 1 1	0.1 P	26

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

BBS, from 137 (Rev. 8-99)

Illinois Department of Transportation
Division of Highways
IDOT

SOIL BORING LOG

Page 2 of 2

Date 4/30/02

ROUTE FA 309 DESCRIPTION P92-140-00 Culvert on US 30, 150' E. of Bishop Road in Morrison LOGGED BY C. Jenkins

SECTION 16RS LOCATION Mt. Pleasant Twp. - SW, SEC. 16, TWP. 21N, RNG. 5E

COUNTY Whiteside DRILLING METHOD Hollow Stem Auger HAMMER TYPE B-53 Diedrich Automatic

STRUCT. NO.
Station 1158+15

BORING NO. B-2c
Station 1158+00
Offset 13.00ft Lt CL
Ground Surface Elev. 641.7 ft

Surface Water Elev. 633.4 ft
Stream Bed Elev. 633.1 ft

Groundwater Elev.:
First Encounter 626.7 ft ▼
Upon Completion Wash ft
After Hrs. ft

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
Wash MEDIUM tan/yellow weathered LIMESTONE 600.20	10 7 6		
Wash Same as above 597.70	5 9 11		
End of Boring			

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)

BBS, from 137 (Rev. 8-99)

DESIGNED	L.L.V
CHECKED	B.L.
DRAWN	M.G.M
CHECKED	L.L.V

BORING LOGS
US RTE. 30 OVER UNNAMED CREEK
F.A.P. ROUTE 309 SECT. 16R-2
WHITESIDE COUNTY
STATION 1158+14.82
STRUCTURE NO. 098-2025

STS CONSULTANTS
111 NE Jefferson Ave.
Peoria, Illinois 61602
Ph(309)676-8464
FAX(309)676-5445
IL Design Firm Reg. No. 64-00156

S:\DOT-098-2025.dgn 1/10/2006 2:16:10 PM