F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
350	103 BS-2	COOK	22	9
STA.		TO STA.		
FED. ROAD DIST NO. 7	ILLINOIS	FED. AID PROJECT		



TRAFFIC SIGNAL LEGEND

- SERVICE INSTALLATION
- CONTROLLER
- DOUBLE HANDHOLE
- HANDHOLE
- HEAVY-DUTY HANDHOLE
- SIGNAL HEAD
- SIGNAL HEAD WITH BACKPLATE
- MAST ARM ASSEMBLY AND POLE, STEEL
- SIGNAL POST
- DETECTOR LOOP
- G.S. CONDUIT IN TRENCH OR PUSHED
- CT — COMMON TRENCH
- UTILITY CO. POLE
- R.O.W. — RIGHT OF WAY
- PVC — POLYVINYLCHLORIDE
- SIGN PANEL LOCATION
- N.T.S. — NOT TO SCALE
- PEDESTRIAN PUSHBUTTON
- PEDESTRIAN SIGNAL HEAD

REPLACE ALL DETECTOR LOOPS AS SHOWN

(WITHIN THE RESURFACING LIMITS)

CODE NO.	QUANTITY	UNIT	ITEM
8600600	1026	Foot	Detector Loop Replacement

NOTE:

THIS PLAN IS FOR THE PURPOSE OF REPLACING THE DETECTOR LOOPS ONLY. ALL OTHER INFORMATION SHOWN IS NOT RELATED AND WILL BE DISREGARDED.

REVISIONS	
NAME	DATE

ILLINOIS DEPARTMENT OF TRANSPORTATION

DETECTOR LOOP REPLACEMENT

U.S. RTE. 41 @ GLENVIEW ROAD

SCALE: NONE

DATE: Dec. 31, 2008

DRAWN BY: JHE
DESIGNED BY: JHE
CHECKED BY: DAD