F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
24	*	**	189	53
STA.		TO STA.		
FED. ROAD DIST. NO.		ILLINOIS	FED. AID PROJECT	

* XL-2,44(2,3,4)RS,BSMARTFY04-4
** WILLIAMSON/JOHNSON
CONTRACT NO.: 98758

TREE REMOVAL

LOCATION STA TO STA (MP IS THE LAST STA. UNLESS OTHERWISE NOTED)		OFFSET FROM E.P. FEET	TREE REMOVAL (6 TO 15 UNITS DIAMETER) UNIT	TREE REMOVAL (OVER 15 UNITS DIAMETER) UNIT	TREE REMOVAL ACRES ACRE	REMARKS
EB LANES						
LT 175+28	(MP 10.6)	126	12			LEFT OF PAVED DITCH, UP BACKSLOPE, (OAK)
LT 175+91	(MP 10.6)	148	11			LEFT OF PAVED DITCH, UP BACKSLOPE, (HICKORY)
LT 176+03	(MP 10.6)	150		16		LEFT OF PAVED DITCH, UP BACKSLOPE
LT 188+28	(MP 10.8)	177	9			RIGHT OF PAVED DITCH, UP FORESLOPE, (OAK)
LT 188+63	(MP 10.8)	177	6			RIGHT OF PAVED DITCH, UP FORESLOPE, (CHERRY)
LT 189+23	(MP 10.8)	183	6			RIGHT OF PAVED DITCH, UP FORESLOPE
LT 193+12	(MP 10.9)	116	6			7' FROM HEADWALL
LT 193+36	(MP 10.9)	94	12			50' FROM HEADWALL
LT 193+50	(MP 10.9)		11			20' FROM HEADWALL
LT 196+90	(MP 11.0)	97	6			
LT 196+94	(MP 11.0)	92	7			
LT 196+94	(MP 11.0)	64	7			(CEDAR)
LT 197+10	(MP 11.0)	76	8			(CEDAR)
LT 199+11	(MP 11.0)	48	6			SOUTH OF PAVED DITCH, 48' LEFT OF EBL, MEDIAN GORE AREA, (CEDAR)
LT 226+05	(MP 11.6)	48	8			6' UP THE BACKSLOPE (CEDAR)
LT 226+09	(MP 11.6)	46	6			2.5' UP THE BACKSLOPE (CEDAR)
LT 226+47	(MP 11.6)	68	13			1' UP THE BACKSLOPE (SYCAMORE)
LT 226+78	(MP 11.6)	88	9			4' UP THE BACKSLOPE
LT 230+10	(MP 11.6)	152	6			1' UP THE FORESLOPE
LT 229+93	(MP 11.6)	49	7 9			2 TREES, (CEDAR)
LT 229+96	(MP 11.6)	62	9			
LT 230+00	(MP 11.6)	66	9			
LT 230+03	(MP 11.6)	100	6 7			2 TREES
LT 230+05	(MP 11.6)	71	6			
LT 233+02	(MP 11.7)	85	8			
LT 233+02	(MP 11.7)	88	6			
LT 233+05	(MP 11.7)	119	7 7 9 10			4 TREES
LT 234+92	(MP 11.7)	148		33		LEFT OF PAVED DITCH, MEDIAN GORE AREA, (OAK)
LT 235+12	(MP 11.7)	130		16		RIGHT OF PAVED DITCH, UP FORESLOPE
LT 236+00	(MP 11.8)	95	9			
LT 241+86	(MP 11.9)	44 TO 120			0.05	SEE PLAN FOR REMOVAL 44' FROM EDGE OF SHOULDER
WB LANES						
LT 150+52	(MP 2.1)	160	6			RIGHT OF PAVED DITCH, FORESLOPE , (SYCAMORE)
LT 150+63	(MP 2.1)	170	6			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 150+64	(MP 2.1)	173	9 12			2 TREES, 3' PAST PAVED DITCH , UP BACKSLOPE, (MAPLE)
LT 150+75	(MP 2.1)	170	10			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 151+20	(MP 2.1)	170	6 7			2 TREES, LEFT OF PAVED DITCH
LT 151+66	(MP 2.2)	170	6			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 151+84	(MP 2.2)	170	8			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 151+90	(MP 2.2)	170	6			DOWNED TREE RIGHT OF PAVED DITCH, UP FORESLOPE
LT 152+15	(MP 2.2)	170	8			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 152+20	(MP 2.2)	160	8			RIGHT OF PAVED DITCH, UP FORESLOPE, (CEDAR)
LT 153+10	(MP 2.2)	165	6			FALLEN TREE
LT 153+23	(MP 2.2)	160	6			RIGHT OF PAVED DITCH, UP FORESLOPE, (CEDAR)
LT 153+34	(MP 2.2)	160	6			RIGHT OF PAVED DITCH, UP FORESLOPE, (CEDAR)
LT 155+85	(MP 2.3)	130	6			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 174+61	(MP 2.6)	126	6			8' FROM SOUTH WING-TREAT STUMP WITH HERBICIDE
LT 174+61	(MP 2.6)	126	6			4' FROM SOUTH WING-TREAT STUMP WITH HERBICIDE
LT 174+61	(MP 2.6)	127	6			3' FROM SOUTH WING-TREAT STUMP WITH HERBICIDE
LT 174+61	(MP 2.6)	130	8			3' SOUTHWEST OF HEADWALL-TREAT STUMP WITH HERBICIDE
LT 174+90	(MP 2.6)	150	11			RIGHT OF PAVED DITCH, UP FORESLOPE
LT 175+61	(MP 2.6)	164	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 176+29	(MP 2.6)	162	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 176+44	(MP 2.6)	162	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 177+31	(MP 2.6)	162	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 178+81	(MP 2.7)	150	7			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 180+32	(MP 2.7)	122	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 180+49	(MP 2.7)	120	6			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 182+82	(MP 2.7)	72	7			LEFT OF PAVED DITCH (DEAD TREE)
LT 182+95	(MP 2.7)	64	8			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 183+10	(MP 2.7)	60	7			LEFT OF PAVED DITCH, UP BACKSLOPE, (CEDAR)
LT 244+09	(MP 3.9)	150	8			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 244+10	(MP 3.9)	152	8			LEFT OF PAVED DITCH, UP BACKSLOPE
LT 245+83	(MP 3.9)	160	10			REMOVE TREE NEAR THE GATE-TREAT STUMP WITH HERBICIDE
LT 245+83	(MP 3.9)	160		16		REMOVE TREE NEAR THE GATE-TREAT STUMP WITH HERBICIDE
LT 245+83	(MP 3.9)	164	6			REMOVAL OF TREE AT THE OUTLET

Monday, December 20, 2004 @ 1:48:55 PM
p:\projects\g980\dgn\g980ts05a+3.dgn