STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2007-9
Various Counties
Sheet 14 of 50
Contract Number 44933

District 2 Schedule of Locations for Overhead Sign Structure Replacement

Location No.: 2-01	State I.D. No.: 2C101ABU0F			R000.0(174)		
County: Winnebago	Route: Au	bum	M.P.:	0	Direc	tion: EB
Description of Work					Unit	Quantity
REMOVE OVERHEAD SIGN STRUCTURE-CANTILEVER					EACH	1.00
REMOVE & REINSTALL SIGN PANEL				SQ FT	93.00	
REMOVE & REINSTALL WALKWAY				FOOT	15.50	
FURNISH & INSTALL SAFETY CHAIN				EACH	2.00	
OVERHEAD SIGN STRUCTURE CANTILEVER TYPE II-C-A					FOOT	30.00
REPAIR HANDRAIL LOCKING PIN CONNECTION					EACH	4.00
DISCONNECT / RECONNECT ELECTRIC SERVICE				EACH	1.00	
REBUILD CONCRETE FOUNDATATION FOR OVERHEAD SIGN ST					EACH	1.00
This sign structure is being comp	oletely replaced	1.				

Location No.: 2-02 State I.D. No.: 2S101S2	51R004.6		
County: Winnebago Route: IL 251 M.P.: 4.6	Direc	tion: NB	
Description of Work	Unit	Quantity	
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00	
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00	
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	73.50	
DRILL SHAFT CONCRETE FOUNDATION	CU YD	20.40	
REMOVE CONCRETE FOUNDATION OVERHEAD	EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	2.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00	
RELOCATE ELECTRIC SERVICE	EACH	1.00	

Location	No.: 2-03	State	I.D. No.:	2S101U020L019.0		0	
County:	Winnebago	Route:	US 20	M.P.:	19	Direc	tion: WB
Description of Work					Unit	Quantity	
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN					EACH	1.00	
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE					EACH	2.00	
FURNISH & INSTALL SADDLE SHIM BLOCK					EACH	4.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER					EACH	1.00	
OVERHEAD SIGN STRUCTURE WALKWAY					FOOT	73.50	
DRILL SHAFT CONCRETE FOUNDATION					CU YD	20.40	
REMOVE CONCRETE FOUNDATION OVERHEAD					EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION					EACH	2.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE					EACH	1.00	
RELOCATE ELECTRIC SERVICE					EACH	1.00	

Location No.: 2-04	State	I.D. No.:	2S101U020L018.5			5
County: Winnebago	Route:	US 20	M.P.: 18.5 Direction			tion: EB
Description of Work					Unit	Quantity
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN					EACH	1.00
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE					EACH	2.00
FURNISH & INSTALL SADDLE SHIM BLOCK					EACH	4.00
FURNISH & INSTALL INTERNAL TRUSS DAMPER					EACH	1.00
OVERHEAD SIGN STRUCTURE WALKWAY					FOOT	73.50
DRILL SHAFT CONCRETE FOUNDATION					CU YD	20.40
REMOVE CONCRETE FOUNDATION OVERHEAD					EACH	2.00
REPAIR HANDRAIL LOCKING PIN CONNECTION					EACH	2.00
DISCONNECT / RECONNECT ELECTRIC SERVICE					EACH	1.00
RELOCATE ELECTRIC SERVICE	E				EACH	1.00