


Bill of Material

Item	Quantity	Unit
Deck Slab Repair Partial Depth	1940.2	Sq Yd
Silicone Joint Sealer, 1 1/2"	336	Foot



Backer rod having a diameter 25% greater than joint opening at the time of installation.

SILICONE JOINT SEALER DETAIL
Remove deteriorated joint seals in arch span and replace with Silicone Joint Sealer (4 Joints).

DECK REPAIR PLAN

Legend
 Deck Slab Repair (Partial Depth)
 Patches shown are potential areas of deck slab repair. Actual areas to be determined in the field.

Date of Deck Survey: October 2010

FILE NAME =	USER NAME = #USER#	DESIGNED -	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	Deck Repair Plan Structure No. 081-0106		F.A.I. RTE. 280	SECTION (81-1B)M-2	COUNTY Rock Island	TOTAL SHEETS 30	SHEET NO. 30	
#FILE#		DRAWN -	REVISED -		SCALE: _____	SHEET NO. 14 OF 14 SHEETS	STA. _____ TO STA. _____	ILLINOIS FED. AID PROJECT				
		CHECKED -	REVISED -									
		DATE -	REVISED -									