

2012 INSPECTION INFORMATION

REPAIR DETAIL NUMBER	07/25/12 NBIS INSPECTION DEFICIENCY ITEM NUMBER	LOCATION
1	68	Span 9, Stringer A at Floorbeam 11, Panel 11
1	142	Span 11, Stringer F at Floorbeam 10, Panel 10
1	169	Span 11, Stringer F at Floorbeam 10, Panel 11
1	143	Span 11, Stringer F at Floorbeam 2, Panel 2
1	195/196	Span 13, Stringer F at Floorbeam 0, Panel 1
2	121	Span 2, Beam D, 15'-8 ³ / ₄ " from Bearing at Bent 2
2	86	Span 11, Beam E, 480'-4 ¹ / ₂ " from Bearing at Pier 4
2	145	Span 16, Beam C, 36'-5" from Bearing at Bent 10
2	-	Span 16, Beam C, 2nd Diaphragm from Bent 10
2	-	Span 16, Beam C, 4th Diaphragm from Bent 10
2	147	Span 17, Beam A, 36'-0" from Bearing at Bent 11
2	148	Span 17, Beam C, 36'-7" from Bearing at Bent 11
2	210	Span 17, Beam D, 4th Diaphragm from Bent 11
2	212	Span 18, Beam C, 4th Diaphragm from Bent 12
2	-	Span 18, Beam D, 4th Diaphragm from Bent 12
2	219	Span 19, Beam A, 4th Diaphragm from Bent 13
2	151	Span 20, Beam C, 3rd Diaphragm from Bent 14
2	230	Span 20, Beam D, 3rd Diaphragm from Bent 14
2	235	Span 21, Beam C, 4th Diaphragm from Bent 15
2	-	Span 21, Beam C, 5th Diaphragm from Bent 15
2	236	Span 21, Beam D, 5th Diaphragm from Bent 15
2	117	Span 23, Beam D, 3rd Diaphragm from Bent 17
2	243	Span 24, Beam C, 2nd Diaphragm from Bent 18
2	-	Span 24, Beam C, 3rd Diaphragm from Bent 18
2	244	Span 24, Beam D, 3rd Diaphragm from Bent 18
2	159	Span 27, Beam A, 2nd Diaphragm from Bent 21
3	72	Span 9, Hanger 7E
3	74	Span 9, Hanger 5E
3	76	Span 9, Hanger 2W
3	78	Span 9, Hanger 2E
4	32	Span 12, Floorbeam 11 at East Tie
5	49	Span 21, Beam F, North Pin
6	152	Span 21, East Sidewalk at 2nd Bracket North of Bent 14
7	118	Span 25, West Sidewalk, 6' North of Bent 18
8	126	Span 5, Beam A, Pin near Bent 5
8	127	Span 5, Beam B, Pin near Bent 5
8	128	Span 5, Beam E, Pin near Bent 5
8	161	Span 5, Beam F, Pin near Bent 5
9	107	Span 18, Beam D at Midspan
10	64	Span 7, Beam C, 24' North of Bent 6
10	-	Span 17, Beam B, 16'-10 ¹ / ₂ " North of Bent 10
10	207	Span 17, Beam C, 16'-11 ¹ / ₂ " North of Bent 10
10	208	Span 17, Beam E, 17'-1" North of Bent 10
10	209	Span 17, Beam F, 17'-2" North of Bent 10
10	223	Span 19, Beam B, 16'-10 ¹ / ₂ " South of Bent 13
10	-	Span 23, Beam A, North Side of Bent 16
10	115	Span 23, Beam B, North Side of Bent 16
10	52	Span 23, Beam C, North Side of Bent 16
10	154	Span 23, Beam D, North Side of Bent 16
10	155	Span 23, Beam E, North Side of Bent 16
10	156	Span 23, Beam F, North Side of Bent 16
11	122	Span 3, Beam D at Bent 2
11	160	Span 27, Beam D at Bent 21
12	137	Span 10, Stringer B, 22'-11 ¹ / ₄ " South of Floorbeam 2
12	138	Span 10, Stringer C, 8'-10 ³ / ₄ " South of Floorbeam 0
13	129	Span 6, Beam C, 15' from Bent 5
13	9	Span 6, Beam D, 6' from Bent 5
14	70	Span 9, Floorbeam 8 at Stringer E
15	135	Span 10, West Bearing at Pier 2
16	41	Span 13, Sidewalk Support Channel West Side at Pier 6
17	134	Span 9, 3rd Purlin South of Floorbeam 3
18	114	Span 23, Diaphragm between Stringers B and C at Bent 16
19	132	Span 9, Floorbeam 11 at Stringer F
20	16	Span 7, Sign Support Channel, E. Side, 6th Bracket from Bent 6
21	75	Span 9, Floorbeam 5 between Stringers D and E
22	144	Span 13, Stringer E at Floorbeam 0
23	165	Span 10, West Tie at West End of Floorbeam 10
23	170	Span 11, West Tie at West End of Floorbeam 9
23	88	Span 11, West Tie at West End of Floorbeam 4
24	113	Span 22, Diaphragm between Stringers C and D over Bent 16
25	77	Span 9, Floorbeam 2 at Stringer D
26	7	Span 4 & 5, Bent 4 at Beam D
27	168	Span 10, Lateral Bracing Hanger at Midspan of Panel 4
28	181	Span 12, Floorbeam 0 at Stringer F

2012 INSPECTION INFORMATION

REPAIR DETAIL NUMBER	07/25/12 NBIS INSPECTION DEFICIENCY ITEM NUMBER	LOCATION
29	163	Span 9, Floorbeam 11 at East End
30	221	Span 19, Beam C, 4th Diaphragm from Bent 13
30	220	Span 19, Beam D, 4th Diaphragm from Bent 13
31	204	Span 16, Beam A, at Midspan
31	146	Span 16, Beam D, at Midspan and ¹ / ₄ Point
31	213	Span 18, Beam A, at Midspan
31	116/157	Span 23, Beam C, 26'-6" from Bearing at Bent 17
32	12	Span 7, Beam D, 2'-0" North of Pin and Link
33	211	Span 17, Outer Sidewalk Channel, West Side
33	214	Span 18, Outer Sidewalk Channel, West Side
33	218	Span 19, Outer Sidewalk Channel, West Side
33	228	Span 20, Outer Sidewalk Channel, West Side
33	234	Span 21, Outer Sidewalk Channel, West Side
34	229	Span 20, Beam A, 8'-0" from Bearing at Bent 13
35	184	Span 13, Inner Sidewalk Channel, West Side btwn FB 10 & FB 11
36	197	Transfer Beam and Columns at Pier 1
36	198	Transfer Beam and Columns at Pier 6
100	5	Span 1, East Side, 3rd Bracket from South Abutment
100	17	Span 8, East Side, 2nd Bracket from Bent 7
101	123	Span 4, East Side, 1st Bracket from North of Bent 3
102	125	Span 4, 5 at East Bracket at Bent 4
103	130	Span 7, East Side, 6th Bracket from Bent 6
104	11	Span 7, East Side, 4th Bracket from Bent 6
105	42	Span 14, East Side, at Panel 6, 1st Bracket at Pier 6
105	63	Span 6, 7 at Bent 6
106	44	Span 17, West Side, 4th Bracket from Bent 10 at Pin and Link
106	205	Span 17, West Side, 3rd Bracket from Bent 10
107	150	Span 19, West Side, 1st Bracket from South of Bent 13
108	149	Span 19, West Side, 2nd Bracket from South of Bent 13
109	153	Span 23, West Side at Bent 16
110	164	Span 9, Floorbeam 3 at West Cantilevered Bracket
110	166	Span 10, Floorbeam 11 at East Cantilevered Bracket
110	80	Span 10, Floorbeam 10 at East Cantilevered Bracket
110	81	Span 10, Floorbeam 8 at East Cantilevered Bracket
110	82	Span 10, Floorbeam 5 at East Cantilevered Bracket
110	167	Span 10, Floorbeam 4 at East Cantilevered Bracket
110	83	Span 10, Floorbeam 1 at East Cantilevered Bracket
110	172	Span 11, Floorbeam 8 at East Cantilevered Bracket
110	173	Span 11, Floorbeam 6 at East Cantilevered Bracket
110	89	Span 12, Floorbeam 10 at East Cantilevered Bracket
110	91	Span 12, Floorbeam 9 at East Cantilevered Bracket
110	92	Span 12, Floorbeam 8 at East Cantilevered Bracket
110	93	Span 12, Floorbeam 7 at East Cantilevered Bracket
110	95	Span 12, Floorbeam 6 at East Cantilevered Bracket
110	96	Span 12, Floorbeam 5 at East Cantilevered Bracket
110	97	Span 12, Floorbeam 4 at East Cantilevered Bracket
110	98	Span 12, Floorbeam 2 at East and West Cantilevered Bracket
110	177	Span 12, Floorbeam 1 at East Cantilevered Bracket
110	178	Span 12, Floorbeam 1 at West Cantilevered Bracket
110	185	Span 13, Floorbeam 10 at East Cantilevered Bracket
110	188	Span 13, Floorbeam 7 at East Cantilevered Bracket
110	190	Span 13, Floorbeam 5 at East Cantilevered Bracket
110	191	Span 13, Floorbeam 4 at East Cantilevered Bracket
111-114	62	All spans throughout
115	61	West Sidewalk at Post location 429 and 467
115	187	Span 13 between Floorbeam 7 and 8
120	18	Span 8, Beam D, 6th Stiffener from Bent 7, East Side
121	65	Span 7, Beam D, 15th and 16th Stiffener from Bent 6, E. Side
121	57	Span 26, Beam A, 4th Stiffener South of Bent 20, East Side
122	67	Span 8, Beam F, 2nd and 3rd Stiffener from Bent 7, W. Side
123	66	Span 7, Beam F, 3rd Stiffener from Bent 7, West Side
124	15	Span 7, Beam F, 19th Stiffener from Bent 6, West Side
125	28	Span 11, Floorbeam 13 between Stringer E and F, Panel 13
125	34	Span 12, Floorbeam 9 between Stringer A and B, Panel 9
125	94	Span 12, Floorbeam 6 between Stringer E and F, Panel 7
125	101	Span 13, Floorbeam 0, 3rd and 4th Stiffener from West Side
126	71	Span 9, Floorbeam 8, Stiffener at Stringer A, North Face
126	133	Span 9, Floorbeam 5, Stiffener at Stringer F, North Face
126	87	Span 11, FB 8, Stiffener at Stringer A, Panel 8, N. Face
126	35	Span 12, FB 7, Stiffener below Stringer F, Panel 7, N. Face
126	71	Span 9, Floorbeam 8, Stiffener at Stringer C, Panel 8, N. Face
127	39	Span 13, FB 10, Stiffener below Stringer F, Panel 10, N. Face
128	33	Span 12, FB 9, Stiffener below Stringer A, Panel 9, N. Face
128	186	Span 13, Floorbeam 9, Stiffener at Stringer F

I:\Projects\4015550\4015550_0001\90_CAD_Models_and_Sheets\04_CJ_Bridge\081905-64H28-002a-Inspection_Table.dgn



USER NAME = pattisjm	DESIGNED - ZM	REVISOR
PLOT SCALE = 0:2.0000 ' = 1"	CHECKED - MJK	REVISION
PLOT DATE = 1/21/2014	DRAWN - ZM	REVISION
	CHECKED - MJK	REVISION

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**2012 INSPECTION INFORMATION TABLES
STRUCTURE NO. 081-9005**

SHEET NO. 3 OF 33 SHEETS

F.A.P. RTE. 308	SECTION (3BRM)	COUNTY ROCK ISLAND	TOTAL SHEETS 47	SHEET NO. 16
C-92-090-12		CONTRACT NO. 64H28		
ILLINOIS FED. AID PROJECT				