


**EAST ABUTMENT**  
(Looking East)

**NOTES**

Hatched area indicates approximate area of Structural Repair of Concrete. Exact repairs are to be determined by the Engineer. All existing abutment seats shall be cleaned & sealed. Work will be paid for as Cleaning Bridge Seats.




**WEST ABUTMENT**  
(Looking West)

**BILL OF MATERIAL**

Item	Unit	Total
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	16.3

**ABUTMENT CONCRETE REPAIR DETAILS**  
S.N. 014-0049

 <b>Allen Henderson &amp; Associates, Inc.</b> Civil and Structural Engineers Springfield, IL 62703 Phone: (217)544-8033 IL Design Firm No. 184-001907	SHEET NO. 11	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
	17 SHEETS	327	14-12BR-1	CLINTON	72	55	
				CONTRACT NO. 76B27			
		FED. ROAD DIST. NO.	ILLINOIS	FED. AID PROJECT			