



**NOTE:**

Remove and replace existing diaphragms and channel clip angles with a W 12X26 and MC 10X21.9 respectively. The cost is included in Structural Steel Repair.

See Sheet 5 of 21 for diaphragm detail.

**BILL OF MATERIALS**

ITEM	UNIT	QUANTITY
STRUCTURAL STEEL REPAIR	POUND	490

FILE NAME =	USER NAME = curryw	DESIGNED - ARP	REVISED -	<b>STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION</b>	<b>39TH ST. (PERSHING RD) OVER RACINE AVE (SN 016-0396) STRUCTURAL STEEL REPAIR</b>	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
c:\pwork\pwork\dot\curryw\08283496\0162	01-sht-plan.dgn	DRAWN - ARP	REVISED -			90/94	2011-068-BR	COOK	21	6
PLOT SCALE = 3/4" = 1' / m		CHECKED - AM	REVISED -			CONTRACT NO. 60P87				
PLOT DATE = 1/19/2012		DATE - 12/22/11	REVISED -			ILLINOIS FED. AID PROJECT				
				SCALE:	SHEET NO. 3 OF 7 SHEETS	STA.	TO STA.			