



PLAN

Number	Length (ft)	Width (ft)	Area (sq yds)
1	4.6	8	4.1
2	3	6	2.0
3	2	3.3	0.7
4	4.6	2.3	1.2
5	2.3	2.6	0.7
6	10.9	3	3.6
7	8.2	5.4	4.9
8	3	5.7	1.9
9	1.5	2.4	0.4
10	4	1.7	0.8
11	6	3.4	2.3
12	3	2.6	0.9
13	3	2.5	0.8
14	3.7	2.7	1.1
15	6	4.5	3.0
16	2.2	1.7	0.4
17	3.4	2.4	0.9
18	2.7	2.5	0.8
19	4.3	4	1.9
20	3	2	0.7
21	1.9	2.4	0.5
22	2.5	3	0.8
23	2.8	2.7	0.8
24	2.6	2.1	0.6
25	3	1.7	0.6
26	3	1	0.3
27	5	2.8	1.6

Number	Length (ft)	Width (ft)	Area (sq yds)
28	6.1	4.5	3.1
29	2.5	1.5	0.4
30	3.3	1	0.4
31	4	3.4	1.5
32	12.5	2	2.8
33	2	1.7	0.4
34	1.5	1	0.2
35	3.5	3	1.2
36	5	3	1.7
37	6	4.8	3.2
38	3	3.5	1.2
39	2.3	2.3	0.6
40	9.4	2.4	2.5
41	1.5	2.4	0.4
42	1.7	2	0.4
43	1.6	2.2	0.4
44	3.2	1.7	0.6
45	6.3	7	4.9
46	3	6.6	2.2
47	4.8	7.6	4.1
48	4	2	0.9
49	3.5	5.3	2.1
50	2.3	2.1	0.5
51	6.6	3	2.2
52	1.8	3.4	0.7
53	2.9	6.4	2.1
54	1.7	1.5	0.3

Number	Length (ft)	Width (ft)	Area (sq yds)
55	4.4	7.5	3.7
56	1.1	4.6	0.6
57	5	1.5	0.8
58	2.9	1.8	0.6
59	2.3	1.6	0.4
60	2.3	3.3	0.8
61	2.2	1.8	0.4
62	2.3	1	0.3
63	2.2	1.8	0.4
64	5.9	1.6	1.0
65	4.8	1.1	0.6
66	1.9	2.7	0.6
67	5.2	1.5	0.9
68	6.1	4	2.7
69	3	1.7	0.6
70	2.3	2.4	0.6
71	2.2	2.3	0.6
72	5	2.3	1.3
73	1	1	0.1
74	3.4	2	0.8
75	1.3	2	0.3
76	2.3	1.1	0.3
77	5.7	1.6	1.0
78	3.1	2.7	0.9
79	3.7	2.4	1.0
80	1.3	1.1	0.2
81	2.4	2.7	0.7

Number	Length (ft)	Width (ft)	Area (sq yds)
82	1.3	1.3	0.2
83	3.4	1.6	0.6
84	1.6	1.5	0.3
85	11.9	1.5	2.0
86	2.2	2.1	0.5
87	2.5	2.8	0.8
88	3.2	1.9	0.7
89	2.4	3.5	0.9
90	2.5	2.4	0.7
91	4.4	1	0.5
92	1.9	3.2	0.7
93	2	1.5	0.3
94	4.8	6.3	3.4
95	1.2	1.1	0.1
96	8.9	1.5	1.5
97	7.4	2.7	2.2
98	1.9	1.3	0.3
99	2.4	1.1	0.3
100	7.8	3	2.6
101	7	1.5	1.2
102	5.1	1	0.6
103	3	1.6	0.5
104	1.8	2.8	0.6
105	2.8	1	0.3
106	3.1	2	0.7
107	4.1	2.1	1.0

Notes: Deck sounding was performed in October 2013.
 The Resident Engineer will determine final patch locations and quantities in the field before bridge deck patching operations begin.
 The Engineer shall show actual locations of deck repairs on As-built Plans.
 * Deck Slab Repair (Full Depth, Type II)

BILL OF MATERIAL

Item	Unit	Total
Deck Slab Repair (Full Depth, Type II)	Sq Yd	18.0
Deck Slab Repair (Partial)	Sq Yd	107