



## NOTES:

1. Actual quantities of repairs shall be approved by the Engineer.

## LEGEND

Structural Repair of Concrete (Depth equal to or less than 5 inches)

Structural Repair of Concrete (Depth greater than 5 inches)

— Epoxy Crack Injection

## BILL OF MATERIAL

ITEM	UNIT	QUANTITY	
Structural Repair of Concrete (Depth equal to or less than 5 inches)	Sq. Ft.	34	
Structural Repair of Concrete (Depth greater than 5 inches)	Sq. Ft.	2	
Epoxy Crack Injection	Foot	26	
Jack and Remove Existing Bearings	Each	4	

BOWMAN, BARRETT & ASSOCIATES INC. CONSULTING ENGINEERS
Chicago, Illinois
312.228.0100
www.bbandainc.com

USER NAME = DESIGNED - TL REVISED CHECKED - BAK REVISED DRAWN - MTR REVISED PLOT DATE = 11/08/2012 CHECKED - TL REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

PIER 7 REPAIR DETAILS STRUCTURE NO. 016-2437 SHEET NO. S-55 OF S-83 SHEETS

SECTION COUNTY COOK 285 218

CONTRACT NO. 60V61 2012-060-BR