



PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 2)
		SO	YD	
1	2.0 x 6.0			12.0
2	2.0 x 6.0			12.0
3	3.0 x 6.0			18.0
4	2.0 x 6.0			12.0
5	6.0 x 2.0			12.0
6	6.0 x 6.0			36.0
7	3.0 x 6.0			18.0
8	2.0 x 6.0			12.0
9	2.0 x 6.0			12.0
TOTAL		0	0	144

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 2)
		SO	YD	
PARTIAL DEPTH				
ESTIMATED				
USE 23 SQ YD				
FULL DEPTH, TYPE 1				
0 / 9 = 0.0				
USE 0 SQ YD				
FULL DEPTH, TYPE 2				
144 / 9 = 16.0				
USE 16 SQ YD				

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 2)
		SO	YD	

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 2)
		SO	YD	

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 2)
		SO	YD	

THE LOCATIONS AND SIZES SHOWN GRAPHICALLY ABOVE ARE APPROXIMATE. SEE THIS TABLE FOR ACTUAL SIZES.

PATCHING LEGEND
(FOR INFORMATION ONLY)

PARTIAL DEPTH

FULL DEPTH

DATE OF SURVEY: 07/07/09
SURVEY BY: M. ALLEN, A. RING
METHOD OF SURVEY: VISUAL

BRIDGE DECK PATCHING
LAWRENCE COUNTY
US 50 WBL OVER TR 262
2.4 MILE EAST
AIRPORT INTERCHANGE
SN 051-0023

023