



Illinois Department of Transportation

2300 South Dirksen Parkway / Springfield, Illinois / 62764

May 6, 2013

SUBJECT: FAP Route 325(IL 16)
Project F-0325(059)
Section (11B-1)BR
Shelby County
Contract No. 74615
Item No. 44, May 24, 2013 Letting
Addendum A

NOTICE TO PROSPECTIVE BIDDERS:

Attached is an addendum to the plans or proposal. This addendum involves revised and/or added material.

1. Revised page i of the Table of Contents to the Special Provisions.
2. Revised pages 93-109 of the Special Provisions.

Prime contractors must utilize the enclosed material when preparing their bid and must include any Schedule of Prices changes in their bidding proposal.

Bidders using computer-generated bids are cautioned to reflect any and all Schedule of Prices changes, if involved, into their computer programs.

Very truly yours,

John D. Baranzelli, P. E.
Acting Engineer of Design and Environment

A handwritten signature in black ink, appearing to read "Ted B. Walschleger P.E." with a small "P.E." to the right.

By: Ted B. Walschleger, P. E.
Engineer of Project Management

cc: Roger Driskell, Region 4, District 7; Mike Renner; D. Carl Puzey;
Estimates

dp

TABLE OF CONTENTS

LOCATION OF PROJECT	1
DESCRIPTION OF PROJECT	1
TRAFFIC CONTROL AND PROTECTION, (SPECIAL)	1
CHANGEABLE MESSAGE SIGNS	5
CLASS BS AGGREGATE OPTIMIZATION	6
INLET MODIFICATION	6
CONCRETE CURB, TYPE M (SPECIAL).....	6
CONCRETE MEDIAN SURFACE REMOVAL	7
BICYCLE RAILING, SPECIAL	7
STATUS OF UTILITIES TO BE ADJUSTED	7
BORROW AREAS, USE AREAS, AND/OR WASTE AREAS	8
SEEDING, CLASS 2 (SPECIAL)	8
STEEL RAILING REMOVAL.....	8
RAISED REFLECTIVE PAVEMENT MARKER, REFLECTOR REMOVAL	9
BONDED PREFORMED JOINT SEAL	9
DECK SLAB REPAIR.....	10
STRUCTURAL REPAIR OF CONCRETE	16
BRIDGE DECK FLY ASH OR GROUND GRANULATED BLAST-FURNACE SLAG CONCRETE OVERLAY	26
HOT-MIX ASPHALT SURFACE REMOVAL DECK.....	35
CONCRETE MIX DESIGN – DEPARTMENT PROVIDED (BDE)	35
DISADVANTAGED BUSINESS ENTERPRISE PARTICIPATION (BDE)	35
GROOVING FOR RECESSED PAVEMENT MARKINGS (BDE).....	45
LIQUIDATED DAMAGES (BDE).....	47
PAVEMENT MARKING REMOVAL (BDE)	47
PAYMENTS TO SUBCONTRACTORS (BDE)	48
PLACING AND CONSOLIDATING CONCRETE (BDE).....	49
PORTLAND CEMENT CONCRETE (BDE)	52
SUBCONTRACTOR MOBILIZATION PAYMENTS (BDE)	110
SYNTHETIC FIBERS IN CONCRETE GUTTER, CURB, MEDIAN, AND PAVED DITCH (BDE).....	110
TRACKING THE USE OF PESTICIDES (BDE).....	111
TRAFFIC CONTROL DEFICIENCY DEDUCTION (BDE)	111
UTILITY COORDINATION AND CONFLICTS (BDE).....	111
WEEKLY DBE TRUCKING REPORTS (BDE).....	117

Revised 5-6-2013

Temperature monitoring results shall be provided to the Engineer a minimum of once each day and whenever requested by the Engineer. The report may be electronic or hard copy. The report shall indicate the location of each sensor, the temperature recorded, and the time recorded. The report shall be for all sensors and shall include ambient air temperature and entrant/exit cooling water temperatures. The temperature data in the report may be provided in tabular or graphical format, and the report shall indicate any corrective actions during the monitoring period. At the completion of the monitoring period, the Contractor shall provide the Engineer a final report that includes all temperature data and corrective actions.

(7) Indicate contingency operations to be used if the maximum temperature or temperature differential of the concrete is reached after placement.

- (c) Temperature Restriction Violations. If the maximum temperature of the concrete after placement exceeds 150 °F (66 °C), but is equal to or less than 158 °F (70 °C), the concrete will be accepted if no cracking or other unacceptable defects are identified. If cracking or unacceptable defects are identified, Article 105.03 shall apply. If the concrete temperature exceeds 158 °F (70 °C), Article 105.03 shall apply.

If a temperature differential between the internal concrete core and concrete 2 to 3 in. (50 to 75 mm) from the exposed surface exceeds the specified or proposed maximum value allowed, the concrete will be accepted if no cracking or other unacceptable defects are identified. If unacceptable defects are identified, Article 105.03 shall apply.

When the maximum 150 °F (66 °C) concrete temperature or the maximum allowed temperature differential is violated, the Contractor shall implement corrective action prior to the next pour. In addition, the Engineer reserves the right to request a new thermal control plan for acceptance before the Contractor is allowed to pour again.

- (d) Inspection and Repair of Cracks. The Engineer will inspect the concrete for cracks after the temperature monitoring is discontinued, and the Contractor shall provide access for the Engineer to do the inspection. A crack may require repair by the Contractor as determined by the Engineer. The Contractor shall be responsible for the repair of all cracks. Protective coat or a concrete sealer shall be applied to a crack less than 0.007 in. (0.18 mm) in width. A crack that is 0.007 in. (0.18 mm) or greater shall be pressure injected with epoxy according to Section 590.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013

THIS PAGE INTENTIONALLY LEFT BLANK.

Revised 5-6-2013