


DATE	
BY	
SURVEYED	
PLOTTED	
TEMPLATE	
AREAS	
CHECKED	
NO.	

DATE	
BY	
SURVEYED	
PLOTTED	
TEMPLATE	
AREAS	
CHECKED	
NO.	



108 + 75.00
 C = 3.7
 F = 0.0

108 + 50.00
 C = 4.2
 F = 0.0

108 + 25.00
 C = 3.0
 F = 0.0

108 + 00.00
 C = 10.4
 F = 0.0