


Note:  
 Concrete median barrier wall shall be removed and replaced between existing saw-cuts on each side of damaged area. Existing reinforcement bars shall remain for a minimum 13" beyond saw-cut and incorporated into new construction. Existing PCC shoulder tie bars shall be cleaned, straightened, and incorporated into new construction.

LEGEND

HIGH MAST LIGHT TOWER



FILE NAME = 68876 1-74 CONCRETE BARRIER WALL REPAIR	USER NAME = jonesce	DESIGNED - CEJ	REVISED -
		DRAWN - CEJ	REVISED -
	PLOT SCALE = 1/32" = 103.7851' / IN.	CHECKED -	REVISED -
	PLOT DATE = 3/3/2009	DATE -	REVISED -

**STATE OF ILLINOIS  
 DEPARTMENT OF TRANSPORTATION**

**MISCELLANEOUS ROADWAY DETAIL  
 DHMB NO. 43A**

SCALE: \_\_\_\_\_ SHEET NO. \_\_\_\_ OF \_\_\_\_ SHEETS STA. \_\_\_\_\_ TO STA. \_\_\_\_\_

F.A.I. RTE. 74	SECTION 72(7,8,9,9-1)R-2	COUNTY PEORIA	TOTAL SHEETS 9	SHEET NO. 6
D4 CONC. MEDIAN REPAIR 2009			CONTRACT NO. 68876	
FED. ROAD DIST. NO. 4 ILLINOIS FED. AID PROJECT				