



**BUTT JOINT DETAIL**



**(TYPICAL) PROPOSED LONGITUDINAL JOINT REPAIR DETAIL PROFILE VIEW**

LOCATION	HMA SURFACE REMOVAL-VARIABLE DEPTH	
	LENGTH OF MILLING	
	SOUTH APPROACH FOOT	NORTH APPROACH FOOT
SN 054-0057	84	82
SN 054-0058	47	35
SN 054-0060	100	100
SN 054-0061	49	100
SN 054-0063	100	100
SN 054-0064	78	92
SN 054-0065	100	89
SN 054-0066	94	37
SN 054-0067	100	100
SN 054-0068	100	100



**PROPOSED LONGITUDINAL JOINT REPAIR PLAN VIEW**