



 Deck Slab Repair (Partial Depth) - 50 SQ. YD.  
 Note: Partial Depth Repair shall be achieved by bridge deck hydro-scarification and filled with microsilica concrete overlay. Cast included in "BRIDGE DECK HYDRO-SCARIFICATION 2 1/2" " and "BRIDGE DECK MICROSILICA CONCRETE OVERLAY 2 1/4" "

**DECK PATCHING PLAN**  
**IL 106 OVER HADLEY CREEK**  
**SN 075-0004**

DESIGNED	KTH
CHECKED	ADL
DRAWN	KTH/BGJ
CHECKED	ADL

**KLINGNER & ASSOCIATES, P.C.**  
 Engineers - Architects - Surveyors  
 105 North 2nd Street, Quincy, IL 62450  
 438 Perry Street, Hannibal, MO 63450  
 100 N. 4th Street, Suite 100, Burlington, IL 62518  
 111 North 1st Street, Champaign, IL 62510  
 Internet Address: www.klingner.com  
 STATE OF ILLINOIS DESIGN FIRM # 1842738



SHEET NO. 5	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	751	D6 BRIDGE REPAIR 2009	PIKE	22	22
5 SHEETS	CONTRACT NO. 72D44				
FED. ROAD DIST. NO.		ILLINOIS FED. AID PROJECT			