

**LEGEND**


- Structural Repair of Concrete (Depth Equal or Less Than 5 Inches)
- Structural Repair of Concrete (Depth Greater Than 5 inches)
- Epoxy Crack Injection

**Note:**  
Repairs shown are based upon observations performed in 2010 and are for bidding purposes only. Actual areas to be repaired shall be determined by the Engineer in the field at the time of construction. Quantities have been adjusted to account for the time difference.

**BILL OF MATERIAL**

Item	Unit	Total
Structural Repair of Concrete (Depth Equal or Less Than 5 Inches)	SQ FT	252
Structural Repair of Concrete (Depth Greater Than 5 inches)	SQ FT	20
Epoxy Crack Injection	FOOT	8

FILE NAME = s:\p1\6380--6399\6346\028\micro\cadd sheets\structural\016\016-PIER1.dgn



1170 SOUTH HOUBOLT ROAD  
JOLIET, ILLINOIS 60431  
(815) 744-4200  
IDFPR NO. 184-001273

USER NAME = brianf	DESIGNED - RRD	REVISED
	CHECKED - AJS	REVISED
PLOT SCALE =	DRAWN - BJF	REVISED
PLOT DATE = 1/29/2013	CHECKED - RRD	REVISED

**STATE OF ILLINOIS**  
**DEPARTMENT OF TRANSPORTATION**

**PIER 1 REPAIR DETAILS**  
**STRUCTURE NO. 016-0587**  
SHEET NO. 30 OF 42 SHEETS

F.A.I. RTE. = 55	SECTION = 22-1HB-R	COUNTY = COOK/DUPAGE	TOTAL SHEETS = 161	SHEET NO. = 118
CONTRACT NO. 60K77				
ILLINOIS FED. AID PROJECT				