

	LIN ENGINEERING, LTD. Consulting Engineers Springfield, Illinois	FILE NAME =	CHECKED - ADB	REVISED -	STATE OF ILLINOIS	SLOPE WALL RI Structure Nos. 045–0035 (E	
		PLOT SCALE =	DRAWN - AJF	REVISED -	DEPARTMENT OF TRANSPORTATION	31NUGTUNE NU3. 043-0033 (EE	
PLOT DATE = CHECKED - MTH REVISED - SHEET NO. 19 OF		PLOT DATE =	CHECKED - MTH	REVISED -		SHEET NO. 19 OF 21	

Existing reinforcement shall be cleaned and incorporated into the new construction. Cost

Repair of the existing slope wall shall include but may not be limited to the areas shown.

The actual areas to be repaired will be determined by the Engineer at the time of construction.

ITEM	UNIT	TOTAL	
Slope Wall Removal	Sq. Yd.	319	
Slope Wall 4 Inch	Sq. Yd.	319	

REPAIR		SECTION	COUNTY	TOTAL SHEETS	SHEET NO.			
(EB) & 045-0036 (WB)	573	61 HB-I-7	KANE	48	37			
(EB) & 043-0030 (WB)		CONTRACT NO. 60N12						
21 SHEETS		ILLINOIS FED. AID PROJECT						