

SCHEDULE OF QUANTITIES

✓25100900 TURF REINFORCEMENT MAT

SQ YD	LOCATION	REMARKS
132	RT. STA 17+ 90 TO 18+ 55	
110	LT. STA. 17+ 97 TO 18+ 55	
99	RT. STA 20 + 25 TO 20 + 60	
342	TOTAL	

✓28000300 TEMPORARY DITCH CHECKS

EACH	LOCATION	REMARKS
1	RT. STA 15+ 00	
1	RT. STA 16 + 00	
1	RT. STA 17+ 00	
2	LT/RT 21+ 00	
1	RT. STA 22+ 00	
2	LT/RT 23+ 00	
8	TOTAL	

✓28000400 PERIMETER EROSION BARRIER

FOOT	LOCATION	REMARKS
345	LT. STA. 14+ 00 TO 17+ 43	
28	RT. STA 17 + 85 TO 18+ 13	
373	TOTAL	

✓28000500 INLET AND PIPE PROTECTION

EACH	LOCATION	REMARKS
1	LT. STA. 18+ 00	
1	LT. STA. 21+ 97	
2	TOTAL	

✓42001420 BRIDGE APPROACH PAVEMENT CONNECTOR (PCC)

SQ YD	LOCATION	REMARKS
65	RT 1421+ 21 TO 1421 + 36	SN 037-0015 North Side
65	RT 1423+ 04 TO 1423 + 19	SN 037-0015 South Side
64	LT 1421+ 21 TO 1421 + 36	SN 037-0016 North Side
65	LT 1423+ 04 TO 1423 + 19	SN 037-0016 South Side
56	LT/RT 1629 + 17 TO 1629 + 29	SN 037-0017 North Side
46	LT/RT 1631+ 24 TO 1631 + 35	SN 037-0017 South Side
41	LT/RT 1629+ 09 TO 1629 + 19	SN 037-0018 North Side
45	LT/RT 1631+ 14 TO 1631 + 24	SN 037-0018 South side
447	TOTAL	

✓44004000 PAVED DITCH REMOVAL

FOOT	LOCATION	REMARKS
348	LT/RT 18+ 21 TO 19 + 95	existing paved ditch in front of piers
23	RT. STA 20 + 41 TO 20 + 52	
371	TOTAL	

✓44000700 APPROACH SLAB REMOVAL

SQ YD	LOCATION	REMARKS
107	LT/RT 1421+ 21 TO 1421 + 61	SN 037-0015 North side
107	LT/RT 1422+ 79 TO 1423+ 19	SN 037-0015 South side
107	LT/RT 1421+ 21 TO 1421 + 61	SN 037-0016 North side
107	LT/RT 1422+ 79 TO 1423+ 19	SN 037-0016 South side
107	LT/RT 1629 + 17 TO 1629 + 57	SN 037-0017 North side
107	LT/RT 1630 + 95 TO 1631+ 35	SN 037-0017 South side
107	LT/RT 1629+ 09 TO 1629 + 49	SN 037-0018 North side
107	LT/RT 1630 + 84 TO 1631+ 24	SN 037-0018 South side
853	TOTAL	

✓44200089 PAVEMENT PATCHING, TYPE I, 8 INCH

SQ YD	LOCATION	REMARKS
73	LT/RT 1418+ 56 TO 1425 + 14	SN 037-0015 contingency shoulder TBD by RE
69	LT/RT 1419 + 28 TO 1425 + 49	SN 037-0016 contingency shoulder TBD by RE
93	LT/RT 1625 + 70 TO 1634 + 11	SN 037-0017 contingency shoulder TBD by RE
88	LT/RT 1626 + 54 TO 1634 + 50	SN 037-0018 contingency shoulder TBD by RE
324	TOTAL	

✓44200094 PAVEMENT PATCHING, TYPE II, 8 INCH

SQ YD	LOCATION	REMARKS
73	LT/RT 1418+ 56 TO 1425 + 14	SN 037-0015 contingency shoulder TBD by RE
69	LT/RT 1419 + 28 TO 1425 + 49	SN 037-0016 contingency shoulder TBD by RE
93	LT/RT 1625 + 70 TO 1634 + 11	SN 037-0017 contingency shoulder TBD by RE
88	LT/RT 1626 + 54 TO 1634 + 50	SN 037-0018 contingency shoulder TBD by RE
324	TOTAL	

✓44200549 CLASS A PATCHES, TYPE I, 10 INCH

SQ YD	LOCATION	REMARKS
88	LT/RT 1418+ 56 TO 1425 + 14	SN 037-0015 contingency pavement TBD by RE
83	LT/RT 1419 + 28 TO 1425 + 49	SN 037-0016 contingency pavement TBD by RE
112	LT/RT 1625 + 70 TO 1634 + 11	SN 037-0017 contingency pavement TBD by RE
106	LT/RT 1626 + 54 TO 1634 + 50	SN 037-0018 contingency pavement TBD by RE
389	TOTAL	

✓44200553 CLASS A PATCHES, TYPE II, 10 INCH

SQ YD	LOCATION	REMARKS
88	LT/RT 1418+ 56 TO 1425 + 14	SN 037-0015 contingency pavement TBD by RE
83	LT/RT 1419 + 28 TO 1425 + 49	SN 037-0016 contingency pavement TBD by RE
112	LT/RT 1625 + 70 TO 1634 + 11	SN 037-0017 contingency pavement TBD by RE
106	LT/RT 1626 + 54 TO 1634 + 50	SN 037-0018 contingency pavement TBD by RE
389	TOTAL	

✓44213000 PATCHING REINFORCEMENT

SQ YD	LOCATION	REMARKS
175	LT/RT 1418+ 56 TO 1425 + 14	SN 037-0015 contingency pavement TBD by RE
166	LT/RT 1419 + 28 TO 1425 + 49	SN 037-0016 contingency pavement TBD by RE
224	LT/RT 1625 + 70 TO 1634 + 11	SN 037-0017 contingency pavement TBD by RE
212	LT/RT 1626 + 54 TO 1634 + 50	SN 037-0018 contingency pavement TBD by RE
778	TOTAL	