




S.N. 018-0049





S.N. 018-0050



<u>FOUR ABUTMENTS</u> BILL OF MATERIAL

ITEM	UNIT	TOTAL	
Structural Repair of Concrete (Depth Equal to or Less Than 5")	Sq. Ft.	31.4	

BLANK, WESSELINK	K, COOK & ASSOCIAT	& ASSOCIATES DECATUR, ILLINOIS ENGINEERS - CONSULTANTS DESIGN FIRM NO. 184000894		L			
FILE NAME =	USER NAME =	DESIGNED PBB	REVISED -		CONCRETE REPAIR DETAILS (WINGWALLS)	F.A.I. SECTION COUN	NTY TOTAL SHEET
		CHECKED MCB	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	STRUCTURE NO. 018-0049(W.B.) & 0050(E.B.)	70 (18-47-VB)K (18-47B, 18-47HB)BR CUMBER	
	PLOT SCALE =	DRAWN MLO	REVISED -			CONT	TRACT NO. 74466
	PLOT DATE =	CHECKED MCB	REVISED -		SHEET NO.26 OF 42 SHEETS	ILLINOIS FED. AID PROJECT)T