

PAVED SHOULDER ITEMS FOR STAGING			
LOCATION	PAVED SHLD REMOVAL (SPECIAL)	BIT MAT PRIME COAT	HMA SHOULDERS
	SQ YD	POUND	TON
NORTHBOUND			
OUTSIDE SHOULDER			
STA. 99+99.80 AH - STA. 107+49	500	225.0	112
STA. 107+49 - STA. 116+25	RAMP OMISSION		
STA. 116+25 - STA. 140+40	1610	724.5	361
STA. 140+40 - STA. 143+49	RAMP OMISSION		
STA. 143+49 - STA. 286+75	9551	4298.0	2139
INSIDE SHOULDER			
STA. 99+99.80 AH - STA. 121+18.42	941	423.7	210
STA. 121+18.42 - STA. 147+06.34	1150	517.6	248
STA. 147+06.34 - STA. 184+43.86	1661	747.5	372
STA. 184+43.86 - STA. 245+51.66	2715	1221.6	608
STA. 245+51.66 - STA. 286+75	1844	824.7	391
NB SUBTOTAL	19972	8982.6	4441
SOUTHBOUND			
OUTSIDE SHOULDER			
STA. 99+99.80 AH - STA. 114+00	934	420.3	209
STA. 114+00 - STA. 118+40	RAMP OMISSION		
STA. 118+40 - STA. 143+79	1693	761.9	379
STA. 143+79 - STA. 152+00	RAMP OMISSION		
STA. 152+00 - STA. 286+75	8983	4042.4	2012
INSIDE SHOULDER			
STA. 99+99.80 AH - STA. 121+18.42	941	423.7	211
STA. 121+18.42 - STA. 147+06.34	1150	571.6	238
STA. 147+06.34 - STA. 184+43.86	1661	747.5	372
STA. 184+43.86 - STA. 245+51.66	2715	1221.6	602
STA. 245+51.66 - STA. 286+75	1844	824.7	261
SB SUBTOTAL	19921	9013.6	4285
TOTALS	39893	17996	8726

OUTSIDE SHOULDER QUANTITIES = INITIAL 4" SHOULDER UPGRADE FOR STAGING
 INSIDE SHOULDER QUANTITIES = MIN 4" NEEDED FOR STAGING
 HMA QUANTITIES ARE IN ADDITION TO WHAT IS SHOW ON HMA RESURFACING SCHEDULE

TEMPORARY EROSION CONTROL		
STATION	LOCATION	TEMPORARY DITCH CHECKS
		FOOT
129+00	MEDIAN	9
132+90	MEDIAN	9
145+90	MEDIAN	9
146+10	MEDIAN	9
164+90	MEDIAN	9
165+10	MEDIAN	9
204+25	MEDIAN	9
205+05	MEDIAN	9
230+90	MEDIAN	9
231+10	MEDIAN	9
238+10	MEDIAN	9
268+90	MEDIAN	9
269+10	MEDIAN	9
286+75	MEDIAN	9
15+90	RAMP A	9
2+50	RAMP B	9
5+50	RAMP B	9
3+50	RAMP C	9
7+50	RAMP C	9
TOTALS		171

TEMPORARY EROSION CONTROL SEEDING QUANTITY (NOT SHOWN)
 BASED ON FINAL SEEDING

PIPE UNDERDRAIN OUTLET EXTENSION FOR 4" PIPE		
STATION	LOCATION	QUANTITY
		EACH
127+00	MEDIAN	1
127+00	SOUTHBOUND	1
164+18	NORTHBOUND	1
165+00	MEDIAN	1
195+00	MEDIAN(SB)	1
205+00	MEDIAN(SB)	1
210+00	MEDIAN(NB)	1
230+01	MEDIAN(SB)	1
240+00	MEDIAN(NB)	1
267+05	MEDIAN(SB)	1
267+05	MEDIAN(NB)	1
272+04	MEDIAN(SB)	1
272+03	MEDIAN(NB)	1
282+98	MEDIAN	1
MAINLINE TOTAL		14
RAMP A		
15+35		1
16+34		1
17+34		1
18+00		1
18+36		1
19+34		1
RAMP B		
0+46		1
2+46		1
4+47		1
5+98		1
6+49		1
RAMP C		
1+22		1
2+84		1
5+21		1
RAMP D		
RAMP TOTAL		14
TOTALS		28

ACCESS CONTROL FENCING						
APPROXIMATE LOCATION	SIDE	WOVEN WIRE FENCE REMOVAL	CABLE GUARDRAIL REMOVAL	WOVEN WIRE FENCE 4'	WOVEN WIRE GATES, 4'x12' SINGLE	COMMENTS
		FOOT	FOOT	FOOT	EACH	
STA. 100+00 - STA. 120+86	RT		2086	2086	1	REMOVE & REPLACE SINGLE STRAND GUARDRAIL
STA. 120+86 TO IL 116 ALONG FRONTAGE ROAD	RT		1405	1405	1	REMOVE & REPLACE SINGLE STRAND GUARDRAIL
STA. 147+95 - STA. 148+70	LT	75		75		FENCE REPAIR
STA. 159+75 - STA. 160+25	LT	50		50		FENCE REPAIR
STA. 162+00 - STA. 162+25	LT	25		25		FENCE REPAIR
STA. 186+60 - STA. 187+10	RT	50		50		FENCE REPAIR
STA. 186+80 - STA. 187+80	LT	100		100		FENCE REPAIR
STA. 192+85 - STA. 193+10	LT	25		25		FENCE REPAIR
STA. 203+60 - STA. 204+60	LT	100		100		FENCE REPAIR
STA. 220+10 - STA. 221+10	RT	100		100		FENCE REPAIR
STA. 223+15 - STA. 224+15	LT	100		100		FENCE REPAIR
STA. 237+95 - STA. 238+95	RT	100		100		FENCE REPAIR
STA. 259+20 - STA. 259+70	RT	50		50		FENCE REPAIR
STA. 260+80 - STA. 261+05	RT	25		25		FENCE REPAIR
STA. 266+30 - STA. 266+55	RT	25		25		FENCE REPAIR
STA. 281+05 - STA. 281+45	LT	40		40		FENCE REPAIR
TOTALS		865	3491	4356	2	

EXACT LOCATIONS OF PROPOSED GATES TO BE DETERMINED IN THE FIELD PER IDOT OPERATIONS