## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

ROUTE NO.	SECTION	COUNTY		TOTAL SHEETS	SHEET NO.	SHEET NO. 9	
F.A.P. 389	2424.2 B-I	соок		23	16	16	SHEETS
FED. ROAD DIST. NO. 7		TLLINOIS	PED. AID PROJECT-				

Contract No. 60E11

Notes:

-Face of existing

dockwall

-Existing timber pile dolphin


Existing reinforcing bars that have been cut and/or damaged during repair operations shall be supplemented by new in kind reinforcing bars. New bars shall be lapped a minimum of 32 bar diameters to existing bars. A mechanical bar splicer shall be used when it is not feasible to provide the minimum bar lap. No welding of bars shall be performed. See Special Provisions for Structural Repair of Concrete.

For below water line concrete repairs utilizing formwork, the concrete mix shall be placed by pumping through ports, which shall be installed at the bottom of each formed repair area.

Areas are in square feet (sq. ft.).

Crack widths shown to be repaired are 1/8" ± 1/6" unless otherwise noted.

## <u>PLAN</u>



– Face of river pier

## BILL OF MATERIAL

Item	Unit	Total	
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	49.0	
Epoxy Crack Injection	Foot	12	

**LEGEND** 

Structural Repair of Concrete Depth equal to or less than 5"

Epoxy Crack Injection

ELEVATION (Looking West)

WEST RIVER PIER REPAIRS F.A.P. RT. 389 - SEC. 2424.2 B-I COOK COUNTY <u>STATION 380+68.75</u> <u>STRUCTURE NO. 016-2445</u>

DESIGNED S. CHELBIAN

CHECKED

CHECKED

A. HAMMAD

D.C.PATEL

A. HAMMAD

Face of existing-

dockwall