


SECTION THRU EAST ABUTMENT



SILICONE JOINT SEALER DETAIL
SECTION THRU WEST ABUTMENT

Note: Contractor should take caution as not to damage the existing joint. Damages will be repaired to the satisfaction of the engineer and at the cost of the Contractor.

FILE NAME =	USER NAME = administrator	DESIGNED -	REVISED -
ca:\pw_work\pwidot\swartzw\d0240046\077	259-sht-brdetail1-0150013.dgn	DRAWN -	REVISED -
	PLOT SCALE = 20.0000' / in.	CHECKED -	REVISED -
	PLOT DATE = 10/21/2011	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

FIXED JOINT & SILICONE JOINT SEALER DETAILS		
SN. 015-0013		
SCALE: NA	SHEET NO. 3 OF 3 SHEETS	STA. TO STA.

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
325	.	.	24	15
			CONTRACT NO. 74259	
ILLINOIS FED. AID PROJECT				