



**NORTH SLOPEWALL PLAN**



**SECTION A-A**



**SECTION B-B**

**LEGEND**

(#') — Slope Wall Crack Sealing with Length

**BILL OF MATERIAL**

| ITEM                     | UNIT    | TOTAL |
|--------------------------|---------|-------|
| Stone Riprap, Class A3   | Sq. Yd. | 3     |
| Slope Wall Crack Sealing | Foot    | 26    |

**Farnsworth**  
 GROUP, INC.  
 2709 MacDraw Drive  
 Bloomington, Illinois 61704  
 309/663-8435, 309/663-1571 fax

|                 |         |
|-----------------|---------|
| DESIGNED - JCZ  | REVISED |
| CHECKED - JML   | REVISED |
| DRAWN - DJM/JWK | REVISED |
| CHECKED - MSW   | REVISED |
| DATE - 11/17/11 |         |

**STATE OF ILLINOIS**  
**DEPARTMENT OF TRANSPORTATION**

**NORTH SLOPEWALL REPAIR AND RIPRAP REPLACEMENT**  
**STRUCTURE NO. 082-0261**

SHEET NO. C9 OF 10 SHEETS

| F.A.I. RTE.               | SECTION    | COUNTY    | TOTAL SHEETS | SHEET NO.          |
|---------------------------|------------|-----------|--------------|--------------------|
| 64                        | 82-13,41RS | ST. CLAIR | 167          | 164                |
|                           |            |           |              | CONTRACT NO. 76415 |
| ILLINOIS FED. AID PROJECT |            |           |              |                    |