

STR #	ADDRESS	CITY	CATCH BASIN TO BE ADJUSTED (Each)	CATCH BASIN TO BE RECONSTRUCTED (Each)	CATCH BASIN TO BE REMOVED (Each)	CATCH BASIN TO BE REPLACED (Each)	INLET TO BE REMOVED (Each)	INLET TO BE REPLACED (Each)	INLET TO BE ADJUSTED (Each)	MANHOLE TO BE REMOVED (Each)	MANHOLE TO BE REPLACED (Each)	MANHOLE TO BE ADJUSTED (Each)	TYPE 1 FRAME & OPEN LID (Each)	TYPE 3 FRAME & GRATE (Each)	TYPE 1 FRAME & CLOSED LID (Each)	CLEAN LATERAL (ft)	CURB & GTRR REPAIR/ RPLCMT (ft)	CLEAN STRUCTR (Each)	SIDEWALK REMV & RPLC (ft <sup>2</sup> )	PVMNT PATCHING (yd <sup>2</sup> )	DRIVEWAY REMV & RPLC (YD <sup>2</sup> )	TRENCH BACKFILL (yd <sup>3</sup> )	ADDITIONAL COMMENTS
37	4413 SOUTHWEST HWY	HOMETOWN	0	0	0	0	0	0	1	0	0	0	0	0	0	50	6	0	0	4.4	0	0	
38	8835 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	1	0	0	50	10	0	0	8.0	0	0	Detector Loop Replacement - 30 feet
39	8757 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	1	0	0	50	6	0	0	1.3	0	0	
40	8702 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	1	0	0	50	4	0	0	0.9	0	2.0	
41	8820 S CICERO	OAK LAWN	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0	0	0	Repair Completed by Others
42	8940 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	1	0	0	50	6	1	0	2.0	0	2.0	
43	9440 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	0	0	0	50	12	0	0	2.0	0	2.0	
44	10320 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	0	0	0	50	10	0	0	1.3	0	2.0	
45	10800 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	0	0	0	50	9	1	0	0.4	0	0	
46	10900 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	0	0	0	50	6	0	0	0.4	0	0	
47	11310 S CICERO	ALSIP	1	0	0	0	0	0	0	0	0	0	0	0	0	50	8	0	0	0.9	0	2.0	
48	11420 S CICERO	ALSIP	1	0	0	0	0	0	0	0	0	0	0	0	0	50	0	0	0	0.0	0	2.0	
49	11400 S CICERO	ALSIP	1	0	0	0	0	0	0	0	0	0	0	0	0	50	7	0	0	0.4	0	2.0	
50	10121 S CICERO	OAK LAWN	0	1	0	0	0	0	0	0	0	0	0	0	0	50	14	1	112	4.4	0	5.0	
51	9643 S CICERO	OAK LAWN	1	0	0	0	0	0	0	0	0	0	0	0	0	50	12	0	0	1.3	0	0	
52	13642 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	6	0	0	0.4	0	0	
53	13716 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	6	0	0	0.4	0	0	
54	14226 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	6	0	0	0.4	0	0	
55	14300 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	6	0	0	0.4	0	0	
56	14330 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	4	1	0	0.9	0	0	
57	14501 S CICERO	CRESTWOOD	0	0	0	0	1	1	0	0	0	0	0	0	0	50	10	0	0	4.4	0	0	
58	14301 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	0	0	0	50	10	0	0	1.3	0	2.0	
59	14301 S CICERO	CRESTWOOD	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0	0	0	Repair Completed by Others
60	14149 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	1	0	0	50	10	0	0	6.7	0	2.0	
61	13233 S CICERO	CRESTWOOD	1	0	0	0	0	0	0	0	0	0	1	0	0	50	11	1	0	1.3	0	2.0	Brick pavement rem. & replcmnt. - 12 SF
62-1	11921 S CICERO	ALSIP	0	0	1	1	0	0	0	0	0	0	0	0	0	50	15	0	0	10.0	0	5	Type A Catch Basin
62-2	11921 S CICERO	ALSIP	0	0	0	0	0	0	0	1	1	0	1	0	0	0	0	0	0	0.0	15	2	
63	117TH AND SOUTHWEST HWY	PALOS HEIGHTS	0	1	0	0	0	0	0	0	0	0	1	0	0	50	10	0	0	6.7	0	0	
64	11920 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	8	0	0	1.7	0	2.0	
65	11932 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	8	0	0	4.0	0	0	
66	12002 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	1	0	0	50	9	0	0	1.8	0	2.0	
67	SOUTHWEST HWY S/O TIMBER LANE	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	8	0	0	3.6	0	2.0	
68	12108 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	11	0	0	3.7	0	0	
69	12108 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	12	0	0	4.0	0	2.0	
70	11919 SOUTHWEST HWY	PALOS PARK	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.0	0	0.0	Repair Completed by Others
71	11111 SOUTHWEST HWY	PALOS PARK	1	0	0	0	0	0	0	0	0	0	0	0	0	50	4	0	0	0.4	0	0	
72	10509 S HARLEM	PALOS PARK	0	0	0	0	0	0	1	0	0	0	0	0	0	50	0	0	0	0.0	0	0	
73	10343 S HARLEM	PALOS PARK	0	0	0	0	0	0	0	0	0	0	1	0	0	50	5	0	0	0.0	0	0	

FILE NAME =	USER NAME = _USER_	DESIGNED -	REVISED -	<b>STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION</b>	<b>DRAINAGE REPAIRS SCHEDULE OF QUANTITIES</b>	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
#FILE#		DRAWN - JJ	REVISED -			*	2010-065-T	COOK	14	5
	PLOT SCALE = 480.0000 1" = 100'	CHECKED - RS	REVISED -			* VARIOUS				
	PLOT DATE = 12/7/2010	DATE - 12-10-2010	REVISED -							CONTRACT NO. 60L46
					SCALE: 20	SHEET NO. 2 OF 4 SHEETS		STA.	TO STA.	
ILLINOIS FED. AID PROJECT										